SAFETY DATA SHEET

Safety Data Sheet according to GB/T 16483-2008 and GB/T 17519-2013



Date of issue/Date of revision 20 December 2023

Version 1.03

	20	December	2023

Section 1. Chem	ical product and company identification
Product code	: 00463378
Product name	: SIGMACOVER 456 BASE BLUE C935
Product name	: SIGMACOVER 456 BASE BLUE C935
Product type	: Liquid.
Relevant identified uses o	f the substance or mixture and uses advised against
Product use	: Professional applications, Used by spraying.
Use of the substance/ mixture	: Coating.
Uses advised against	: Not applicable.
Supplier's details	: PPG Coatings (Kunshan) Co., Ltd 53 Jinyang Road, Lujia Town, 215331 Kunshan City, Jiangsu Province, P.R. China Tel: 86 512 57678859 Fax: 86 512 57678857
Emergency telephone number (with hours of operation)	: 00 86 532 83889090

Section 2. Hazards identification

Classification of the substance or mixture according to GB 13690-2009 and GB 30000-2013

Emergency overview Liquid. Characteristic. Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Toxic to aquatic life with long lasting effects. Prolonged or repeated contact may dry skin and cause irritation.

IF exposed or concerned: Get medical advice or attention. IF INHALED: Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. If skin irritation or rash occurs: Get medical advice or attention. If eye irritation persists: Get medical advice or attention.

See Section 12 for environmental precautions.

Section 2. Hazards identification

Classification of the substance or mixture	 FLAMMABLE LIQUIDS - Category 3 ACUTE TOXICITY (dermal) - Category 5 ACUTE TOXICITY (inhalation) - Category 4 SKIN CORROSION/IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 2 AQUATIC HAZARD (ACUTE) - Category 3 AQUATIC HAZARD (LONG-TERM) - Category 2 Percentage of the mixture consisting of ingredient(s) of unknown acute dermal toxicity: 63.1% Percentage of the mixture consisting of ingredient(s) of unknown acute inhalation toxicity: 63.1% Percentage of the mixture consisting of ingredient(s) of unknown hazards to the aquatic environment: 39.8%
GHS label elements	
Hazard pictograms	
Signal word	: Warning
Hazard statements	 Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Toxic to aquatic life with long lasting effects.
Precautionary statements	
Prevention	: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use explosion-proof electrical, ventilating or lighting equipment. Use non-sparking tools. Take action to prevent static discharges. Keep container tightly closed. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Avoid breathing vapor. Wash thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace.
Response	: Collect spillage. IF exposed or concerned: Get medical advice or attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice or attention.
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.

Date of issue 20 December 2023 Version 1.03

Product name SIGMACOVER 456 BASE BLUE C935

Section 2. Hazards identification

Storage	: Store locked up. Store in a well-ventilated place. Keep cool.
Disposal	: Dispose of contents and container in accordance with all local, regional, national and international regulations.
Physical and chemical hazards	: Flammable liquid and vapor.
Health hazards	: Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Prolonged or repeated contact may dry skin and cause irritation.
Symptoms related to the phy	sical, chemical and toxicological characteristics
Eye contact	: Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	: No specific data.
Delayed and immediate effect	ts and also chronic effects from short and long term exposure
<u>Short term exposure</u>	
Potential immediate effects	: Not available.
Potential delayed effects Long term exposure	: Not available.
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Environmental hazards	: Harmful to aquatic life. Toxic to aquatic life with long lasting effects.
Other hazards which do not result in classification	: Prolonged or repeated contact may dry skin and cause irritation.

Section 3. Composition/information on ingredients

Substance/mixture : Mixture

CAS number/other identifier	<u>s</u>	
CAS number	:	Not applicable.

Section 3. Composition/information on ingredients

Ingredient name	%	CAS number
4,4'-Isopropylidenediphenol, oligomeric reaction products with 1-chloro- 2,3-epoxypropane, reaction products with fatty acids, C18-unsatd., dimers	25 - <40	67989-52-0
xylene isomers mixture ethylbenzene	10 - <25 1 - <10	1330-20-7 100-41-4
barium sulfate Talc , not containing asbestiform fibres	1 - <10 1 - <10	7727-43-7 14807-96-6
2-methylpropan-1-ol	1 - <10	78-83-1

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SUB codes represent substances without registered CAS Numbers.

Section 4. First aid measures

Description of necessary first aid measures Eye contact : Remove contact lenses, irrigate copiously with clean, fresh water, holding the eyelids apart for at least 10 minutes and seek immediate medical advice. Inhalation : Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. Remove contaminated clothing and shoes. Wash skin thoroughly with soap and Skin contact water or use recognized skin cleanser. Do NOT use solvents or thinners. : If swallowed, seek medical advice immediately and show this container or label. Ingestion Keep person warm and at rest. Do NOT induce vomiting. Most important symptoms/effects, acute and delayed Potential acute health effects Eye contact : Causes serious eye irritation. Inhalation : Harmful if inhaled. : May be harmful in contact with skin. Causes skin irritation. Defatting to the skin. Skin contact May cause an allergic skin reaction. Ingestion : No known significant effects or critical hazards. **Over-exposure signs/symptoms** Eye contact : Adverse symptoms may include the following: pain or irritation watering redness Inhalation : No specific data. Skin contact Adverse symptoms may include the following: irritation redness dryness cracking Ingestion : No specific data.

Indication of immediate medical attention and special treatment needed, if necessary

Date of issue 20 December 2023 Version 1.03

Product name SIGMACOVER 456 BASE BLUE C935

Section 4. First aid measures

Notes to physician	 Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is toxic to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides sulfur oxides halogenated compounds metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protectiv	re equipment and emergency procedures
For non-emergency : personnel	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders :	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".

Product name SIGMACOVER 456 BASE BLUE C935

Section 6. Accidental release measures

Environmental precautions :	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmful to the environment if released in large quantities. Collect spillage.
Methods and materials for con	tainment and cleaning up
Small spill :	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
Large spill :	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling	:	Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapor or mist. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.
Conditions for safe storage, including any incompatibilities	:	Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

ethylbenzene barium sulfate Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls : Use only with adequate ventilation or work proor dust contaminants below any recommender also need to keep gas, vapor or dust colimits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce ndividual protection measures Hygiene measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated stops to the workstation lot contaminated stops to the workstation lot contaminated work clothing should not contaminated stops to the workstation lot contaminated work clothing shoul	ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
ethylbenzene barium sulfate Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures Recommended monitoring controls Propriate engineering controls Image: State	PC-STEL: 100 mg/m ³ 15 minutes. PC-TWA: 50 mg/m ³ 8 hours. 3BZ 2.1 (China, 11/2022). PC-STEL: 150 mg/m ³ 15 minutes. PC-TWA: 100 mg/m ³ 8 hours. 3BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. 3BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust ACGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
barium sulfate Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures Appropriate engineering controls Environmental exposure controls Environmental exposu	PC-TWA: 50 mg/m ³ 8 hours. BZ 2.1 (China, 11/2022). PC-STEL: 150 mg/m ³ 15 minutes. PC-TWA: 100 mg/m ³ 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust ACGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
barium sulfate Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to appropri- national guidance documents for meth- substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommender also need to keep gas, vapor or dust co- limits. Use explosion-proof ventilation or they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce ndividual protection measures Hygiene measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing, showers are close to the workstation to Eye protection Skin protection	 BZ 2.1 (China, 11/2022). PC-STEL: 150 mg/m³ 15 minutes. PC-TWA: 100 mg/m³ 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m³, (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
barium sulfate Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to appropri- national guidance documents for meth- substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommender also need to keep gas, vapor or dust co- limits. Use explosion-proof ventilation or they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce ndividual protection measures Hygiene measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing, showers are close to the workstation to Eye protection Skin protection	PC-STEL: 150 mg/m ³ 15 minutes. PC-TWA: 100 mg/m ³ 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls Environmental exposure controls : Use only with adequate ventilation or work proor dust or limits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce adividual protection measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation lot contaminated clothing before reusing. showers are close to the workstation lot contaminated clothing before reusing. Showers are close to the workstation lot contaminated splash goggles.	PC-TWA: 100 mg/m ³ 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls Environmental exposure controls : Use only with adequate ventilation or work proor dust or limits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce adividual protection measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation lot contaminated clothing before reusing. showers are close to the workstation lot contaminated clothing before reusing. Showers are close to the workstation lot contaminated splash goggles.	BZ 2.1 (China, 11/2022). PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Talc , not containing asbestiform fibres 2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls Environmental exposure controls : Use only with adequate ventilation or work proor dust or limits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce Individual protection measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing before reusing. showers are close to the workstation to contaminated clothing before reusing. showers are close to the workstation to contaminated clothing before reusing. Showers are close to the workstation to contaminated clothing before reusing. Showers are close to the workstation to contaminated splash goggles.	PC-TWA: 10 mg/m ³ , (as Ba) 8 hours. BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls Environmental exposure controls : Use only with adequate ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce Inividual protection measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing, showers are close to the workstation lo Eye protection : Chemical splash goggles.	BZ 2.1 (China, 11/2022). PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
2-methylpropan-1-ol Recommended monitoring procedures : Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Us ventilation or other engineering controls Environmental exposure controls : Use only with adequate ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce Inividual protection measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing, showers are close to the workstation lo Eye protection : Chemical splash goggles.	PC-TWA: 1 mg/m ³ 8 hours. Form: espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
2-methylpropan-1-ol Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust collimits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce Adividual protection measures Wash hands, forearms and face thorous eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation to contaminated clothing before reusing. Showers are close to the workstation to contaminated splash goggles.	espirable dust PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
2-methylpropan-1-ol Reference should be made to approprinational guidance documents for methor substances will also be required. Appropriate engineering controls Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust collimits. Use explosion-proof ventilation or work proor they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduce Adividual protection measures Wash hands, forearms and face thorous eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation to contaminated clothing before reusing. Showers are close to the workstation to contaminated splash goggles.	PC-TWA: 3 mg/m ³ 8 hours. Form: total dust CGIH TLV (United States, 1/2023). TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Recommended monitoring procedures: Reference should be made to appropri national guidance documents for methal substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controlsEnvironmental exposure controls: Use only with adequate ventilation or work product on they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceEnvironmental protection measures Hygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated vork clothing before reusing, showers are close to the workstation lo Complash goggles.Eye protection Skin protection: Chemical splash goggles.	CGIH TLV (United States, 1/2023). TWA: 152 mg/m³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Recommended monitoring procedures: Reference should be made to appropri national guidance documents for methe substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controlsEnvironmental exposure controls: Use only with adequate ventilation or work product of they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation lo Comparison in the splash goggles.Eye protection Skin protection: Chemical splash goggles.	TWA: 152 mg/m ³ 8 hours. TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
proceduresnational guidance documents for methe substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation lo Eye protectionEye protection Skin protection: Chemical splash goggles.	TWA: 50 ppm 8 hours. te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
proceduresnational guidance documents for methe substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measures Hygiene measures: Wash hands, forearms and face thoro eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation lo Eye protectionEye protection Skin protection: Chemical splash goggles.	te monitoring standards. Reference to ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
proceduresnational guidance documents for methe substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation lo Eye protectionEye protection Skin protection: Chemical splash goggles.	ds for the determination of hazardous e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measures Hygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing before reusing, showers are close to the workstation lo Eye protectionEye protection Skin protection: Chemical splash goggles.	e process enclosures, local exhaust to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Appropriate engineering controls: Use only with adequate ventilation. Us ventilation or other engineering controls contaminants below any recommended also need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measures Hygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing before reusing, showers are close to the workstation lo contaminated splash goggles.Eye protection Skin protection: Chemical splash goggles.	to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
controlsventilation or other engineering controlsEnvironmental exposure controlsEmissions from ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measuresImage: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation loEye protectionImage: Chemical splash goggles.	to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
controlsventilation or other engineering controlsEnvironmental exposure controlsEmissions from ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measuresImage: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated clothing before reusing, showers are close to the workstation loEye protectionImage: Chemical splash goggles.	to keep worker exposure to airborne or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Environmental exposure controlscontaminants below any recommended also need to keep gas, vapor or dust con limits. Use explosion-proof ventilation or they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measures Hygiene measures:Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing before reusing, showers are close to the workstation loEye protection Skin protection:Chemical splash goggles.	or statutory limits. The engineering controls ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Environmental exposure controlsalso need to keep gas, vapor or dust or limits. Use explosion-proof ventilation or work proof they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measures Hygiene measures:Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection Skin protection:Chemical splash goggles.	ncentrations below any lower explosive quipment. ess equipment should be checked to ensure
Environmental exposure controlslimits. Use explosion-proof ventilation of they comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reduceIndividual protection measuresWash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing before reusing. showers are close to the workstation lo Skin protectionEye protection:Chemical splash goggles.	quipment. ess equipment should be checked to ensure
 Environmental exposure controls Emissions from ventilation or work proceeding they comply with the requirements of encases, fume scrubbers, filters or engine equipment will be necessary to reduce Individual protection measures Wash hands, forearms and face thorous eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing, showers are close to the workstation lot Eye protection Chemical splash goggles. 	ess equipment should be checked to ensure
controlsthey comply with the requirements of e cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measures:Hygiene measures:Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection:Skin protection:	
cases, fume scrubbers, filters or engine equipment will be necessary to reducendividual protection measuresHygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.	Vironmental protection legislation In some
equipment will be necessary to reduce ndividual protection measures Hygiene measures : Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation lo Eye protection : Chemical splash goggles.	
Individual protection measures Hygiene measures : Wash hands, forearms and face thorous eating, smoking and using the lavatory Appropriate techniques should be used. Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation lote. Skin protection Eye protection : Chemical splash goggles.	
Hygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.	
Hygiene measures: Wash hands, forearms and face thorou eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.Skin protection: Chemical splash goggles.	
eating, smoking and using the lavatory Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.Skin protection:	
Appropriate techniques should be used Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation lo Eye protection : Chemical splash goggles. Skin protection	
Contaminated work clothing should not contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.Skin protection	
contaminated clothing before reusing. showers are close to the workstation loEye protection: Chemical splash goggles.Skin protection	
showers are close to the workstation lo Eye protection : Chemical splash goggles. Skin protection	
Skin protection	
Skin protection	
-	
	complying with an approved standard should
	nical products if a risk assessment indicates meters specified by the glove manufacturer,
	I retaining their protective properties. It
	l retaining their protective properties. It rough for any glove material may be
several substances, the protection time	rough for any glove material may be
estimated.	rough for any glove material may be rs. In the case of mixtures, consisting of
Gloves : butyl rubber	rough for any glove material may be rs. In the case of mixtures, consisting of
	rough for any glove material may be rs. In the case of mixtures, consisting of
	rough for any glove material may be rs. In the case of mixtures, consisting of

Section 8. Exposure controls/personal protection

•	• •
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	 Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

Section 9. Physical and chemical properties

<u>Appearance</u>		
Physical state	iquid.	
Odor	Characteristic.	
Boiling point	37.78°C (>100°F)	
Flash point	Closed cup: 26°C (78.8°F)	
Lower and upper explosive (flammable) limits	Greatest known range: Lower: 1.7% Upper: 10.9% (2-methylpropan-1-ol)	
Relative density	.37	
Solubility(ies)	Media Result	
oolubility(ies)	cold water Not soluble	
Viscosity	(inematic (40°C): >21 mm²/s	

Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	: Depending on conditions, decomposition products may include the following materials: carbon oxides sulfur oxides halogenated compounds metal oxide/ oxides

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
ylene isomers mixture	LD50 Dermal	Rabbit	1.7 g/kg	-
	LD50 Oral	Rat	4.3 g/kg	-
ethylbenzene	LC50 Inhalation Vapor	Rat	17.8 mg/l	4 hours
	LD50 Dermal	Rabbit	17.8 g/kg	-
	LD50 Oral	Rat	3.5 g/kg	-
barium sulfate	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
2-methylpropan-1-ol	LC50 Inhalation Vapor	Rat	24.6 mg/l	4 hours
	LD50 Dermal	Rabbit	2460 mg/kg	-
	LD50 Oral	Rat	2830 mg/kg	-

Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
xylene isomers mixture	Skin - Moderate irritant	Rabbit	-	24 hours 500 mg	-

Sensitization

Not available.

Mutagenicity

Not available.

Carcinogenicity

Not available.

Reproductive toxicity

Not available.

Teratogenicity

Not available.

Specific target organ toxicity (single exposure)

Name	Category	Route of exposure	Target organs
Talc , not containing asbestiform fibres	Category 3	-	Respiratory tract irritation
2-methylpropan-1-ol	Category 3	-	Respiratory tract irritation
	Category 3		Narcotic effects

Specific target organ toxicity (repeated exposure)

Name		Route of exposure	Target organs
ethylbenzene	Category 2	-	-

Aspiration hazard

Name	Result
ethylbenzene	ASPIRATION HAZARD - Category 1

Product name SIGMACOVER 456 BASE BLUE C935

Section 11. Toxic	ological information
Information on the likely routes of exposure	: Not available.
Potential acute health effect	t <u>s</u>
Eye contact	: Causes serious eye irritation.
Inhalation	: Harmful if inhaled.
Skin contact	: May be harmful in contact with skin. Causes skin irritation. Defatting to the skin. May cause an allergic skin reaction.
Ingestion	: No known significant effects or critical hazards.
Symptoms related to the ph	ysical, chemical and toxicological characteristics
Eye contact	: Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	: No specific data.
Delayed and immediate effe	cts and also chronic effects from short and long term exposure
<u>Short term exposure</u>	
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Long term exposure	
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Potential chronic health ef	<u>fects</u>
General	: Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/ or dermatitis. Once sensitized, a severe allergic reaction may occur when
	subsequently exposed to very low levels.
Carcinogenicity	 Suspected of causing cancer. Risk of cancer depends on duration and level of exposure.
Carcinogenicity Mutagenicity	: Suspected of causing cancer. Risk of cancer depends on duration and level of

Numerical measures of toxicity

Acute toxicity estimates

Section 11. Toxicological information

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)		Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
GMACOVER 456 BASE BLUE C935	6624.5	3202.6	N/A	20.6	2.4
xylene isomers mixture	4300	1700	N/A	11	1.5
ethylbenzene	3500	17800	N/A	17.8	1.5
barium sulfate	N/A	2500	N/A	N/A	N/A
2-methylpropan-1-ol	2830	2460	N/A	24.6	N/A

Other information

Prolonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

Section 12. Ecological information

_	
	itv/
10/	IL Y

Product/ingredient name	Result	Species	Exposure
ethylbenzene	Acute EC50 1.8 mg/l Fresh water Chronic NOEC 1 mg/l Fresh water	Daphnia Daphnia - Ceriodaphnia dubia	48 hours -
2-methylpropan-1-ol	Acute EC50 1100 mg/l	Daphnia	48 hours

Persistence/degradability

Product/ingredient name	Test	Result		Dose		Inoculum
ethylbenzene	-	79 % - Rea	ıdily - 10 days	-		-
Product/ingredient name	Aquatic half-life		Photolysis		Biodeg	radability
xylene isomers mixture ethylbenzene	-		-		Readily Readily	

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
Vene isomers mixture		7.4 to 18.5	Low
ethylbenzene	3.6	79.43	Low
2-methylpropan-1-ol	1	-	Low

Mobility in soil

Soil/water partition : No coefficient (Koc)

: Not available.

Other adverse effects

: No known significant effects or critical hazards.

Product name SIGMACOVER 456 BASE BLUE C935

Section 13. Disposal considerations

Disposal methods

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

	•			
	China	UN	IMDG	ΙΑΤΑ
UN number	UN1263	UN1263	UN1263	UN1263
UN proper shipping name	PAINT	PAINT	PAINT	PAINT
Transport hazard class(es)	3	3	3	3
Packing group	III	Ш	Ш	Ш
Environmental hazards	Yes. The environmentally hazardous substance mark is not required.	Yes. The environmentally hazardous substance mark is not required.	Yes.	Yes. The environmentally hazardous substance mark is not required.
Marine pollutant substances	Not applicable.	Not applicable.	(4,4'- Isopropylidenediphenol, oligomeric reaction products with 1-chloro- 2,3-epoxypropane, reaction products with fatty acids, C18-unsatd., dimers)	Not applicable.

Additional information

CN	: None identified.
UN	: None identified.
IMDG	: The marine pollutant mark is not required when transported in sizes of \leq 5 L or \leq 5 kg.
ΙΑΤΑ	: The environmentally hazardous substance mark may appear if required by other transportation regulations.

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Section 14. Transport information

Transport in bulk according : Not applicable. to IMO instruments

Section 15. Regulatory information

China inventory (IECSC)	: All components are listed or exempted.
References	 Production Safety Law of the People's Republic of China Code of Occupational Disease Prevention of the People's Republic of China Environmental Protection Law of the People's Republic of China Fire Control Law of the People's Republic of China Regulations on the Control over Safety of Dangerous Chemicals Occupational exposure limits for hazardous agents in the workplace chemical hazardous agents (GBZ2.1) General rule for classification and hazard communication of chemicals (GB13690) Safety data sheet for chemical products - Content and order of sections (GB/ T16483) Guidance on the compilation of safety data sheet for chemical products (GB/ T17519) General rule for preparation of precautionary label for chemicals (GB15258) Safety rules for classification, precautionary labeling and precautionary statements of chemicals (GB30000.2-29)

Section 16. Other information

<u>History</u>	
Date of issue/Date of revision	: 20 December 2023
Date of previous issue	: 8/10/2023
Version	: 1.03
	EHS
Key to abbreviations	 ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations
_	

✓ Indicates information that has changed from previously issued version.

Notice to reader

Section 16. Other information

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.