SAFETY DATA SHEET



Date of issue/Date of revision9 December 2023Version 5

Section 1. Identification				
Product name	: FLAMENCO PINK TEXTURE POLYESTER			
Product code	: PCTA60221			
Other means of identification	: Not available.			
Product type	: Powder.			
Relevant identified uses of	the substance or mixture and uses advised against			
Product use	: Industrial applications.			
Use of the substance/ mixture	: Coating. Paints. Painting-related materials.			
Uses advised against	: Not applicable.			
Manufacturer <u>Emergency telephone</u> <u>number</u>	 PPG Industries, Inc. One PPG Place Pittsburgh, PA 15272 (412) 434-4515 (U.S.) (514) 645-1320 (Canada) SETIQ Interior de la República: 800-00-214-00 (México) SETIQ Ciudad de México: (55) 5559-1588 (México) 			
Technical Phone Number	: 1-888-774-2001 (US and Canada)			

Section 2. Hazards identification

OSHA/HCS status	 This material is considered hazardous by the OSHA Hazard Communication Standard (29 CFR 1910.1200).
Classification of the substance or mixture	: COMBUSTIBLE DUSTS ACUTE TOXICITY (oral) - Category 4 SKIN SENSITIZATION - Category 1 GERM CELL MUTAGENICITY - Category 1 CARCINOGENICITY - Category 2 SPECIFIC TARGET ORGAN TOXICITY (REPEATED EXPOSURE) - Category 2
	Percentage of the mixture consisting of ingredient(s) of unknown acute toxicity: 72.6% (oral), 79.5% (dermal), 66.6% (inhalation)
GHS label elements	
Hazard pictograms	



Product name FLAMENCO PINK TEXTURE POLYESTER

Section 2. Hazards identification

Signal word	Danger
Hazard statements	Harmful if swallowed. May cause an allergic skin reaction. May cause genetic defects. Suspected of causing cancer. May cause damage to organs through prolonged or repeated exposure. May form combustible dust concentrations in air.
Precautionary statements	
Prevention	Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Do not breathe dust or mist. Do not eat, drink or smoke when using this product. Wash thoroughly after handling. Contaminated work clothing must not be allowed out of the workplace.
Response	IF exposed or concerned: Get medical advice or attention. IF SWALLOWED: Call a POISON CENTER or doctor if you feel unwell. Rinse mouth. Wash contaminated clothing before reuse. IF ON SKIN: Wash with plenty of water. If skin irritation or rash occurs: Get medical advice or attention.
Storage	Store locked up.
Disposal	Dispose of contents and container in accordance with all local, regional, national and international regulations.
Supplemental label elements	Keep container tightly closed. Keep away from heat, sparks, open flames and hot surfaces No smoking. Prevent dust accumulation. Emits toxic fumes when heated.
Hazards not otherwise classified	Fine dust clouds may form explosive mixtures with air. Handling and/or processing of this material may generate a dust which can cause mechanical irritation of the eyes, skin, nose and throat.

Section 3. Composition/information on ingredients

Substance/mixture	1	Mixture
Product name	:	FLAMENCO PINK TEXTURE POLYESTER

Ingredient name	%	CAS number
inanium dioxide	≥10 - ≤20	13463-67-7
Wollastonite	≥5.0 - ≤10	13983-17-0
1,3,5-tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione	≥1.0 - ≤5.0	2451-62-9
carbon black	≤1.0	1333-86-4
titanium dioxide (<10 microns)	≤1.0	13463-67-7

SUB codes represent substances without registered CAS Numbers.

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 4. First aid measures

If ingestion, irritation, any type of overexposure or symptoms of overexposure occur during or persists after use of this product, contact a POISON CONTROL CENTER, EMERGENCY ROOM OR PHYSICIAN immediately; have Safety Data Sheet information available. Never give anything by mouth to an unconscious or convulsing person. Description of necessary first aid measures

Eye contact: Check for and remove any contact lenses. Immediately flush eyes with running water for
at least 15 minutes, keeping eyelids open. Seek immediate medical attention.Inhalation: Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is
irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained
personnel.Skin contact: Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water
or use recognized skin cleanser. Do NOT use solvents or thinners.Ingestion: If swallowed, seek medical advice immediately and show this container or label. Keep
person warm and at rest. Do NOT induce vomiting.

Most important symptoms/effects, acute and delayed

Potential acute health effects Eye contact : Exposure to airborne concentrations above statutory or recommended exposure limits may cause irritation of the eyes. Inhalation : Exposure to airborne concentrations above statutory or recommended exposure limits may cause irritation of the nose, throat and lungs. Skin contact : May cause an allergic skin reaction. Ingestion : Harmful if swallowed. Over-exposure signs/symptoms Eye contact : Adverse symptoms may include the following: irritation redness : Adverse symptoms may include the following: Inhalation respiratory tract irritation coughing Skin contact : Adverse symptoms may include the following: irritation redness : No specific data. Ingestion Indication of immediate medical attention and special treatment needed, if necessary Notes to physician : In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. **Specific treatments** : No specific treatment. Protection of first-aiders : No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

See toxicological information (Section 11)

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical powder.
Unsuitable extinguishing media	: Avoid high pressure media which could cause the formation of a potentially explosible dust-air mixture.
Specific hazards arising from the chemical	: Fine dust clouds may form explosive mixtures with air.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing dust. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	: If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	: Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and materials for co	ontainment and cleaning up
Small spill	: Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a HEPA filter and place in a closed, labeled waste container. Place spilled material in a designated, labeled waste container. Dispose of via a licensed waste disposal contractor.
Large spill	: Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a HEPA filter and place in a closed, labeled waste container. Avoid creating dusty conditions and prevent wind dispersal. Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.
	United States Page: 4/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 6. Accidental release measures

Section 7. Handling and storage

Precautions for safe handling	9	
Protective measures		Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not breathe dust. Do not ingest. Avoid the creation of dust when handling and avoid all possible sources of ignition (spark or flame). Prevent dust accumulation. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Electrical equipment and lighting should be protected to appropriate standards to prevent dust coming into contact with hot surfaces, sparks or other ignition sources. Take precautionary measures against electrostatic discharges. To avoid fire or explosion, dissipate static electricity during transfer by grounding and bonding containers and equipment before transferring material. Empty containers retain product residue and can be hazardous. Do not reuse container.
Special precautions	:	If this material is part of a multiple component system, read the Safety Data Sheet(s) for the other component or components before blending as the resulting mixture may have the hazards of all of its parts.
Advice on general occupational hygiene	:	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
Conditions for safe storage, including any incompatibilities	:	Do not store below the following temperature: 5°C (41°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

Ingredient name	Exposure limits
inanium dioxide	OSHA PEL (United States, 5/2018).
	TWA: 15 mg/m ³ 8 hours. Form: Total dust
	ACGIH TLV (United States, 1/2023).
	TWA: 2.5 mg/m ³ 8 hours. Form: respirable
	fraction, finescale particles
Wollastonite	ACGIH TLV (United States, 1/2023).
	TWA: 1 mg/m ³ 8 hours. Form: Inhalable
	fraction
	United States Page: 5/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 8. Exposure controls/personal protection

carbon black TWA: 0.05 mg/m³ 8 hours. ACGH TLV (United States, 1/2023). titanium dioxide (<10 microns) TWA: 3.5 mg/m³ 8 hours. Form: Inhalable fraction OSHA PEL (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. TWA: 2.5 mg/m³ 8 hours. OSHA PEL (United States, 1/2023). TWA: 2.5 mg/m³ 8 hours. Ference Ference TWA: 2.5 mg/m³ 8 hours. Ference SER Ference SER Sensensitzation STEL Shours mentization TV Threshold Limit Values TP TUX SER Respirable Z OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Drouptate	1,3,5-tris(oxiranylmethyl)-1,3,	,5-triazine-2,4,6(1H,3H,5H)-trione	ACGIH TLV (United States, 1/2023). [1,3,5-Triglycidyl-s-triazinetrione] TWA: 0.05 mg/m ³ 8 hours		
carbon black ACGIH TLV (United States, 1/2023). TWA: 3 mg/m³ 8 hours. Form: Inhalable fraction titanium dioxide (<10 microns) States, 5/2018). TWA: 3.5 mg/m³ 8 hours. Form: Total dust ACGIH TLV (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. Form: respirable fraction, finescale particles A = Acceptable Maximum Peak S CCIH = American Conference of Governmental Industrial Hygienists. S C = Celling Limit SS F = Fume SS C2 = Offential skin absorption C3 = Skin sensitization SS = Skin sensitization SS = Skin sensitization C3 = Offential skin absorption C4 = Acceptable Maximum Peak SS C5 = Celling Limit SS F = Fume SS = Skin sensitization C4 = Colley A29 CFR 1910.1200 Subpart 2 - Toxic and Hazardous Substances TUV = Treal dust Forcedures : Efference should be made to appropriate monitoring standards. Reference to nationa guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering mtrois : Use only with adequate ventilation. If user operations generate dust, fumes,					
titanium dioxide (<10 microns) TWA: 3 mg/m³ 8 hours. Form: Inhalable fraction OSHA PEL (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. Form: Total dust A = Acceptable Maximum Peak S = Potential skin absorption COH = Acceptable Maximum Peak S = Potential skin absorption CO = Acceptable Maximum Peak S = Potential skin absorption CO = Comparing Limit SR = Respiratory sensitization F = Fume STEL = Skin sensitization FEL = Internal Permissible Exposure Limit TD = Total dust TVV = Three spiratole TWA: 3 mg/m³ 8 hours. Form: respiratole Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Veighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Veighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - toxic and Hazardous Substances Time Veighted Average Emissions from ventilation or other engineering controls for the determination of hazardous substances will also be required. Porportiate engine	carbon black				
titanium dioxide (<10 microns) OSHA PEL (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. OSHA PEL (United States, 5/2018). TWA: 15 mg/m³ 8 hours. Form: respirable fraction, finescale particles A = Acceptable Maximum Peak S = Potential skin absorption CGH = American Conference of Governmental Industrial Hygienists. S = Potential skin absorption CH = American Conference of Governmental Industrial Hygienists. S = Respiratory sensitization CH = Ceiling Limit SS = Skin sensitization F = Fume STEL = Short term Exposure limit values PEL = Internal Permissible Exposure Limit TD = Total dust SYAA = OCcupational Safety and Health Administration. T.V. T.V. = Three Posoure limit values PEL = Internal Permissible Exposure Limit TD = Total dust Strence should be made to appropriate monitoring standards. Reference to nationar guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering ntrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, yapp or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statut limits. The engineening controls also need to keep gas, vapor o			TWA: 3 mg/m ³ 8 hours. Form: Inhalable fraction		
bittering OSHA PEL (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. tittanium dioxide (<10 microns) SHA PEL (United States, 5/2018). TWA: 3.5 mg/m³ 8 hours. Form: Total dust ACGHT TLV (United States, 1/2023). TWA: 2.5 mg/m³ 8 hours. Form: respirable fraction, finescale particles A = Acceptable Maximum Peak S = Potential skin absorption CGIH = Acceptable Maximum Peak S = Potential skin absorption CGI = Caling Limit SR = Respiratory sensitization F = Fume STEL = Shorterm Exposure limit values PEL = Internal Permissible Exposure Limit TD = Total dust NSHA = Cocupational Safety and Health Administration. TLV = Threshold Limit Value SFA = Respirable TUV = Threshold Limit Value C = Cell Pinto 200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average C = OSHA 290 CFR 1910.1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average C = Osten ywith adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventiliation or other engineering or mist, use process enclosures, local exhaust ventiliation or other engineering controls also need to keep gas, vapor or dust concentrations below any					
titanium dioxide (<10 microns) TWA: 35 mg/m³ 8 hours. OSHA PEL (United States, 5/2018). TWA: 15 mg/m³ 8 hours. Form: Total dust ACCIH TLV (United States, 1/2023). A = Acceptable Maximum Peak S CCIH = Anerican Conference of Governmental Industrial Hygienists. S = Potential skin absorption C = Celling Limit S = Potential skin absorption C = Celling Limit SS = Short tem Exposure limit values PFL = Internal Permissible Exposure Limit TD = Toredud dust TVA = Sepirable STEL = Short tem Exposure limit values R = Respirator TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Time Weighted Average = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Time Weighted Average = State S					
titanium dioxide (<10 microns) OSHA PEL [United States, 5/2018). TWA: 15 mg/m ² 8 hours. Form: Total dust ACGIH TLV (United States, 1/2023). TWA: 25 mg/m ² 8 hours. Form: respirable fraction, finescale particles A = Acceptable Maximum Peak S = Potential skin absorption CGIH = American Conference of Governmental Industrial Hygienists. S = Potential skin absorption CGIH = American Conference of Governmental Industrial Hygienists. S = Skin sensitization C = Ceiling Limit SS = Skin sensitization FE = Fume STEL = Shorterm Exposure limit values TD = Total dust TUV = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TUV = Time Weighted Average Nonsult local authorities for acceptable exposure limits. Ecommended monitoring : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering nitrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mits, use process enclosures, local exhaust ventiliation or other engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. ivironm					
TWA: 15 mg/m ³ 8 hours. Form: Total dust ACGIH TLV (United States, 1/2023). TWA: 2.5 mg/m ³ 8 hours. Form: respirable fraction, finescale particles A = Acceptable Maximum Peak CGIH = American Conference of Governmental Industrial Hygienists. S = Potential skin absorption SR = Respiratory sensitization STEL = Short term Exposure limit values TD = Total dust TWA = 10 coupational Safety and Health Administration. TWA = Coupational Safety and Health Administration. TWA = Total dust TD = Total dust TWA = Total dust TWA = Total dust TWA = Time Weighted Average 2 = 0SHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances bonsult local authorities for acceptable exposure limits. Recommended monitoring rocedures Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Popropriate engineering introls : Use only with adequate ventilation. If user operations generate dust, furmes, gas, vapp or mist, use process enclosures, local exhaust ventilation or other engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Emissions from ventilation or work process equipoint hould be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, furme scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. dividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appro	titanium diavida (<10 microns		OSHA PEL (United States, 5/2018).		
A CGH TLV (United States, 1/2023). TWA 2.5 mg/m² 8 hours. Form: respirable fraction, finescale particles Key to abbreviations A = Acceptable Maximum Peak S = Potential skin absorption CGH = American Conference of Governmental Industrial Hygienists. S = Respiratory sensitization F = Furme STEL = Short term Exposure limit values FPL = Internal Permissible Exposure Limit TD = Total dut VMA = Occupational Safety and Health Administration. TLV = Threshold Limit Value Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910-1200 Subpart 2 - Toxi		5)			
TWA: 2.5 mg/m³ 8 hours. Form: respirable fraction, finescale particles Key to abbreviations A = Acceptable Maximum Peak S = Potential skin absorption CGIH = American Conference of Governmental Industrial Hygienists. S = Skin sensitization C = Celling Limit SS = Skin sensitization F = Fume STEL = Short term Exposure limit values PEL = Internal Permissible Exposure Limit TD = Total dust NPH = Aspirable TLV = Threshold Limit Value R = Respirable TWA = Time Weighted Average 2 = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Time Weighted Average Orcedures : Reference should be made to appropriate monitoring standards. Reference to national gradence documents for methods for the determination of hazardous substances will also be required. Purpopriate engineering introls : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statut limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. tvironmental exposure : Emissions from ventilation or work process equipment should be checked to ensure the vorophy with the requirements of environmental protection legislation. In some cases, fume sc			0		
Key to abbreviations A = Acceptable Maximum Peak S = Potential skin absorption CGH = American Conference of Governmental Industrial Hygienists. SR = Respiratory sensitization C = Ceiling Limit SS = Skin sensitization F = Fume STEL Short term Exposure limit values PPEL = Internal Permissible Exposure Limit TD = Total dust PVH = Occupational Safety and Health Administration. TU = Threshold Limit Value R = Respiratole TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average properiate engineering incode monitoring : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering introls : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. wirronmental exposure : Emissions from ventilation or work process equipment solud be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.					
Key to abbreviations Potential skin absorption CGIH = Acceptable Maximum Peak S = Potential skin absorption CGIH = American Conference of Governmental Industrial Hygienists. SR = Respiratory sensitization C = Celling Limit SS = Skin sensitization = F = Fume STEL = Short term Exposure limit values PEL = Internal Permissible Exposure Limit TD = Total dust NEH = Respiratole Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Orscedures = Respiratole Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Optionarrocedures : Reference should be made to appropriate monitoring standards. Reference to nationar guidance documents for methods for the determination of hazardous substances will also be required. optionpriate engineering : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapp or or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls use process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering					
A = Acceptable Maximum Peak S = Potential skin absorption CGIH = American Conference of Governmental Industrial Hygienists. SR = Respiratory sensitization CGIH = American Conference of Governmental Industrial Hygienists. SR = Respiratole SKin sensitization F = Furme STEL = Skin sensitization TD = Total dust PR = Respirable Total dust = Total dust Total dust Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Directures : Reference should be made to appropriate monitoring standards. Reference to nationar guidance document					
CGIH = American Conference of Governmental Industrial Hygienists. SR = Respiratory sensitization C = Celling Limit SS = Skin sensitization F = Fume STEL = Short term Exposure limit values IPEL = Internal Permissible Exposure Limit TD = Total dust SPHA = Occupational Safety and Health Administration. TLV = Threshold Limit Value R = Respirable TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Drocedures : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Propriate engineering introls : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modif	A = Acceptable Maximum Pe	-	S = Potential skin absorption		
C = Celling Limit STEL = Skin sensitization F = Fume STEL = Short term Exposure limit values PFL = Internal Permissible Exposure Limit TD = Total dust VSHA = Occupational Safety and Health Administration. TLV = Threshold Limit Value R = Respirable TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances = Time Weighted Average multical authorities for acceptable exposure limits. = Cereptable exposure limits. teccommended monitoring : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering ntrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. vironmental exposure : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection measures virodual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating,					
PEL = Internal Permissible Exposure Limit TD = Total dust SHA = Occupational Safety and Health Administration. TUV = Threshold Limit Value SHA = Respirable TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances = Time Weighted Average insult local authorities for acceptable exposure limits. = Time Weighted Average ecommended monitoring : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. propriate engineering notrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminats below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. vironmental exposure : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. tividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory a					
SHA = Occupational Safety and Health Administration. TLV = Threshold Limit Value R = Respirable TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Insult local authorities for acceptable exposure limits. Ecommended monitoring : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Impropriate engineering ntrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. vironmental exposure ntrols : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. tividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should he used to remove potentially contaminated cothing. Contaminated work clohing before reusing. Ensure t	F = Fume		STEL = Short term Exposure limit values		
R = Respirable TWA = Time Weighted Average Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Substances = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Substances = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances TWA = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = CostHa 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Twa = Time Weighted Average Substance = Use only with adequate ventilation. If user operations generate dust, furnes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls also need to keep gas, vap	•				
Z = OSHA 29 CFR 1910.1200 Subpart Z - Toxic and Hazardous Substances Insult local authorities for acceptable exposure limits. tecommended monitoring rocedures : Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. proppriate engineering ntrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. etwiconmental exposure ntrols : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. dividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. ygiene measures : Safety glasses with side shields. <td></td> <td>Health Administration.</td> <td></td>		Health Administration.			
Insult local authorities for acceptable exposure limits.tecommended monitoring roceduresReference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.upropriate engineering ntrolsUse only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statuto limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.twironmental exposure ntrolsEmissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.dividual protection measures lygiene measuresWash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.ye/face protectionSafety glasses with side shields.	P - Pospirabla		IWA = Ime Weighted Average		
 Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the working. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. 		0 Cubpart 7 Taxia and Hazardaya Cubatanaaa			
procedures guidance documents for methods for the determination of hazardous substances will also be required. ppropriate engineering ntrols : Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statute limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. entrols : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. dividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. type/face protection : Safety glasses with side shields.	Z = OSHA 29 CFR 1910.120				
Introlsor mist, use process enclosures, local exhaust ventilation or other engineering controlsInvironmental exposureor mist, use process enclosures, local exhaust ventilation or other engineering controlsInvironmental exposureimits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.ImitorisEmissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.dividual protection measuresImage: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Safety glasses with side shields.	Z = OSHA 29 CFR 1910.120 onsult local authorities for a	acceptable exposure limits.	nriate monitoring standards. Reference to notions		
Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Safety glasses with side shields.	Z = OSHA 29 CFR 1910.120	 Reference should be made to appro guidance documents for methods fo 	priate monitoring standards. Reference to nationa r the determination of hazardous substances will		
 eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Safety glasses with side shields. 	Z = OSHA 29 CFR 1910.120 onsult local authorities for a Recommended monitoring procedures opropriate engineering ontrols	 Acceptable exposure limits. Reference should be made to approguidance documents for methods for also be required. Use only with adequate ventilation. or mist, use process enclosures, loc to keep worker exposure to airborne limits. The engineering controls also below any lower explosive limits. Use Emissions from ventilation or work p they comply with the requirements or cases, fume scrubbers, filters or engineering 	r the determination of hazardous substances will f user operations generate dust, fumes, gas, vaporal exhaust ventilation or other engineering controls contaminants below any recommended or statute need to keep gas, vapor or dust concentrations e explosion-proof ventilation equipment. rocess equipment should be checked to ensure f environmental protection legislation. In some ineering modifications to the process equipment		
ye/face protection : Safety glasses with side shields.	Z = OSHA 29 CFR 1910.120 onsult local authorities for a Recommended monitoring procedures opropriate engineering ontrols	 Acceptable exposure limits. Reference should be made to approguidance documents for methods for also be required. Use only with adequate ventilation. or mist, use process enclosures, loc to keep worker exposure to airborne limits. The engineering controls also below any lower explosive limits. Use: Emissions from ventilation or work p they comply with the requirements or cases, fume scrubbers, filters or engineering to reduce emission 	r the determination of hazardous substances will f user operations generate dust, fumes, gas, vaporal exhaust ventilation or other engineering controls contaminants below any recommended or statute need to keep gas, vapor or dust concentrations e explosion-proof ventilation equipment. rocess equipment should be checked to ensure f environmental protection legislation. In some ineering modifications to the process equipment		
	Z = OSHA 29 CFR 1910.120 onsult local authorities for a Recommended monitoring procedures opropriate engineering ontrols	 Acceptable exposure limits. Reference should be made to approguidance documents for methods for also be required. Use only with adequate ventilation. or mist, use process enclosures, loc to keep worker exposure to airborne limits. The engineering controls also below any lower explosive limits. Use Emissions from ventilation or work p they comply with the requirements or cases, fume scrubbers, filters or engwill be necessary to reduce emission Wash hands, forearms and face tho eating, smoking and using the lavate Appropriate techniques should be us Contaminated work clothing should a contaminated clothing before reusing 	r the determination of hazardous substances will of user operations generate dust, fumes, gas, vapor al exhaust ventilation or other engineering controls contaminants below any recommended or statute oneed to keep gas, vapor or dust concentrations e explosion-proof ventilation equipment. rocess equipment should be checked to ensure f environmental protection legislation. In some ineering modifications to the process equipment as to acceptable levels.		
	Z = OSHA 29 CFR 1910.120 onsult local authorities for a Recommended monitoring rocedures opropriate engineering ntrols evironmental exposure ntrols dividual protection measure lygiene measures	 Acceptable exposure limits. Reference should be made to approguidance documents for methods for also be required. Use only with adequate ventilation. or mist, use process enclosures, loc to keep worker exposure to airborne limits. The engineering controls also below any lower explosive limits. Use Emissions from ventilation or work p they comply with the requirements or cases, fume scrubbers, filters or engwill be necessary to reduce emission Wash hands, forearms and face tho eating, smoking and using the lavate Appropriate techniques should be us contaminated work clothing should be contaminated clothing before reusing showers are close to the workstation 	r the determination of hazardous substances will of user operations generate dust, fumes, gas, vapor al exhaust ventilation or other engineering controls contaminants below any recommended or statute oneed to keep gas, vapor or dust concentrations e explosion-proof ventilation equipment. rocess equipment should be checked to ensure f environmental protection legislation. In some ineering modifications to the process equipment as to acceptable levels.		

United States

Page: 7/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 8. Exposure controls/personal protection

Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.
Gloves	: butyl rubber
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Other skin protection	: Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. The respiratory protection shall be in accordance to 29 CFR 1910.134.

Section 9. Physical and chemical properties

Appearance

Physical state	:	Solid.	
		Powder.	
Color	:	Not available.	
Odor	:	Not available.	
Odor threshold	:	Not available.	
рН	1	Not applicable.	
Melting point	1	Not available.	
Boiling point	1	Not available.	
Flash point	:	Closed cup: Not applicable.	
Auto-ignition temperature	:	Not applicable.	
Decomposition temperature	:	Not available.	
Flammability	:	Not available.	
Lower and upper explosive (flammable) limits	:	Not applicable.	
Evaporation rate	:	Not available.	
Vapor pressure	:	Not available.	
Vapor density	:	Not applicable.	
Relative density	1	1.4	
Density(lbs / gal)	:	11.68	
- • • • • • •		Media	Result
Solubility(ies)	-	cold water	Not soluble

United States

Page: 8/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 9. Physical and chemical properties

Partition coefficient: n- octanol/water	: Not applicable.
Viscosity	: Kinematic (40°C (104°F)): Not applicable.
Volatility	: 0% (v/v), 0% (w/w)
% Solid. (w/w)	: 100

Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products. Refer to protective measures listed in sections 7 and 8.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	: Depending on conditions, decomposition products may include the following materials: carbon oxides nitrogen oxides metal oxide/oxides

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
titanium dioxide	LC50 Inhalation Dusts and mists	Rat	>6.82 mg/l	4 hours
	LD50 Dermal	Rabbit	>5000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
1,3,5-tris(oxiranylmethyl) -1,3,5-triazine-2,4,6(1H,3H, 5H)-trione	LD50 Oral	Rat	138 mg/kg	-
carbon black	LD50 Oral	Rat	>10 g/kg	-
titanium dioxide (<10 microns)	LC50 Inhalation Dusts and mists	Rat	>6.82 mg/l	4 hours
,	LD50 Dermal	Rabbit	>5000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
Conclusion/Summary	: There are no data available on the second se	he mixture itself.		
rritation/Corrosion				
Conclusion/Summary				
Skin	: There are no data available on the	he mixture itself.		
Eyes	: There are no data available on the	he mixture itself.		
Respiratory	: There are no data available on the	he mixture itself.		

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 11. Toxicological information

Sensitization				
Conclusion/Summary				
Skin	1	There are	e no data av	vailable on the mixture itself.
Respiratory	1	There are	e no data av	vailable on the mixture itself.
<u>Mutagenicity</u>				
Conclusion/Summary	1	There are	e no data av	vailable on the mixture itself.
<u>Carcinogenicity</u>				
Conclusion/Summary	:	There are	e no data av	vailable on the mixture itself.
Classification				
Product/ingredient name		OSHA	IARC	NTP
titanium dioxide		-	2B	-

Product/ingredient name	USHA	IARC	NIP	
tit anium dioxide	-	2B	-	
Wollastonite	-	3	-	
carbon black	-	2B	-	
titanium dioxide (<10	-	2B	-	
microns)				

Carcinogen Classification code:

IARC: 1, 2A, 2B, 3, 4 NTP: Known to be a human carcinogen; Reasonably anticipated to be a human carcinogen OSHA: + Not listed/not regulated: -

Reproductive toxicity

Conclusion/Summary

: There are no data available on the mixture itself.

Teratogenicity

Conclusion/Summary : There are no data available on the mixture itself.

Specific target organ toxicity (single exposure)

Not available.

Specific target organ toxicity (repeated exposure)

Name		Route of exposure	Target organs
1,3,5-tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)- trione	Category 2	-	-

Target organs

: Contains material which causes damage to the following organs: skin, eyes. Contains material which may cause damage to the following organs: kidneys, lungs, the reproductive system, upper respiratory tract, , bone marrow, testes.

Aspiration hazard

Not available.

Information on the likely routes of exposure

Potential acute health effects

Eye contact	: Exposure to airborne concentrations above statutory or recommended exposure limits may cause irritation of the eyes.
Inhalation	: Exposure to airborne concentrations above statutory or recommended exposure limits may cause irritation of the nose, throat and lungs.

United States Page: 9/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 11. Toxicological information

Skin contact		May cause an allergic	skin reactior	٦.			
Ingestion		Harmful if swallowed.					
Over-exposure signs/symp				.			
Eye contact	:	Adverse symptoms m irritation redness	ay include th	e following:			
Inhalation	:	Adverse symptoms m respiratory tract irritati		e following:			
Skin contact	:	coughing Adverse symptoms m irritation redness	ay include th	e following:			
Ingestion		No specific data.					
Delayed and immediate effect		•	cts from sho	ort and long	term exposu	re	
Conclusion/Summary		There are no data ava low level of dust can p may lead to chronic re vomiting. This takes i also chronic effects of inhalation and dermal	ailable on the produce eye i espiratory irrit nto account, components	mixture itself rritation. Rep ation. Ingesti where known s from short-te	. Repeated e eated or prole on may cause , delayed and erm and long-	exposure of th onged inhalat e nausea, dia d immediate e	ion of dust arrhea and effects and
<u>Short term exposure</u>							
Potential immediate effects	:	There are no data ava	ailable on the	mixture itself			
Potential delayed effects	:	There are no data ava	ailable on the	mixture itself			
<u>Long term exposure</u>							
Potential immediate effects	:	There are no data ava	ailable on the	mixture itself			
Potential delayed effects	1	There are no data ava	ailable on the	mixture itself			
Potential chronic health eff	iect	<u>s</u>					
General	:	May cause damage to prolonged inhalation of a severe allergic react	of dust may le	ead to chronic	respiratory ir	ritation. Once	e sensitized,
Carcinogenicity	;	Suspected of causing exposure.	cancer. Ris	k of cancer de	epends on du	ration and lev	el of
Mutagenicity	1	May cause genetic de	fects.				
Reproductive toxicity	:	No known significant e	effects or crit	ical hazards.			
Numerical measures of toxic	city						
Acute toxicity estimates							
Product/ingredient name			Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases) (ppm)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/ I)

AMENCO PINK TEXTURE POLYESTER 1,3,5-tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H, 5H)-trione	549.3 100	N/A N/A	N/A N/A	N/A N/A	N/A N/A

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 12. Ecological information

Toxicity

Product/ingredient name	Result	Species	Exposure
	5	Daphnia - <i>Daphnia magna</i> Daphnia - <i>Daphnia magna</i>	48 hours 48 hours

Persistence and degradability

Not available.

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
√,3,5-tris(oxiranylmethyl) -1,3,5-triazine-2,4,6(1H,3H, 5H)-trione	-0.8	-	Low

Mobility in soil

Soil/water partition coefficient (Koc)

: Not available.

Section 13. Disposal considerations

Disposal methods

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Disposal should be in accordance with applicable regional, national and local laws and regulations.

Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees. Section 6. Accidental release measures

14. Transport information

Listed

Product name FLAMENCO PINK TEXTURE POLYESTER

14. Transport information

	DOT	IMDG	IATA
UN number	Not regulated.	Not regulated.	Not regulated.
UN proper shipping name	-	-	-
Transport hazard class (es)	-	-	-
Packing group	-	-	-
Environmental hazards	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.

Additional information

DOT: None identified.IMDG: None identified.IATA: None identified.

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

Section 15. Regulatory information

United States

United States inventory (TSCA 8b) : All components are active or exempted.

United States - TSCA 5(a)2 - Final significant new use rules:

<u>SARA 302/304</u> SARA 304 RQ

: Not applicable.

Composition/information on ingredients

No products were found.

SARA 311/312

Classification	: COMBUSTIBLE DUSTS
	ACUTE TOXICITY (oral) - Category 4
	SKIN SENSITIZATION - Category 1
	GERM CELL MUTAGENICITY - Category 1
	CARCINOGENICITY - Category 2
	SPECIFIC TARGET ORGAN TOXICITY (REPEATED EXPOSURE) - Category 2

Composition/information on ingredients

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 15. Regulatory information

Name	%	Classification
titanium dioxide	≥10 - ≤20	CARCINOGENICITY - Category 2
1,3,5-tris(oxiranylmethyl)	≥1.0 - ≤5.0	COMBUSTIBLE DUSTS
-1,3,5-triazine-2,4,6(1H,3H,5H)-		ACUTE TOXICITY (oral) - Category 3
trione		SERIOUS EYE DAMAGE - Category 1
		SKIN SENSITIZATION - Category 1B
		GERM CELL MUTAGENICITY - Category 1B
		SPECIFIC TARGET ORGAN TOXICITY (REPEATED
		EXPOSURE) - Category 2
carbon black	≤1.0	COMBUSTIBLE DUSTS
		CARCINOGENICITY - Category 2
titanium dioxide (<10 microns)	≤1.0	CARCINOGENICITY - Category 2

SARA 313

Supplier notification

Chemical name

CAS number 7,3,5-tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H, 2451-62-9 3H,5H)-trione

Concentration 1 - 5

SARA 313 notifications must not be detached from the SDS and any copying and redistribution of the SDS shall include copying and redistribution of the notice attached to copies of the SDS subsequently redistributed.

Additional environmental information is contained on the Environmental Data Sheet for this product, which can be obtained from your PPG representative.

California Prop. 65

WARNING: Cancer - www.P65Warnings.ca.gov.

2

Section 16. Other information

Hazardous Material Information System (U.S.A.)

Flammability : 0 Physical hazards : 70 Health : 2

(*) - Chronic effects

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks. Although HMIS® ratings and the associated label are not required on MSDSs or products leaving a facility under 29 CFR 1910.1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered trademark and service mark of the American Coatings Association, Inc.

The customer is responsible for determining the PPE code for this material. For more information on HMIS® Personal Protective Equipment (PPE) codes, consult the HMIS® Implementation Manual.

National Fire Protection Asso	ociation (U.S.A.)	
Health : 2 Flamma	bility : 0 Instability : 📈	
Date of previous issue	: 6/18/2021	
Organization that prepared the SDS	: EHS	
Key to abbreviations	: ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IBC = Internediate Bulk Container IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973	

United States Page: 13/14

Product name FLAMENCO PINK TEXTURE POLYESTER

Section 16. Other information

as modified by the Protocol of 1978. ("Marpol" = marine pollution) N/A = Not available SGG = Segregation Group UN = United Nations

Indicates information that has changed from previously issued version.

Disclaimer

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.