EC700 ONE - VISIT™ PRODUCTION CLEARCOAT HARDENER SELECTION GUIDE

Lower Air Movement
Temperature and Humidity

Average Air Flow & Humidity

Higher Air Movement
Temperature and Humidity

12,000 - 24,000 CFM - 30% - 90% RH

TEMPERATURE

55°F	60°F	65°F	70°F	75°F	80°F	85°F	90°F	95°F	100ºF	100ºF +
13ºC	15ºC	18ºC	21ºC	24ºC	27ºC	29ºC	32ºC	35ºC	38ºC	38ºC +

Hardener
ECH7070

Hardener
ECH7080

Hardener
ECH7090

Smaller ← **Temperature and Size of The Repair Will Affect Hardener Selection** → **Larger**