# SAFETY DATA SHEET

PHENGUARD 985 BASE GREY



#### Date of issue 2 October 2024

Version 2.01

mixture

number

**Uses advised against** 

**Emergency telephone** 

Supplier's details

# 1. Product and company identification

: Not applicable.

: 078 574 2777

Product name	: PHENGUARD 985 BASE GREY
Product code	: 00463616
Product type	: Liquid.
Relevant identified uses of	f the substance or mixture and uses advised against
Product use	: Professional applications, Used by spraying.
Use of the substance/	: Coating.

652-0803 Japan; Tel: +81-78-574-2777

: PPG PMC Japan Co., Ltd., 8F, Shintetsu Bldg., 1-1, Daikaidori 1-chome, Kobe

# 2. Hazards identification

	: FLAMMABLE LIQUIDS - Category 3 SKIN IRRITATION - Category 2 SERIOUS EYE DAMAGE - Category 1 SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 1A TOXIC TO REPRODUCTION - Category 1B SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) - Category 1 SPECIFIC TARGET ORGAN TOXICITY (REPEATED EXPOSURE) - Category 1 HAZARDOUS TO THE AQUATIC ENVIRONMENT - ACUTE HAZARD - Category 2 HAZARDOUS TO THE AQUATIC ENVIRONMENT - CHRONIC HAZARD - Category 2
GHS label elements	
Hazard pictograms	$ \land \land \land \land \land \land$
Signal word	: Danger

### FIODUCT NAME FIELOGOARD 303 BASE OR

### 2. Hazards identification

organs, nervous system, respiratory organs) Toxic to aquatic life with long lasting effects.

Precautionary statements	
Prevention	: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Avoid release to the environment. Do not breathe vapor. Do not eat, drink or smoke when using this product. Wash thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace.
Response	: Collect spillage. IF exposed or concerned: Call a POISON CENTER or doctor. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. If skin irritation or rash occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor.
Storage	: Store locked up.
Disposal	: Dispose of contents and container in accordance with all local, regional, national and international regulations.
Other hazards which do not	: Prolonged or repeated contact may dry skin and cause irritation.

Other hazards which do n result in classification

# 3. Composition/information on ingredients

Substance/mixture

: Mixture

#### **CAS number/other identifiers**

CAS number	: Not applicable.
CSCL number	: Not available.

Ingredient name	%	CAS number	CSCL
barium sulfate	25 - <50	7727-43-7	1-89
Phenol, polymer with formaldehyde, glycidyl ether (MW<=700)	20 - <25	28064-14-4	7-1285
Talc (containing no asbestos or quartz)	15 - <20	14807-96-6	Not available.
Xylene	10 - <12.5	1330-20-7	3-3; 3-60
Titanium dioxide (excluding nanoparticle)	5 - <7	13463-67-7	1-558; 5-5225
isobutyl alcohol	3 - <5	78-83-1	2-3049
Ethyl Benzene	1 - <2	100-41-4	3-28; 3-60
Crystalline silica (quartz)	0.2 - <0.5	14808-60-7	1-548
carbon black	<0.1	1333-86-4	5-3328; 5-5222

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SUB codes represent substances without registered CAS Numbers.

### 4. First aid measures

<b>Description of necess</b>	sary first aid measures
Eye contact	<ul> <li>Check for and remove any contact lenses. Immediately flush eyes with running water for at least 15 minutes, keeping eyelids open. Seek immediate medical attention.</li> </ul>
Inhalation	: Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.
Skin contact	<ul> <li>Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.</li> </ul>
Ingestion	: If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.
Most important symp	toms/effects, acute and delayed

Potential acute health effect	S	
Eye contact	:	Causes serious eye damage.
Inhalation	:	No known significant effects or critical hazards.
Skin contact	:	Causes damage to organs following a single exposure in contact with skin. Causes skin irritation. Defatting to the skin. May cause an allergic skin reaction.
Ingestion	:	Causes damage to organs following a single exposure if swallowed.
Over-exposure signs/sympt	on	<u>15</u>
Eye contact	:	Adverse symptoms may include the following: pain watering redness
Inhalation	:	Adverse symptoms may include the following: reduced fetal weight increase in fetal deaths skeletal malformations
Skin contact	-	Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformations
Ingestion	:	Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations
Indication of immediate medi	<u>ca</u>	l attention and special treatment needed, if necessary
Notes to physician	:	Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Specific treatments	:	No specific treatment.
Protection of first-aiders	:	No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing the result because the removable with water before removing it or was always.

thoroughly with water before removing it, or wear gloves.

#### See toxicological information (Section 11)

### 4. First aid measures

### 5. Fire-fighting measures

<u>Extinguishing media</u>	
Suitable extinguishing media	: Use dry chemical, CO <sub>2</sub> , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is toxic to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides sulfur oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.

# 6. Accidental release measures

#### Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Do not breathe vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	: If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	: Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmful to the environment if released in large quantities. Collect spillage.
Methods and materials for co	ntainment and cleaning up
Small spill	: Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble.

Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

### 6. Accidental release measures

Large spill: Stop leak if without risk. Move containers from spill area. Use spark-proof tools and<br/>explosion-proof equipment. Approach release from upwind. Prevent entry into<br/>sewers, water courses, basements or confined areas. Wash spillages into an<br/>effluent treatment plant or proceed as follows. Contain and collect spillage with non-<br/>combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth<br/>and place in container for disposal according to local regulations (see Section 13).<br/>Dispose of via a licensed waste disposal contractor. Contaminated absorbent<br/>material may pose the same hazard as the spilled product. Note: see Section 1 for<br/>emergency contact information and Section 13 for waste disposal.

### 7. Handling and storage

**Precautions for safe** : Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which handling this product is used. Avoid exposure - obtain special instructions before use. Avoid exposure during pregnancy. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not breathe vapor or mist. Do not ingest. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.

Conditions for safe storage : Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

### 8. Exposure controls/personal protection

#### Control parameters

#### Occupational exposure limits

Ingredient name	Exposure limits
ralc , not containing asbestiform fibres	Japan Society for Occupational Health (Japan, 5/2023) [Class 1 dusts (Activated charcoal, Alumina, Aluminium, Bentonite, Diatomite, Graphite, Kaolinite, Pagodite, Pyrites, Pyrite cinder)] OEL-M 8 hours: 2 mg/m <sup>3</sup> . Form: Total dust (Class 1 Dust). OEL-M 8 hours: 0.5 mg/m <sup>3</sup> . Form: Respirable dust (Class 1 Dust).
xylene	Japan Society for Occupational Health (Japan, 5/2023) OEL-M 8 hours: 50 ppm. OEL-M 8 hours: 217 mg/m <sup>3</sup> . Industrial Safety and Health Act (Japan,
	Japan Page: 5/14

# 8. Exposure controls/personal protection

		C/0000) [mulama]
		6/2020) [xylene]
titanium diavida		TWA 8 hours: 50 ppm.
titanium dioxide		Japan Society for Occupational Health
		(Japan, 5/2023) [titanium dioxide]
		OEL-M 8 hours: 1.5 mg/m <sup>3</sup> (as Ti). Form:
		Respirable particulate matter.
		OEL-M 8 hours: 2 mg/m³ (as Ti). Form:
		Total particulate matter.
		Japan Society for Occupational Health
		(Japan, 5/2023) [titanium dioxide
		(nanoparticle)]
		OEL-M 8 hours: 0.3 mg/m <sup>3</sup> . Form:
		nanoparticle.
2-methylpropan-1-ol		Japan Society for Occupational Health
		(Japan, 5/2023)
		OEL-M 8 hours: 50 ppm.
		OEL-M 8 hours: 150 mg/m <sup>3</sup> .
		Industrial Safety and Health Act (Japan,
		6/2020)
		TWA 8 hours: 50 ppm.
ethylbenzene		Japan Society for Occupational Health
		(Japan, 5/2023) Absorbed through skin.
		OEL-M 8 hours: 20 ppm.
		OEL-M 8 hours: $87 \text{ mg/m}^3$ .
		Industrial Safety and Health Act (Japan,
		6/2020)
		TWA 8 hours: 20 ppm.
crystalline silica, respirable p	owder (<10 microns)	Japan Society for Occupational Health
Crystalline Slica, Tespirable p		(Japan, 5/2023) [Respirable crystalline
		silica]
		OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust.
		OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to
Recommended monitoring procedures	national guidance documents for met	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust.
		OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to
	national guidance documents for met	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to
procedures	national guidance documents for met substances will also be required.	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous
	national guidance documents for met substances will also be required. : Use only with adequate ventilation. U	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous
procedures Appropriate engineering	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants
procedures Appropriate engineering	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to
procedures Appropriate engineering	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use
procedures Appropriate engineering controls	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous lse process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use
procedures Appropriate engineering controls Environmental exposure	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work pro-</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous lese process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use
procedures Appropriate engineering controls	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work pro- they comply with the requirements of</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use the openation of the ensure environmental protection legislation. In some
procedures Appropriate engineering controls Environmental exposure	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work pro- they comply with the requirements of cases, fume scrubbers, filters or engineering</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment
procedures Appropriate engineering controls Environmental exposure	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work pro- they comply with the requirements of</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment
procedures Appropriate engineering controls Environmental exposure controls	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Urrow or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work protocases, fume scrubbers, filters or engineering will be necessary to reduce emissions</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment
procedures Appropriate engineering controls Environmental exposure controls	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Urrow or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work protocases, fume scrubbers, filters or engineering will be necessary to reduce emissions</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentratior explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work prothey comply with the requirements of cases, fume scrubbers, filters or engine will be necessary to reduce emissions</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to hs below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for met substances will also be required.</li> <li>Use only with adequate ventilation. U or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentratior explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work prothey comply with the requirements of cases, fume scrubbers, filters or engine will be necessary to reduce emissions</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use cocess equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment is to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Urrest or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work protiney comply with the requirements of cases, fume scrubbers, filters or engine will be necessary to reduce emissions</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use cocess equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment s to acceptable levels.
procedures Appropriate engineering controls Environmental exposure	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Ure or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work protection or work protections for the scrubbers, filters or engine will be necessary to reduce emissions</li> <li>Wash hands, forearms and face thoro eating, smoking and using the lavator Appropriate techniques should be used</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous lese process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use to be checked to ensure environmental protection legislation. In some neering modifications to the process equipment as to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Ure or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment.</li> <li>Emissions from ventilation or work protection or work protections for the scrubbers, filters or engineering will be necessary to reduce emissions.</li> <li>Wash hands, forearms and face thoro eating, smoking and using the lavator Appropriate techniques should be use Contaminated work clothing should not be used.</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous lese process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use to access equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment is to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Ure or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment.</li> <li>Emissions from ventilation or work protection or work protections for the scrubbers, filters or engineering will be necessary to reduce emissions.</li> <li>Wash hands, forearms and face thoro eating, smoking and using the lavator Appropriate techniques should be use Contaminated work clothing should not be used.</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous lese process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use  ocess equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment is to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu Hygiene measures	<ul> <li>national guidance documents for metric substances will also be required.</li> <li>Use only with adequate ventilation. Use or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment</li> <li>Emissions from ventilation or work protection or work protection of the second secon</li></ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment a to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls Individual protection measu	<ul> <li>national guidance documents for metrisubstances will also be required.</li> <li>Use only with adequate ventilation. Ure or other engineering controls to keep below any recommended or statutory keep gas, vapor or dust concentration explosion-proof ventilation equipment.</li> <li>Emissions from ventilation or work protection or work protections for they comply with the requirements of cases, fume scrubbers, filters or engine will be necessary to reduce emissions.</li> <li>Wash hands, forearms and face thord eating, smoking and using the lavator Appropriate techniques should be use Contaminated work clothing should no contaminated clothing before reusing.</li> </ul>	OEL-C: 0.03 mg/m <sup>3</sup> . Form: Respirable dust. riate monitoring standards. Reference to hods for the determination of hazardous se process enclosures, local exhaust ventilation worker exposure to airborne contaminants limits. The engineering controls also need to as below any lower explosive limits. Use correst equipment should be checked to ensure environmental protection legislation. In some neering modifications to the process equipment a to acceptable levels.

# 8. Exposure controls/personal protection

Hand protection	<ul> <li>Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately</li> </ul>
	estimated.
Gloves	: butyl rubber
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	<ul> <li>Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.</li> </ul>
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

# 9. Physical and chemical properties

<u>Appearance</u>							
Physical state	: Liquid.						
Odor	: Characteristic.						
Boiling point	: >37.78°C (>100°F)						
Flash point	: Closed cup: 26°C (	78.8°F)					
Relative density	: 1.79						
Solubility(ies)	Media	Result					
Solubility(les)	. cold water						

10. Stability and reactivity				
Reactivity	: No specific test data related to reactivity available for this product or its ingredients.			
Chemical stability	: The product is stable.			
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.			
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products.			
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.			

### FIODUCE Halle PHENGUARD 505 BASE GRE

# 10. Stability and reactivity

Hazardous decomposition products

: Depending on conditions, decomposition products may include the following materials: carbon oxides sulfur oxides metal oxide/oxides

# 11. Toxicological information

#### Information on toxicological effects

#### Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
barium sulfate	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
Xylene	LD50 Dermal	Rabbit	1.7 g/kg	-
-	LD50 Oral	Rat	4.3 g/kg	-
Titanium dioxide (excluding nanoparticle)	LC50 Inhalation Dusts and mists	Rat	>6.82 mg/l	4 hours
. ,	LD50 Dermal	Rabbit	>5000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
isobutyl alcohol	LC50 Inhalation Vapor	Rat	24.6 mg/l	4 hours
-	LD50 Dermal	Rabbit	2460 mg/kg	-
	LD50 Oral	Rat	2830 mg/kg	-
Ethyl Benzene	LC50 Inhalation Vapor	Rat	17.8 mg/l	4 hours
-	LD50 Dermal	Rabbit	17.8 g/kg	-
	LD50 Oral	Rat	3.5 g/kg	-
carbon black	LD50 Oral	Rat	>10 g/kg	-

#### Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
Xylene	Skin - Moderate irritant	Rabbit	-	24 hours 500 mg	-

#### **Sensitization**

Not available.

#### **Mutagenicity**

Not available.

#### **Carcinogenicity**

Not available.

#### **Reproductive toxicity**

Not available.

#### **Teratogenicity**

Not available.

#### Specific target organ toxicity (single exposure)

Name	Category	Route of exposure	Target organs
Talc (containing no asbestos or quartz) Xylene	Category 1 Category 1		respiratory organs central nervous system (CNS), kidneys, liver,
isobutyl alcohol	Category 3 Category 3 Category 3		respiratory organs Narcotic effects Respiratory tract irritation Narcotic effects
	I	Ja	apan Page: 8/14

Product name PHENGUARD 985 BASE GREY

# 11. Toxicological information

Ethyl Benzene	Category 3 -	Respiratory tract
		irritation
	Category 3	Narcotic effects

#### Specific target organ toxicity (repeated exposure)

Name	Category	Route of exposure	Target organs
barium sulfate	Category 1	-	respiratory organs
Talc (containing no asbestos or quartz)	Category 1	-	respiratory organs
Xylene	Category 1	-	nervous system, respiratory organs
Titanium dioxide (excluding nanoparticle)	Category 1	-	respiratory organs
Ethyl Benzene	Category 1	-	hearing organs, nervous system
Crystalline silica (quartz)	Category 1	-	immune system, kidneys, respiratory organs
carbon black	Category 1	-	respiratory organs

#### **Aspiration hazard**

Name	Result
Xylene	ASPIRATION HAZARD - Category 1
Ethyl Benzene	ASPIRATION HAZARD - Category 1

Information on the likely routes of exposure	Not available.	
Potential acute health effec		
Eye contact	Causes serious eye damage.	
Inhalation	No known significant effects or critical hazards.	
Skin contact	Causes damage to organs following a single exposure in contact with skin skin irritation. Defatting to the skin. May cause an allergic skin reaction.	1. Causes
Ingestion	Causes damage to organs following a single exposure if swallowed.	
Symptoms related to the ph	al, chemical and toxicological characteristics	
Eye contact	Adverse symptoms may include the following: pain watering redness	
Inhalation	Adverse symptoms may include the following: reduced fetal weight increase in fetal deaths skeletal malformations	
Skin contact	Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformations	

Product code 00463616		Date of issue 2 October 2024 Version 2.01
Product name PHENGUARD	98	5 BASE GREY
11. Toxicological i	n	formation
Ingestion	:	Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations
Delayed and immediate effect	<u>ts</u>	and also chronic effects from short and long term exposure
Short term exposure		
Potential immediate effects	:	Not available.
Potential delayed effects	1	Not available.
Long term exposure		
Potential immediate effects	:	Not available.
Potential delayed effects	1	Not available.
Potential chronic health effe	ect	<u>S</u>
General	:	Causes damage to organs through prolonged or repeated exposure. Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/or dermatitis. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels.
Carcinogenicity	1	May cause cancer. Risk of cancer depends on duration and level of exposure.
Mutagenicity	:	No known significant effects or critical hazards.

**Reproductive toxicity** : May damage fertility or the unborn child.

#### Numerical measures of toxicity

Acute toxicity estimates

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)	(gases)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
PHENGUARD 985 BASE GREY	N/A	2966.2	N/A	53.7	N/A
barium sulfate	N/A	2500	N/A	N/A	N/A
Xylene	4300	1700	N/A	11	N/A
isobutyl alcohol	2830	2460	N/A	11	N/A
Ethyl Benzene	3500	17800	N/A	17.8	N/A

#### Other information

Prolonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

### **12. Ecological information**

ŝ

#### **Toxicity**

Product/ingredient name	Result	Species	Exposure
Titanium dioxide (excluding nanoparticle)	Acute LC50 >100 mg/l Fresh water	Daphnia - Daphnia magna	48 hours
isobutyl alcohol	Acute EC50 1100 mg/l	Daphnia	48 hours
Ethyl Benzene	Acute EC50 1.8 mg/l Fresh water	Daphnia	48 hours
-	Chronic NOEC 1 mg/l Fresh water	Daphnia - Ceriodaphnia dubia	-

Japan Page: 10/14

### 12. Ecological information

#### Persistence/degradability

Product/ingredient name	Test	Result		Dose		Inoculum
Ethyl Benzene	-	79 % - Rea	dily - 10 days	-		-
Product/ingredient name	Aquatic half-life		Photolysis		Biodeg	radability
Xylene Ethyl Benzene	-		-		Readily Readily	

#### **Bioaccumulative potential**

Product/ingredient name	LogPow	BCF	Potential
Xylene	3.12	7.4 to 18.5	Low
isobutyl alcohol	1	-	Low
Ethyl Benzene	3.6	79.43	Low

#### Mobility in soil

Soil/water partition coefficient (K <sub>oc</sub> )	1	Not available.
Mobility	1	Not available.

Other adverse effects

: No known significant effects or critical hazards.

### 13. Disposal considerations

**Disposal methods** The generation of waste should be avoided or minimized wherever possible. 2 Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

14. Transport information				
	UN	IMDG	IATA	1
UN number	UN1263	UN1263	UN126	63
UN proper shipping name	PAINT	PAINT	PAINT	
Transport hazard class(es)	3	3	3	
Packing group	III	III		
11		1	Japan	Page: 11/14

Product code 00 Product name Pl	0463616 HENGUARD 985 BASE GREY	Date of issue 2 Oct	ober 2024 Version 2.01
14. Transp	ort information		
Environmental hazards	No.	No.	No.
Marine pollutan substances	t Not applicable.	Not applicable.	Not applicable.
Additional inform	nation		
UN	: None identified.		
IMDG	: None identified.		
ΙΑΤΑ	: None identified.		

upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

## **15. Regulatory information**

#### **Fire Service Law**

Category	Substance name/Type	Danger category	Signal word	Designated quantity
Category IV	Class II petroleums	III	Flammable - Keep Fire Away	1000 L

#### Pollutant Release and Transfer Registers (PRTR)

Ingredient name			
Xylene	11	Class 1	80
Ethylbenzene	2.0	Class 1	53

#### **Industrial Safety and Health Act**

#### Ordinance on the Prevention of the Hazard due to Specified Chemical Substances

Ingredient name	%		Reference number
ethyl benzene	≤10	Special Organic Solvents	3-3

#### Substance(s) requiring labelling

Ingredient name	%	Status	Reference number
Xylene	≤10	Listed	136
Titanium(IV) oxide		Listed	191
Butanol		Listed	477
Ethylbenzene		Listed	70
Crystalline silica		Listed	165-2

**Chemicals requiring notification** 

Product name PHENGUARD 985 BASE GREY

# 15. Regulatory information

Ingredient name	%	Status	Reference number
Xylene	≥10 - ≤20	Listed	136
Titanium(IV) oxide	≤10	Listed	191
Butanol	≤10	Listed	477
Ethylbenzene	≤10	Listed	70
Crystalline silica	≤10	Listed	165-2
Carbon black	≤10	Listed	130

#### Carcinogens based on Article 577-2 of the Ordinance on ISH

Ingredient name	%		Reference number
quartz	≤10	Listed	-

#### <u>Mutagen</u>

None of the components are listed.

Corrosive liquid	: Not listed
Occupational Safety and Health Law	: Inflammable
Regulations on the Prevention of Tetraalkyl Lead Poisoning	: Not listed
Harmful Substances Subject to Obtaining Permission for Manufacturing	: Not listed
Harmful Substances, Prohibited for Manufacturing	: Not listed
ISHL Enforcement Order Appendix 1 - Dangerous Substances	: Inflammable
Lead regulation	: Not listed
Organic solvents poisoning prevention	: Class 2

#### Poisonous and Deleterious Substances

None of the components are listed.

#### Chemical Substances Control Law (CSCL)

Ingredient name	%	Status	Reference number
Xylene	≥10 - ≤20	Priority assessment	125
Ethylbenzene	≤10	Priority assessment	50

# High Pressure Gas Control : Not available.

#### **Explosives Control Law**

None of the components are listed.

### 15. Regulatory information

Law concerning prevention : Not available. of pollution of the ocean

#### Maritime Safety Law

#### Notification Regulating Transportation of Dangerous Materials by Sea

None of the components are listed.

#### **Container class**

None of the components are listed.

JSOH Carcinogen	: Group 1
List of Specially Controlled Industrial Waste	: Not listed
Japan inventory	: All components are listed or exempted.
Road law	: Not available.

### **16. Other information**

<u>History</u>	
Date of issue/Date of revision	: 2 October 2024
Date of previous issue	: 5/16/2024
Version	: 2.01
Prepared by	: EHS
Key to abbreviations	: ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations

**V** Indicates information that has changed from previously issued version.

#### Notice to reader

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.