SAFETY DATA SHEET

29 June 2021

Version3

Section 1 Identification

Date of issue/Date of revision

Section 1. Identification		
Product code	: 00346835	
Product name	: SIGMA ALPHAGEN 650 IN BLACK	
Other means of identification	: Not available.	
Product type	: Liquid.	
Relevant identified uses	of the substance or mixture and uses advised against	
Product use	: Antifouling products Professional applications, Used by spraying.	
Uses advised against	: Product is not intended, labelled or packaged for consumer use.	
Supplier's details	: PT PPG Coatings Indonesia JI. Rawagelam III No.1 13930 Jakarta Indonesia Tel +62 21 4605710 PMC.Safety@PPG.com	
Emergency telephone number	: CHEMTREC 001-803-017-9114 (CCN 17704)	

Section 2. Hazards identification

k	
Classification of the	: FLAMMABLE LIQUIDS - Category 3
substance or mixture	ACUTE TOXICITY (inhalation) - Category 4
	SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 1
	SKIN SENSITIZATION - Category 1
	SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Respiratory tract
	irritation) - Category 3
	AQUATIC HAZARD (ACUTE) - Category 1
	AQUATIC HAZARD (LONG-TERM) - Category 1
	Percentage of the mixture consisting of ingredient(s) of unknown acute inhalation
	toxicity: 28%
	Percentage of the mixture consisting of ingredient(s) of unknown hazards to the aquatic environment: 8.2%
	·

GHS label elements, including precautionary statements

Hazard pictograms	
Signal word	: Danger

Product code 00346835

Product name SIGMA ALPHAGEN 650 IN BLACK

Version 3

Section 2. Hazards identification

Hazard statements	:	Fammable liquid and vapor. May cause an allergic skin reaction. Causes serious eye damage. Harmful if inhaled. May cause respiratory irritation. Very toxic to aquatic life with long lasting effects.
Precautionary statements		
Prevention	:	Wear protective gloves, protective clothing and eye or face protection. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use explosion-proof electrical, ventilating or lighting equipment. Use non- sparking tools. Take action to prevent static discharges. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Avoid breathing vapor. Contaminated work clothing should not be allowed out of the workplace.
Response	:	Collect spillage. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Wash with plenty of water. If skin irritation or rash occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor.
Storage	:	Store locked up. Store in a well-ventilated place. Keep container tightly closed. Keep cool.
Disposal	:	Dispose of contents and container in accordance with all local, regional, national and international regulations.
Other hazards which do not result in classification	:	Prolonged or repeated contact may dry skin and cause irritation.

result in classification

Section 3. Composition/information on ingredients

Substance/mixture

: Mixture

CAS number/other identifiers

CAS number	: Not applicable.
EC number	: Mixture.

Ingredient name	%	CAS number
dicopper oxide	25- <50	1317-39-1
rosin	10- <20	8050-09-7
zinc oxide	10- <20	1314-13-2
4-methylpentan-2-one	5- <10	108-10-1
Solvent naphtha (petroleum), light aromatic	5- <10	64742-95-6
zineb (ISO)	5- <10	12122-67-7
1,2,4-trimethylbenzene	3- <5	95-63-6
xylene	1- <3	1330-20-7
Talc, not containing asbestiform fibers	1- <3	14807-96-6
copper oxide	0.3- <1	1317-38-0

There are no ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

SUB codes represent substances without registered CAS Numbers.

Occupational exposure limits, if available, are listed in Section 8.

Section 4. First aid measures

Description of necessary fi	rst aid measures
Eye contact	 Check for and remove any contact lenses. Immediately flush eyes with running water for at least 15 minutes, keeping eyelids open. Seek immediate medical attention.
Inhalation	: Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.
Skin contact	 Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.
Ingestion	: If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.
Most important symptoms/	effects, acute and delayed
Potential acute health effe	<u>cts</u>
Eye contact	: Causes serious eye damage.
Inhalation	: Harmful if inhaled. May cause respiratory irritation.
Skin contact	: Defatting to the skin. May cause skin dryness and irritation. May cause an allergic skin reaction.
Ingestion	: No known significant effects or critical hazards.
Over-exposure signs/sym	<u>otoms</u>
Eye contact	: Adverse symptoms may include the following: pain watering redness
Inhalation	: Adverse symptoms may include the following: respiratory tract irritation coughing
Skin contact	: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur
Ingestion	: Adverse symptoms may include the following: stomach pains
Indication of immediate me	dical attention and special treatment needed, if necessary
Notes to physician	: In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours.
Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is very toxic to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Do not breathe vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	:	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmful to the environment if released in large quantities. Collect spillage.
Methods and materials for co	nt	ainment and cleaning up
Small spill	:	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Product name SIGMA ALPHAGEN 650 IN BLACK

Section 6. Accidental release measures

Large spill

: Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling

Protective measures	:	Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Do not get in eyes or on skin or clothing. Do not breathe vapor or mist. Do not ingest. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.
Advice on general occupational hygiene	:	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
Conditions for safe storage, including any incompatibilities	:	Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

Section 8. Exposure controls/personal protection

<u>Control parameters</u> <u>Occupational exposure limits</u>

Section 8. Exposure controls/personal protection

Bisin Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). Absorbed through skin. Skin sensitizer. Inhalation sensitizer. 2inc oxide Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ² B hours. Form: respirable fraction and vapor STEL: 10 mg/m ² 15 minutes. Form: respirable fraction and vapor 4-methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 21 ang/m ² 8 hours. TWA: 20 BDS 8 hours. Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m ² 8 hours. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effective equipment. Reference should be made to appropriate monitoring standards. Reference should be ma	Ingredient name		Exposure limits
zinc oxide through skin. Skin sensitizer. Inhalation sensitizer. atmethylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). 1.2.4-trimethylpentan-2-one STEL: 10 mg/m ² 8 hours. Form: respirable fraction and vapor 1.2.4-trimethylbenzene STEL: 10 mg/m ² 15 minutes. 1.2.4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 22 BDS 8 hours. STEL: 15 BDS 15 minutes. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ² 8 hours. TWA: 25 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ² 8 hours. TWA: 123 mg/m ² 8 hours. Talc, not containing asbestiform fibers STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 16 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 mg/m ³ 8 hours. Form: respirable particles Talc, not containing asbestiform fibers If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be requirued to determine th			Minister of Labor of the Republic of
zinc oxide sensitizer. A-methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 8 hours. Form: respirable fraction and vapor 4-methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ³ 8 hours. TWA: 123 mg/m ³ 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m ³ 8 hours. TWA: 123 mg/m ³ 8 hours. Talc, not containing asbestiform fibers STEL: 651 mg/m ³ 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratole protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determinants below any recommended or sultory limits. The engineering control standards. Reference to national guidance documents for methods for the determinants below any recommender or statutory limits. The engineering control standards. Reference to national guidance documents for methods for the determinants below any recommender or statutory limits. The engineering control subsome or the regineering control sto keep worker exposure to aiborne cont			
zinc oxide Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 8 hours. Form: respirable fraction and vapor STEL: 10 mg/m ³ 15 minutes. Form: respirable fraction and vapor 4-methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ³ 8 hours. STEL: 75 BDS 15 minutes. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 424 mg/m ³ 8 hours. TWA: 120 BDS 8 hours. STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers STEL: 651 mg/m ³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 424 mg/m ³ 8 hours. STEL: 150 BDS 15 minutes. Ministry of Employment and Labor (Indonesia, 21097). STEL: 651 mg/m ³ 15 minutes. STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 8 hours. Form: respirable particles Recommended monitoring protective equipment. : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respirator protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determinants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosiv			
4-methylpentan-2-one Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable fraction and vapor STEL: 10 mg/m³ 15 minutes. Form: respirable fraction and vapor 4methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. 1,2,4-trimethylbenzene STEL: 75 BDS 15 minutes. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m³ 8 hours. TWA: 123 BDS 8 hours. Take, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m³ 8 hours. TWA: 100 BDS 15 minutes. Talc, not containing asbestiform fibers STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respirator protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determinants below any recommended or subtory limits. The engineering control is to keep worker exposure to alborne contaminants below any recommended or statuory limits. The engineering control is to keep worker exposure to alborne contaminants below any process enclosures, local exhaust wetiliation or other engineering control is to keep worker exposure to alborne control masures, and/or the necessity to user e	zinc oxide		
4-methylpentan-2-one TWA: 2 mig/m ³ 8 hours. Form: respirable fraction and vapor 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia (Indon			
4-methylpentan-2-one STEL: 10 mg/m² 15 minutes. Form: respirable fraction and vapor 4-methylpentan-2-one Minister of Labor of the Republic of Indonesia, 4/2018). TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. 1.2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m² 8 hours. TWA: 123 mg/m² 8 hours. TWA: 126 BDS 8 hours. STEL: 651 mg/m² 15 minutes. STEL: 150 BDS 15 minutes. STEL: 651 mg/m² 15 minutes. STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia, 4/2018). TWA: 100 BDS 8 hours. STEL: 651 mg/m² 15 minutes. Recommended monitoring or it fibers If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls I Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to aitborne contaminants below any recommended or statutory limits. The engineering controls to keep worker exposure to aitborne contaminants below any recommended or statutory limits. The engineering controls to keep wor			
4-methylpentan-2-one respirable fraction and vapor 4-methylpentan-2-one Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). 1,2,4-trimethylbenzene TWA: 20 BDS 8 hours. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m³ 8 hours. TWA: 123 mg/m³ 8 hours. TWA: 25 BDS 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. Broocedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to			
 4-methylpentan-2-one Indonesia (Indonesia (Indones			
1,2,4-trimethylbenzene Indonesia (Indonesia, 4/2018). TWA: 20 BDS 8 hours. 1,2,4-trimethylbenzene STEL: 75 BDS 15 minutes. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ³ 8 hours. TWA: 25 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 100 BDS 8 hours. TWA: 100 BDS 8 hours. TWA: 100 BDS 8 hours. STEL: 651 mg/m ³ 15 minutes. STEL: 50 BDS 15 minutes. STEL: 150 BDS 15 minutes. Ministry of Employment and Labor (Indonesia, 4/2018). STEL: 150 BDS 15 minutes. Tale, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 15 minutes. STEL: 150 BDS 15 minutes. Strel: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Tale, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 8 hours. Form: respirable particles Stel: 150 BDS 15 minutes. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods			
1.2,4-trimethylbenzene TWA: 20 BDS 8 hours. STEL: 75 BDS 15 minutes. 1.2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m ³ 8 hours. TWA: 25 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m ³ 8 hours. TWA: 100 BDS 8 hours. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia, 2/1997). STEL: 651 mg/m ³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m ³ 8 hours. Form: respirable particles Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legi	4-methylpentan-2-one		•
1,2,4-trimethylbenzene STEL: 75 BDS 15 minutes. 1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 123 mg/m³ 8 hours. TWA: 25 BDS 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m³ 8 hours. TWA: 434 mg/m³ 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 100 BDS 15 minutes. Talc, not containing asbestiform fibers STEL: 651 mg/m³ 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 2/1997). STEL: 651 mg/m³ 15 minutes. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls as oneed to keep gas, yaor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som			
1,2,4-trimethylbenzene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). xylene TWA: 123 BDS 8 hours. TWA: 124 BDS 8 hours. TWA: 25 BDS 8 hours. TWA: 124 Mg/m 8 hours. TWA: 126 BDS 8 hours. TWA: 120 BDS 8 hours. TWA: 120 BDS 8 hours. TWA: 100 BDS 8 hours. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m 3 the mutes. Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia, 4/2018). TWA: 2 mg/m 3 the summation of the republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m 3 the summation of the republic of Indonesia (Indonesia, 4/2018). Recommended monitoring or the summation of the republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m 3 the summation of the republic of Indonesia (Indonesia, 4/2018). Recommended monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls to keep worker exposure to airborne control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also			
xyleneIndonesia (Indonesia, 4/2018). TWA: 123 mg/m³ 8 hours. TWA: 25 BDS 8 hours. TWA: 25 BDS 8 hours. TWA: 25 BDS 8 hours. TWA: 25 BDS 8 hours. TWA: 243 mg/m³ 8 hours. TWA: 434 mg/m³ 8 hours. TWA: 434 mg/m³ 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference to national guidance documents for methods for the determination of hazardous substance			
xylene TWA: 123 mg/m³ 8 hours. TWA: 25 BDS 8 hours. minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m³ 8 hours. TWA: 434 mg/m³ 8 hours. TWA: 400 BDS 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Talc, not containing asbestiform fibers	1,2,4-trimethylbenzene		
xylene TWA: 25 BD\$ 8 hours. xylene Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m³ 8 hours. TWA: 434 mg/m³ 8 hours. TWA: 100 BDS 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particles TWA: 2 mg/m³ 8 hours. Form: respirable particles Recommended monitoring concedures If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering control to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering contro also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls			
xyleneMinister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 434 mg/m³ 8 hours. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minu			
Indonesia (Indonesia, 4/2018).TWA: 434 mg/m³ 8 hours.TWA: 100 BDS 8 hours.STEL: 651 mg/m³ 15 minutes.STEL: 651 mg/m³ 15 minutes.STEL: 150 BDS 15 minutes.Ministry of Employment and Labor(Indonesia, 2/1997).STEL: 150 BDS 15 minutes.STEL: 150 BDS 15 minutes.STEL: 150 BDS 15 minutes.Ministry of Labor of the Republic of Indonesia, 4/2018).TWA: 20 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures*If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls*Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls*Environmental exposure controls**Environmental exposure**************	vulono.		
TWA: 434 mg/m³ 8 hours. TWA: 100 BDS 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference to halonal guidance documents for methods for the determinants below any recommended or statutory limits. The engineering control sonards. Reference to national guidance documents for methods for the determinants below any recommended or statutory limits. The engineering contro also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process	xyiene		
TWA: 100 BDS 8 hours. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls:Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control sone of to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensu they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Ministry of Employment and Labor (Indonesia, 2/1997). STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls:Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne containing also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensu they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
Talc, not containing asbestiform fibersSTEL: 150 BDS 15 minutes. Ministry of Employment and Labor (Indonesia, 2/1997). STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring orocedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls:Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensu they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
Ministry of Employment and Labor (Indonesia, 2/1997).Talc, not containing asbestiform fibersSTEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls:Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne containants below any recommended or statutory limits. The engineering control so need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation or work process equipment.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som cases, furme scrubbers, filters or engineering modifications to the process			
Talc, not containing asbestiform fibers(Indonesia, 2/1997). STEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes. Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particlesRecommended monitoring procedures: If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control so need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
Talc, not containing asbestiform fibersSTEL: 651 mg/m³ 15 minutes. STEL: 150 BDS 15 minutes.Recommended monitoring procedures:If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls:Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering contraliso need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
Talc, not containing asbestiform fibers Minister of Labor of the Republic of Indonesia (Indonesia, 4/2018). TWA: 2 mg/m³ 8 hours. Form: respirable particles Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
Indonesia (Indonesia, 4/2018). Recommended monitoring procedures If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensut they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			STEL: 150 BDS 15 minutes.
TWA: 2 mg/m³ 8 hours. Form: respirable particles Recommended monitoring procedures i If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensut they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process	Talc, not containing asbestifo	rm fibers	
Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. : Emissions from ventilation or work process equipment should be checked to ensu- they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process			
 Recommended monitoring procedures If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Emissions from ventilation or work process equipment should be checked to ensut they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process 			
 atmosphere or biological monitoring may be required to determine the effectivene of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls from ventilation or work process equipment should be checked to ensut they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process 			•
 controls ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering control also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process 	•	atmosphere or biological monitoring of the ventilation or other control me protective equipment. Reference sl standards. Reference to national gu	y may be required to determine the effectiveness easures and/or the necessity to use respiratory hould be made to appropriate monitoring uidance documents for methods for the
 contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control control control control control control control control control control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. The engineering control contaminants below any recommended or statutory limits. 			
 Imits. Use explosion-proof ventilation equipment. Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process 	.0111 015	contaminants below any recommen	ded or statutory limits. The engineering controls
controls they comply with the requirements of environmental protection legislation. In som cases, fume scrubbers, filters or engineering modifications to the process		limits. Use explosion-proof ventilati	on equipment.
	-	they comply with the requirements of cases, fume scrubbers, filters or en	of environmental protection legislation. In some gineering modifications to the process

Individual protection measures

Indonesia	* Page: 6/13

Product code 00346835

Version 3

Product name SIGMA ALPHAGEN 650 IN BLACK

Section 8. Exposure controls/personal protection

Hygiene measures	: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Eye/face protection	: Chemical splash goggles and face shield.
Skin protection	
Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.
Gloves	: butyl rubber
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	 Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

Section 9. Physical and chemical properties

<u>Appearance</u>	
Physical state	: Liquid.
Color	: Black.
Odor	: Characteristic.
Odor threshold	: Not available.
рН	: Not applicable.
Melting point	: Not available.
Boiling point	: >37.78°C (>100°F)
Flash point	: Closed cup: 34°C (93.2°F)
Evaporation rate	: Not available.
Flammability/Combustible properties (solid, gas)	: Not available.
Lower and upper explosive (flammable) limits	: Greatest known range: Lower: 1.4% Upper: 7.6% (Solvent naphtha (petroleum), light aromatic)
Vapor pressure	: Not available.
Vapor density	: Not available.

Section 9. Physical and chemical properties

Relative density	: 1.62
Solubility	: Insoluble in the following materials: cold water.
Partition coefficient: n- octanol/water	: Not applicable.
Auto-ignition temperature	: Not available.
Decomposition temperature	: Not available.
Viscosity	: K inematic (40°C): >21 mm²/s

Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	: Depending on conditions, decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
dícopper oxide	LC50 Inhalation Dusts and mists	Rat	3.34 mg/l	4 hours
	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	1340 mg/kg	-
rosin	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	7600 mg/kg	-
zinc oxide	LC50 Inhalation Dusts and mists	Rat	>5700 mg/m ³	4 hours
	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
4-methylpentan-2-one	LC50 Inhalation Vapor	Rat	12.3 mg/l	4 hours
	LD50 Dermal	Rabbit	>5000 mg/kg	-
	LD50 Oral	Rat	2.08 g/kg	-
Solvent naphtha (petroleum),	LD50 Dermal	Rabbit	3.48 g/kg	-
light aromatic				
	LD50 Oral	Rat	8400 mg/kg	-
zineb (ISO)	LD50 Oral	Rat	>2000 mg/kg	-
1,2,4-trimethylbenzene	LC50 Inhalation Vapor	Rat	18000 mg/m ³	4 hours
-	LD50 Oral	Rat	5 g/kg	-
xylene	LD50 Dermal	Rabbit	1.7 g/kg	-
-	LD50 Oral	Rat	4.3 g/kg	-
copper oxide	LD50 Oral	Rat	>2000 mg/kg	-

Product code 00346835

Product name SIGMA ALPHAGEN 650 IN BLACK

Date of issue 29 June 2021

Version 3

Section 11. Toxicological information

: There are no data available on the mixture itself.

Irritation/Corrosion

Result	Species	Score	Exposure	Observation
Skin - Moderate irritant	Rabbit	-	24 hours 500 mg	-
				Skin - Moderate irritant Rabbit - 24 hours 500

Conclusion/Summary

:	There are no data available on the mixture itself.	
---	--	--

Eyes	: There are no data available on the mixture itself.
Respiratory	: There are no data available on the mixture itself.

Respiratory Sensitization

Skin

Product/ingredient name	Route of exposure	Species	Result
zineb (ISO)	skin	Guinea pig	Sensitizing
Conclusion/Summany			•

Conclusion/Summary		
Skin	: There are no data available on the mixture itself.	
Respiratory	: There are no data available on the mixture itself.	
<u>Mutagenicity</u>		
Conclusion/Summary	: There are no data available on the mixture itself.	
Carcinogenicity		
Conclusion/Summary	: There are no data available on the mixture itself.	
Reproductive toxicity		
Conclusion/Summary	: There are no data available on the mixture itself.	
Teratogenicity		
Conclusion/Summary	: There are no data available on the mixture itself.	

Specific target organ toxicity (single exposure)

Name	Category	Route of exposure	Target organs
✓-methylpentan-2-one	Category 3	-	Respiratory tract irritation
Solvent naphtha (petroleum), light aromatic	Category 3	-	Respiratory tract irritation
	Category 3		Narcotic effects
zineb (ISO)	Category 3	-	Respiratory tract irritation
1,2,4-trimethylbenzene	Category 3	-	Respiratory tract irritation
xylene	Category 3	-	Respiratory tract irritation
Talc, not containing asbestiform fibers	Category 3	-	Respiratory tract irritation

Specific target organ toxicity (repeated exposure)

Not available.

Aspiration hazard

Section 11. Toxicological information

Name	Result
	ASPIRATION HAZARD - Category 1 ASPIRATION HAZARD - Category 1

Information on the likely routes of exposure	:	Not available.
Potential acute health effects		
Eye contact	1	Causes serious eye damage.
Inhalation	1	Harmful if inhaled. May cause respiratory irritation.
Skin contact	:	Defatting to the skin. May cause skin dryness and irritation. May cause an allergic skin reaction.
Ingestion	1	No known significant effects or critical hazards.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact	: Adverse symptoms may include the following: pain watering redness
Inhalation	: Adverse symptoms may include the following: respiratory tract irritation coughing
Skin contact	: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur
Ingestion	: Adverse symptoms may include the following: stomach pains

Delayed and immediate effe	cts and also chronic effects from short and long term exposure
Short term exposure	
Potential immediate effects	: There are no data available on the mixture itself.
Potential delayed effects	: There are no data available on the mixture itself.
<u>Long term exposure</u>	
Potential immediate effects	: There are no data available on the mixture itself.
Potential delayed effects	: There are no data available on the mixture itself.
Potential chronic health ef	ects
General	: Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/ or dermatitis. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels.
Carcinogenicity	: No known significant effects or critical hazards.
Mutagenicity	: No known significant effects or critical hazards.
Reproductive toxicity	: No known significant effects or critical hazards.

Section 11. Toxicological information

Numerical measures of toxicity

Acute toxicity estimates

Route	ATE value
Øral	4655.2 mg/kg
Dermal	80756.72 mg/kg
Inhalation (vapors)	67.16 mg/l
Inhalation (dusts and mists)	3.94 mg/l

Other information

Folonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

Section 12. Ecological information

Toxicity

Product/ingredient name	Result	Species	Exposure
dicopper oxide	LC50 0.003 mg/l	Fish	96 hours
zinc oxide	Acute EC50 0.17 mg/l	Algae	72 hours
	Acute EC50 0.481 mg/l Fresh water	Daphnia - Daphnia magna -	48 hours
		Neonate	
	Chronic NOEC 0.017 mg/l Fresh water	Algae	72 hours
4-methylpentan-2-one	Acute LC50 >179 mg/l	Fish	96 hours
Solvent naphtha (petroleum), light aromatic	Acute LC50 8.2 mg/l	Fish	96 hours

Persistence/degradability

Product/ingredient name	Test	Result		Dose	Inoculum
-methylpentan-2-one	OECD 301F	83 % - Readily - 28	days	-	-
Product/ingredient name	Aquatic half-life		Photolysis	5	Biodegradability
<pre> #-methylpentan-2-one xylene </pre>	-		-		Readily Readily

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
rosin	1.9 to 7.7	-	high
4-methylpentan-2-one	1.9	-	low
zineb (ISO)	1.3	-	low
1,2,4-trimethylbenzene	3.63	120.23	low
xylene	3.12	7.4 to 18.5	low

Mobility in soil

Soil/water partition coefficient (Koc)

: Not available.

Indonesia Page: 11/13

Section 12. Ecological information

Other adverse effects

: No known significant effects or critical hazards.

Section 13. Disposal considerations

Disposal methods	: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non- recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil,
	waterways, drains and sewers.

Section 14. Transport information

	UN	IMDG	ΙΑΤΑ
UN number	UN1263	UN1263	UN1263
UN proper shipping name	PAINT	PAINT	PAINT
Transport hazard class(es)	3	3	3
Packing group	III	III	III
Environmental hazards	Yes. The environmentally hazardous substance mark is not required.	Yes.	Yes. The environmentally hazardous substance mark is not required.
Marine pollutant substances	Not applicable.	(dicopper oxide, zinc oxide)	Not applicable.

Additional information

IMDG

- UN : None identified.
 - : The marine pollutant mark is not required when transported in sizes of ≤ 5 L or ≤ 5 kg.
- : The environmentally hazardous substance mark may appear if required by other transportation ΙΑΤΑ regulations.
- Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

Section 15. Regulatory information

Safety, health and environmental regulations specific for the product : No known specific national and/or regional regulations applicable to this product (including its ingredients).

Law No. 74/2001 - Banned

None of the components are listed.

Law No. 74/2001 - Restricted

None of the components are listed.

Law No. 74/2001 - : Not determined Chemicals that may be used

International regulations

Montreal Protocol

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Section 16. Other information

<u>History</u>	
Date of issue/Date of revision	: 29 June 2021
Date of previous issue	: 11/24/2019
Version	: 3
Prepared by	: EHS
Key to abbreviations	 ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations
Vindiantan information th	at has shewyod fysys wysylaydy lasyad ysystem

Indicates information that has changed from previously issued version.

Notice to reader

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.