SAFETY DATA SHEET

Safety Data Sheet according to GB/T 16483-2008 and GB/T 17519-2013



Date of issue/Date of revision 30 July 2021

Version 6

Product code	: 00226474
Product name	: SIGMACOVER 522 BASE REDBROWN 9028
Product name	: SIGMACOVER 522 BASE REDBROWN 9028
Product type	: Liquid.
Relevant identified uses o	f the substance or mixture and uses advised against
Product use	: Professional applications, Used by spraying.
Use of the substance/ mixture	: Coating.
Uses advised against	: Not applicable.
Supplier's details	: PPG Coatings (Kunshan) Co., Ltd 53 Jinyang Road, Lujia Town, 215331 Kunshan City, Jiangsu Province, P.R. China Tel: 86 512 57678859 Fax: 86 512 57678857
Emergency telephone number (with hours of operation)	: 00 86 532 83889090

Section 2. Hazards identification

Classification of the substance or mixture according to GB 13690-2009 and GB 30000-2013

Emergency overview Liquid. Brownish-red. Aromatic. Fammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Prolonged or repeated contact may dry skin and cause irritation.

I exposed or concerned: Get medical advice or attention. IF INHALED: Call a POISON CENTER or doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. If skin irritation or rash occurs: Get medical advice or attention. If eye irritation persists: Get medical advice or attention.

See Section 12 for environmental precautions.

Date of issue 30 July 2021

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 2. Hazards identification

48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute der toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Fercentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Hazard pictograms : : <th></th> <th></th>		
ACUTE TOXICITY (dermal). Category 5 ACUTE TOXICITY (inhibitation). Category 4 SKIN CORROSION/IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2 SKIN SENSITIZATION - Category 1 CARCINOGENUCITY - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute are toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Hazard pictograms I Warning Facenatage of the anizture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word I Warning Hazard statements Hazard statements Percentage of the anizture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% CHS label elements Hazard statements Procentage and the mixture consisting of ingredient(s) of unknown acute are toxicity, 75.9% CHS label elements Hazard statements Percenting Percenting in the instructions before use. Do not handle until all safety preca Prevention Prevention Enclass and and understood.	Classification of the	: FLAMMABLE LIQUIDS - Category 3
ACUTE TOXICITY (inhalation) - Category 4 SKIN CORROSION(IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A SKIN SENSITIZATION - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute der toxidy, 63% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxidy, 75.9% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word Hazard pictograms : Varning Hazard statements : Fermable liquid and vapor. May cause an allergic skin reaction. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful to aquatic life. Precoutionary statements : Provention : : Øbtain special instructions before use. Do not handle until all safety preca have been read and understood. Wear protective gloves, ported citercal, we or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-area, and/or leases to the environment. Avoid release to the environment. Avoid release to the environting vapor. Wash the after handling. Contaminated work	substance or mixture	
SKIN CORROSION/IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% CHS label elements Hazard pictograms Image: Signal word Hazard statements Hazard statements Percentage of cause an allergic skin reaction. Causes an allergic skin reaction. Causes an allergic skin reaction. Causes an allergic skin reaction. Causes are initiation. May cause an allergic skin reaction. Causes are initiation. Harmful to aquatic life. Prevention Image bein read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open 1 and other ignition sources. No smoking. Use encloans of the attrates avoid release to the environment. Avoid release cautions protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open 1 and other ignition sources. No smoking. Use encloand out or to workplace. Response Image: Percenter tight with water. If NNLAED. Percenter tight workplace. Response Image: P		
SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 1 SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 2 AQUATIC HAZARD (ACUTE) - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Hazard pictograms Image: Signal word Hazard statements Image: Signal word Hazard pictograms Image: Signal word Hazard statements Image: Signal word Hazard pictograms Image: Signal word Hazard pictograms Image: Signal word Hazard statements		
SKIN SENSITIZATION - Category 1 CARCONGENCITY - Category 2 AQUATIC HAZARD (ACUTE) - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word : Hazard pictograms : Variantiation : May be hamful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes skin irritation. May cause an allergic skin reaction. Causes skin irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Prevention : Stain special instructions before use. Do not handle until all safety precathave been read and understood. Wear protective gloves, protective clothin eye of face protection. Keep away from heat, hot suffaces, sparks, open fi and other ignition sources. No smoking. Use explosion-proof electrical, we or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightify closed. Use only outdoors or in a welkarea. Avoid release to the environment. Avoid breathing		
 CARCINOGENICITY - Category 2 AQUATIC HAZARD (ACUTE) - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% CHS label elements Hazard pictograms Warning Firanmable liquid and vapor. May be harmful if swallowed or in contact with skin. Category and an analysis of the set of the contact with skin. Category and the set of the analysis of the set of the set of the set of the available set of the analysis of the set of the se		SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A
AQUATIC HAZARD (ACUTE) - Category 3 Percentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Hazard pictograms : Vercentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word : Hazard statements : May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Prevention : Prevention : : Distain special instructions before use. Do not handle until all safety precat have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fi and drife righton sources. No smoking. Use explosion-proof electrical, we or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tighty closed. Use only outdoors or in a well-area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace. Response : : : : : : : :<		
Fercentage of the mixture consisting of ingredient(s) of unknown acute ora 48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Fercentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word : Hazard statements Hazard statements 'Farmable liquid and vapor: May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Precautionary statements 'Data inspecial instructions before use. Do not handle until all safety precanhave been read and understood. Wear protective glows, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fi and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tighty closed. Use only outdoors or in a well-area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace. Response 'F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or dy ou feel unwell. IF SMXLLOWED: Call a POISON CENTER or dy ou feel unwell. IF SMXLLOWED: Call a POISON CENTER or or you feel unwell. IF SMXLLOWED: Call a POISON CENTER or or you feel unwell. IF SMXLLOWED: Call a POISON CENTER or or you feel unwell. IF SMXLLOWED: Call a POISON CENTER or or you feel unwell. IF SMXLLOWED: Call a POISO		
48.8% Percentage of the mixture consisting of ingredient(s) of unknown acute der toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% Fercentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Hazard pictograms : : <td></td> <td>AQUATIC HAZARD (ACUTE) - Category 3</td>		AQUATIC HAZARD (ACUTE) - Category 3
Percentage of the mixture consisting of ingredient(s) of unknown acute der toxicity: 63% Percentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% GHS label elements Fercentage of the mixture consisting of ingredient(s) of unknown hazards t aquatic environment: 75.9% Signal word :		✓ Fercentage of the mixture consisting of ingredient(s) of unknown acute oral toxicity: 48.8%
Percentage of the mixture consisting of ingredient(s) of unknown acute inh toxicity: 75.9% GHS label elements Hazard pictograms : : Signal word : Hazard statements Hazard statements : : 'Flammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin intration. May causes an allergic skin reaction. Causes serious eye iritation. Harmful if inheld. Suspected of causing cancer. Harmful if ouderstore. Harmful if inheld. Suspected of causing cancer. Harmful if inheld. Suspected of causing cancer. Harmful if inheld. Suspected of causing cancer. Harmful if inscretcion. Keep away from heat, hot surfaces, sparks, open f and other ignition sources. No smoking. Use explosion-proof electrical, we or face protection. void release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace. Response : Fexposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep		Percentage of the mixture consisting of ingredient(s) of unknown acute dermal
GHS label elements Hazard pictograms : image: ima		Percentage of the mixture consisting of ingredient(s) of unknown acute inhalation
Hazard pictograms :		Percentage of the mixture consisting of ingredient(s) of unknown hazards to the
Signal word Hazard statements: WarningEFrammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements: Øbtain special instructions before use. Do not handle until all safety precau have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fi and other ignition sources. No smoking. Use explosion-proof electrical, we or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well- area. Avoid release to the environment. Avoid breathing vapor. Wash the date rhandling. Contaminated work clothing should not be allowed out of th workplace.Response: IF exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or of you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF NS SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF SWALLOWED: Call a POISON CENTER or of you feel unwell. IF SWALLOWED: Call a POISON CENTER or of you feel unwell. IF NS skin with jenty of water. If skin irritation or rash occurs: medical advice or attention. IF INHALED: R emotion persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.	GHS label elements	
Signal word Hazard statements: WarningEFrammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements: Øbtain special instructions before use. Do not handle until all safety precau have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fi and other ignition sources. No smoking. Use explosion-proof electrical, we or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well- area. Avoid release to the environment. Avoid breathing vapor. Wash the date rhandling. Contaminated work clothing should not be allowed out of th workplace.Response: IF exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or of you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF NS SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF SWALLOWED: Call a POISON CENTER or of you feel unwell. IF SWALLOWED: Call a POISON CENTER or of you feel unwell. IF NS skin with jenty of water. If skin irritation or rash occurs: medical advice or attention. IF INHALED: R emotion persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.	Hazard pictograms	
Hazard statements:Frammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May causes an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Image: Dist		
Hazard statements:Frammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May causes an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Image: Dist		$\langle \langle \langle \rangle \rangle \langle \langle \rangle \rangle \langle \langle \rangle \rangle \langle \langle \rangle \rangle \rangle$
Hazard statements:Frammable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May causes an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Prevention:Image: District Statements:Image: District Statements:Image: District Statements:Prevention:Image: District Statements:Image: Dist		
Hazard statements: Framable liquid and vapor. May be harmful if swallowed or in contact with skin. Causes skin irritation. May causes an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statements:Prevention: Øbtain special instructions before use. Do not handle until all safety preca have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: If exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or d you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or d you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.		v v v
May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety preca have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: If exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or d you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminata clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.	Signal word	: Warning
May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety preca have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: If exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or d you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminata clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.	Hazard statements	• Fammable liquid and vapor
Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety preca have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well- area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: Ørexposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or of you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. IF ON SKIN: Call a POISON CENTER or of you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for se minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.	nazara otatomonto	
May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life.Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety precau have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: IF exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or d you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or d you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for se minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.		
Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Harmful to aquatic life. Prevention : Øbtain special instructions before use. Do not handle until all safety precauthave been read and understood. Wear protective gloves, protective clothiney or face protection. Keep away from heat, hot surfaces, sparks, open fland other ignition sources. No smoking. Use explosion-proof electrical, veor lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-varea. Avoid release to the environment. Avoid breathing vapor. Wash thot after handling. Contaminated work clothing should not be allowed out of thworkplace. Response : Prexposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or do you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF INHALED: R medical advice or attention. IF IN EYES: Rinse cautiously with water for see minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing : Use dry chemical, CO ₂ , water spray (fog) or foam.		
Harmful if inhaled.Suspected of causing cancer.Harmful to aquatic life.Prevention: Øbtain special instructions before use. Do not handle until all safety precar have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace.Response: IF exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or of you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for se minutes. Remove contact lenses, if present and easy to do. Continue rinsi irritation persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.		
Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety precau have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash tho after handling. Contaminated work clothing should not be allowed out of th workplace.Response: F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. If Skin irritation or rash occurs: medical advice or attention. IF INH actors and u feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF INEYES: Rinse cautiously with water for se minutes. Remove contact lenses, if present and easy to do. Continue rinsin irritation persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.		
Precautionary statementsPrevention: Øbtain special instructions before use. Do not handle until all safety precau have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-v area. Avoid release to the environment. Avoid breathing vapor. Wash tho after handling. Contaminated work clothing should not be allowed out of th workplace.Response: F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. If Skin irritation or rash occurs: medical advice or attention. IF INH actors and u feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF INEYES: Rinse cautiously with water for se minutes. Remove contact lenses, if present and easy to do. Continue rinsin irritation persists: Get medical advice or attention.Suitable extinguishing: Use dry chemical, CO2, water spray (fog) or foam.		Suspected of causing cancer.
 Prevention Stain special instructions before use. Do not handle until all safety precat have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-varea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for see minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Use dry chemical, CO₂, water spray (fog) or foam. 		
 Prevention Stain special instructions before use. Do not handle until all safety precat have been read and understood. Wear protective gloves, protective clothin eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-varea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for see minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Use dry chemical, CO₂, water spray (fog) or foam. 	Precautionary statements	
 Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or og you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		• Obtain special instructions before use . Do not handle until all safety precautions
 eye or face protection. Keep away from heat, hot surfaces, sparks, open fl and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-varea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of th workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CENTER or do you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Suitable extinguishing 		
 and other ignition sources. No smoking. Use explosion-proof electrical, ve or lighting equipment. Use non-sparking tools. Take action to prevent stat discharges. Keep container tightly closed. Use only outdoors or in a well-varea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Use dry chemical, CO₂, water spray (fog) or foam. 		
 r lighting equipment. Use non-sparking tools. Take action to prevent statt discharges. Keep container tightly closed. Use only outdoors or in a well-warea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Use dry chemical, CO₂, water spray (fog) or foam. 		
 discharges. Keep container tightly closed. Use only outdoors or in a well-warea. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Suitable extinguishing 		
 area. Avoid release to the environment. Avoid breathing vapor. Wash the after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		discharges. Keep container tightly closed. Use only outdoors or in a well-ventilated
 after handling. Contaminated work clothing should not be allowed out of the workplace. Response F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Use dry chemical, CO₂, water spray (fog) or foam. 		area. Avoid release to the environment. Avoid breathing vapor. Wash thoroughly
 Response : F exposed or concerned: Get medical advice or attention. IF INHALED: R person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. : Use dry chemical, CO₂, water spray (fog) or foam. 		after handling. Contaminated work clothing should not be allowed out of the
 person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		workplace.
 person to fresh air and keep comfortable for breathing. Call a POISON CE doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 	Response	: 📕 exposed or concerned: Get medical advice or attention. IF INHALED: Remove
 doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or do you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminate clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or or you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		person to fresh air and keep comfortable for breathing. Call a POISON CENTER or
 clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		doctor if you feel unwell. IF SWALLOWED: Call a POISON CENTER or doctor if
 clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or of you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated
 you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: medical advice or attention. IF IN EYES: Rinse cautiously with water for seminutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or doctor if
 minutes. Remove contact lenses, if present and easy to do. Continue rinsir irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: Get
 irritation persists: Get medical advice or attention. Suitable extinguishing Use dry chemical, CO₂, water spray (fog) or foam. 		medical advice or attention. IF IN EYES: Rinse cautiously with water for several
Suitable extinguishing : Use dry chemical, CO ₂ , water spray (fog) or foam.		minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye
	Suitable extinguishing	: Use dry chemical, CO ₂ , water spray (fog) or foam.
III GAIA	media	
China F		China Page: 2/13

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 2. Hazards identification

Storage	4	Store locked up. Store in a well-ventilated place. Keep cool.
Disposal	:	Dispose of contents and container in accordance with all local, regional, national and international regulations.
Physical and chemical hazards	:	Flammable liquid and vapor.
Health hazards	:	May be harmful if swallowed or in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Prolonged or repeated contact may dry skin and cause irritation.
Symptoms related to the phy	sic	cal, chemical and toxicological characteristics
Eye contact	:	Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	:	No specific data.
Skin contact	:	Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	1	No specific data.
Delayed and immediate effec	<u>ts</u>	and also chronic effects from short and long term exposure
<u>Short term exposure</u>		
Potential immediate effects	:	Not available.
Potential delayed effects Long term exposure	:	Not available.
Potential immediate effects	:	Not available.
Potential delayed effects	:	Not available.
Environmental hazards	:	Harmful to aquatic life.
Other hazards which do not result in classification	:	Frolonged or repeated contact may dry skin and cause irritation.
Section 3. Compos	si	tion/information on ingredients

Substance/mixture : Mixture

CAS number/other identifiers

CAS number

: Not applicable.

Date of issue 30 July 2021

Version 6

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 3. Composition/information on ingredients

Ingredient name	%	CAS number
	10 - <25	25036-25-3
Epoxy Resin (700 <mw<=1100) isomers="" mixture<="" td="" xylene=""><td>10 - <25</td><td>1330-20-7</td></mw<=1100)>	10 - <25	1330-20-7
Talc, not containing asbestiform fibers	1 - <10	14807-96-6
ethylbenzene	1 - <10	100-41-4
2-methylpropan-1-ol	1 - <10	78-83-1

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SUB codes represent substances without registered CAS Numbers.

Section 4. First aid measures

Description of necessary first aid measures		
Eye contact	 Remove contact lenses, irrigate copiously with clean, fresh water, holding the eyelids apart for at least 10 minutes and seek immediate medical advice. 	
Inhalation	: Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.	
Skin contact	 Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners. 	
Ingestion	 If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting. 	

Most important symptoms/effects, acute and delayed

		China	Page: 4/13
Notes to physician	Treat symptomatically. Contact poison treatment specialist ir quantities have been ingested or inhaled.	nmediately if	large
Indication of immediate medic	al attention and special treatment needed, if necessary		
Ingestion	No specific data.		
	Adverse symptoms may include the following: irritation redness dryness cracking		
Inhalation	pain or irritation watering redness No specific data.		
Eye contact	Adverse symptoms may include the following:		
Over-exposure signs/sympto	<u>ms</u>		
Ingestion	May be harmful if swallowed.		
Skin contact	May be harmful in contact with skin. Causes skin irritation. E May cause an allergic skin reaction.	Defatting to the	ne skin.
Inhalation	Harmful if inhaled.		
Eye contact	Causes serious eye irritation.		
Potential acute health effects			

Section 4. First aid measures

Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

Date of issue 30 July 2021

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is harmful to aquatic life. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

For non-emergency personnel	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	:	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".

Date of issue 30 July 2021

Version 6

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 6. Accidental release measures

Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material.
		May be harmful to the environment if released in large quantities.

Methods and materials for containment and cleaning up Small spill : Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor. Large spill Stop leak if without risk. Move containers from spill area. Use spark-proof tools and • explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with noncombustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling	Fut on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapor or mist. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.
Conditions for safe storage, including any incompatibilities	Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

Version 6

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

Weine isomers mixture Gitz 2.1 (China, 8/2019). PC-STE:: 100 mg/m ² 15 minutes. PC-TWA: 50 mg/m ² 8 hours. Form: respirable dust PC-TWA: 3 mg/m ² 8 hours. Form: respirable dust PC-TWA: 100 mg/m ² 16 minutes. PC-TWA: 100 mg/m ² 16 minutes. PC-TWA: 100 mg/m ² 16 minutes. PC-TWA: 100 mg/m ² 16 hours. 2-methylpropan-1-ol If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other regioneering or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proor ventilation ess equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fum esclubers, filters or engineering modifications to the process. equipment will be necessary to reduce emissions to acceptable levels. Mygiene measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working products, working contaminated work koting before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Skin protection <th>Ingredient name</th> <th></th> <th>Exposure limits</th>	Ingredient name		Exposure limits
ethylbenzene PC-TWA: 1 mg/m3 hours. Form: respirable dust PC-TWA: 3 mg/m3 hours. Form: total dust GEZ 2.1 (China, 8/2019). 2-methylpropan-1-ol PC-STEL: 150 mg/m1 5 minutes. PC-TWA: 150 mg/m1 5 minutes. PC-TWA: 150 mg/m1 5 hours. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proor dust concentrations below any rower explosive limits. Use explosion-proor dust concentrations below any lower explosive limits. Use explosion-proor dust concentrations below any lower explosive limits. Use explosion-proor dust concentrations below any lower explosive limits. Use explosion-proor dust concess equipment should be checked to ensure taese, me scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. ndividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the workplace. Wash contaminated tothing before rus		m fibers	PC-STEL: 100 mg/m ³ 15 minutes. PC-TWA: 50 mg/m ³ 8 hours.
2-methylpropan-1-ol PC-STE:L 150 mg/m³ 5 hours: ACGHTLV (United States, 3/2020). TWA: 152 mg/m³ 6 hours: ACGHTLV (United States, 3/2020). TWA: 152 mg/m³ 6 hours. TWA: 50 ppm 8 hours. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. ndividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the workplace. Wash contaminated work tothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye protection : Chemic	Tale, not containing assession inbers		PC-TWA: 1 mg/m ³ 8 hours. Form: respirable dust
TWA: 152 ppm8 hours. TWA: 50 ppm8 hours. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. ndividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the workplace. Wash contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye protection : Chemical resistant, impervious gloves complying with an approved standard should be worn at	ethylbenzene		PC-STEL: 150 mg/m ³ 15 minutes.
procedures atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended of statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any locate explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. ndividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be calowed out of the working exerc. Wash contaminated work clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye protection : Chemical-resistant, impervious gloves complying with an approved standard should be worm and alt times when handling chemical products if a risk assessment indicates this is necessary. Considering the prameters speclified by the glove manufacturer, check during use th	2-methylpropan-1-ol		TWA: 152 mg/m ³ 8 hours.
controlsventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.ndividual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection Hand protection: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.		atmosphere or biological n of the ventilation or other of protective equipment. Ref standards. Reference to r	nonitoring may be required to determine the effectiveness control measures and/or the necessity to use respiratory erence should be made to appropriate monitoring national guidance documents for methods for the
controlsthey comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures•Hygiene measures•Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection•Skin protection•Hand protection•Hand protection•Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the glove are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.Gloves•butyl rubber		ventilation or other engine contaminants below any re also need to keep gas, va	ering controls to keep worker exposure to airborne ecommended or statutory limits. The engineering controls por or dust concentrations below any lower explosive
Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection: Chemical splash goggles.Skin protection: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.Gloves: butyl rubber		they comply with the requine cases, fume scrubbers, fill	rements of environmental protection legislation. In some ers or engineering modifications to the process
 eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye protection Chemical splash goggles. Skin protection Hand protection Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. Gloves 	ndividual protection measure	e <u>s</u>	
Skin protection Hand protection : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. Gloves : butyl rubber	Hygiene measures	eating, smoking and using Appropriate techniques sh Contaminated work clothir contaminated clothing befo	the lavatory and at the end of the working period. ould be used to remove potentially contaminated clothing. In should not be allowed out of the workplace. Wash pre reusing. Ensure that eyewash stations and safety
 Hand protection Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. Butyl rubber 	Eye protection	: Chemical splash goggles.	
 be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. Gloves : butyl rubber 			
-	Hand protection	be worn at all times when this is necessary. Conside check during use that the should be noted that the til different for different glove several substances, the pr estimated.	handling chemical products if a risk assessment indicates ering the parameters specified by the glove manufacturer, gloves are still retaining their protective properties. It me to breakthrough for any glove material may be manufacturers. In the case of mixtures, consisting of
China Page: 7/13	Gloves	: butyl rubber	
			China Page: 7/13

Section 8. Exposure controls/personal protection

•	
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	 Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

Section 9. Physical and chemical properties

<u>Appearance</u>	
Physical state	: Liquid.
Color	: Brownish-red.
Odor	: Aromatic.
Boiling point	: >37.78°C (>100°F)
Flash point	: Closed cup: 27°C (80.6°F)
Lower and upper explosive (flammable) limits	: Greatest known range: Lower: 1.7% Upper: 10.9% (2-methylpropan-1-ol)
Relative density	: 1.93
Solubility	: Insoluble in the following materials: cold water.
Viscosity	: K inematic (40°C): >21 mm²/s

Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	: Depending on conditions, decomposition products may include the following materials: carbon oxides metal oxide/oxides

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
Epoxy Resin (700 <mw<=1100)< p=""></mw<=1100)<>	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	>2000 mg/kg	-
xylene isomers mixture	LD50 Dermal	Rabbit	1.7 g/kg	-
	LD50 Oral	Rat	4.3 g/kg	-
ethylbenzene	LC50 Inhalation Vapor	Rat	17.8 mg/l	4 hours
	LD50 Dermal	Rabbit	17.8 g/kg	-
	LD50 Oral	Rat	3.5 g/kg	-
2-methylpropan-1-ol	LC50 Inhalation Vapor	Rat	24.6 mg/l	4 hours
	LD50 Dermal	Rabbit	2460 mg/kg	-
	LD50 Oral	Rat	2830 mg/kg	-

Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
ylene isomers mixture	Skin - Moderate irritant	Rabbit	-	24 hours 500	-
				mg	

Sensitization

Not available.

Mutagenicity

Not available.

Carcinogenicity

Not available.

Reproductive toxicity

Not available.

Teratogenicity

Not available.

Specific target organ toxicity (single exposure)

Name	Category	Route of exposure	Target organs
	Category 3	-	Respiratory tract irritation
2-methylpropan-1-ol	Category 3	-	Respiratory tract irritation
	Category 3		Narcotic effects

Specific target organ toxicity (repeated exposure)

Name		Route of exposure	Target organs
ethylbenzene	Category 2	-	-

Aspiration hazard

Name	Result
ethylbenzene	ASPIRATION HAZARD - Category 1

Section 11. Toxicological information Information on the likely : Not available. routes of exposure Potential acute health effects Eye contact : Causes serious eye irritation. Inhalation : Harmful if inhaled. Skin contact : May be harmful in contact with skin. Causes skin irritation. Defatting to the skin. May cause an allergic skin reaction. : May be harmful if swallowed. Ingestion Symptoms related to the physical, chemical and toxicological characteristics : Adverse symptoms may include the following: Eye contact pain or irritation watering redness Inhalation : No specific data. Skin contact Adverse symptoms may include the following: irritation redness dryness cracking Ingestion : No specific data. Delayed and immediate effects and also chronic effects from short and long term exposure Short term exposure **Potential immediate** : Not available. effects **Potential delayed effects** : Not available. Long term exposure **Potential immediate** : Not available. effects **Potential delayed effects** : Not available. Potential chronic health effects General : Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/ or dermatitis. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels. Carcinogenicity ŝ, Suspected of causing cancer. Risk of cancer depends on duration and level of exposure. : No known significant effects or critical hazards. **Mutagenicity** : No known significant effects or critical hazards. **Reproductive toxicity**

Numerical measures of toxicity

Acute toxicity estimates

Date of issue 30 July 2021

Version 6

Section 11. Toxicological information

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases) (ppm)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
GMACOVER 522 BASE REDBROWN 9028	4398.8	2331	N/A	17.6	2.3
Epoxy Resin (700 <mw<=1100)< td=""><td>2500</td><td>2500</td><td>N/A</td><td>N/A</td><td>N/A</td></mw<=1100)<>	2500	2500	N/A	N/A	N/A
xylene isomers mixture	4300	1700	N/A	11	1.5
ethylbenzene	3500	17800	N/A	17.8	1.5
2-methylpropan-1-ol	2830	2460	N/A	24.6	N/A

Other information

Frolonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

Section 12. Ecological information

To	xic	ity

Product/ingredient name	Result	Species	Exposure
ethylbenzene	Acute EC50 1.8 mg/l Fresh water Chronic NOEC 1 mg/l Fresh water	Daphnia Daphnia - Ceriodaphnia dubia	48 hours -
2-methylpropan-1-ol	Acute EC50 1100 mg/l	Daphnia	48 hours

Persistence/degradability

Product/ingredient name	Test	Result		Dose		Inoculum
ethylbenzene	-	79 % - Rea	ıdily - 10 days	-		-
Product/ingredient name	Aquatic half-life		Photolysis		Biodeg	radability
xylene isomers mixture ethylbenzene	-		-		Readily Readily	

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
✓Jene isomers mixture	3.12	7.4 to 18.5	low
ethylbenzene	3.6	79.43	low
2-methylpropan-1-ol	1	-	low

Mobility in soil

Soil/water partition : No coefficient (Koc)

: Not available.

Other adverse effects

: No known significant effects or critical hazards.

Product name SIGMACOVER 522 BASE REDBROWN 9028

Section 13. Disposal considerations

Disposal methods

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and nonrecyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

	•			
	China	UN	IMDG	ΙΑΤΑ
UN number	UN1263	UN1263	UN1263	UN1263
UN proper shipping name	PAINT	PAINT	PAINT	PAINT
Transport hazard class(es)	3	3	3	3
Packing group	Ш	Ш	111	111
Environmental hazards	No.	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.	Not applicable.

Additional information

CN	: None identified.
UN	: None identified.
IMDG	: None identified.
ΙΑΤΑ	: None identified.

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

Product name SIGMACOVER 522 BASE REDBROWN 9028

Date of issue 30 July 2021

Version 6

Section 15. Regulatory information

China inventory (IECSC)	: All components are listed or exempted.
References	 Production Safety Law of the People's Republic of China Code of Occupational Disease Prevention of the People's Republic of China Environmental Protection Law of the People's Republic of China Fire Control Law of the People's Republic of China Regulations on the Control over Safety of Dangerous Chemicals Occupational exposure limits for hazardous agents in the workplace chemical hazardous agents (GBZ2.1) General rule for classification and hazard communication of chemicals (GB13690) Safety data sheet for chemical products - Content and order of sections (GB/ T16483) Guidance on the compilation of safety data sheet for chemical products (GB/ T17519) General rule for preparation of precautionary label for chemicals (GB15258) Safety rules for classification, precautionary labeling and precautionary statements of chemicals (GB30000.2-29)

History Date of issue/Date of revision Date of previous issue : 11/24/2019 Version : 6 EHS Key to abbreviations : ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail	Section 16. Other information		
revision 11/24/2019 Version : 6 EHS Key to abbreviations : ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Air Transport Association IMDG = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail	History		
Version: 6 EHSKey to abbreviations: ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Arit Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail		: 30 July 2021	
Key to abbreviationsEHS: ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail	Date of previous issue	: 11/24/2019	
Key to abbreviations: ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail	Version	: 6	
Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail		EHS	
	Key to abbreviations	Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods	

Indicates information that has changed from previously issued version.

Notice to reader

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.