SAFETY DATA SHEET

Safety Data Sheet according to GB/T 16483-2008 and GB/T 17519-2013



Date of issue/Date of revision 8 October 2021

Version 5.01

Section 1. Chem	ical product and company identification
Product code	: 00345920
Product name	: SIGMADUR 550 BASE CNC1044
Product name	: SIGMADUR 550 BASE CNC1044
Product type	: Liquid.
Relevant identified uses o	f the substance or mixture and uses advised against
Product use	: Professional applications, Used by spraying.
Use of the substance/ mixture	: Coating.
Uses advised against	: Not applicable.
Supplier's details	: PPG Coatings (Kunshan) Co., Ltd 53 Jinyang Road, Lujia Town, 215331 Kunshan City, Jiangsu Province, P.R. China Tel: 86 512 57678859 Fax: 86 512 57678857
Emergency telephone number (with hours of operation)	: 00 86 532 83889090

Section 2. Hazards identification

Classification of the substance or mixture according to GB 13690-2009 and GB 30000-2013

Emergency overview Liquid. Blue. Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Toxic to aquatic life. Harmful to aquatic life with long lasting effects. Prolonged or repeated contact may dry skin and cause irritation.

F exposed or concerned: Get medical advice or attention. IF INHALED: Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. If skin irritation occurs: Get medical advice or attention. If eye irritation persists: Get medical advice or attention.

See Section 12 for environmental precautions.

Section 2. Hazard	Is identification
Classification of the substance or mixture	 FLAMMABLE LIQUIDS - Category 3 ACUTE TOXICITY (dermal) - Category 5 ACUTE TOXICITY (inhalation) - Category 4 SKIN CORROSION/IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A CARCINOGENICITY - Category 2 AQUATIC HAZARD (ACUTE) - Category 2 AQUATIC HAZARD (LONG-TERM) - Category 3 Fercentage of the mixture consisting of ingredient(s) of unknown acute dermal toxicity: 4% Percentage of the mixture consisting of ingredient(s) of unknown acute inhalation toxicity: 36%
	Percentage of the mixture consisting of ingredient(s) of unknown hazards to the aquatic environment: 33%
GHS label elements	
Hazard pictograms	
Signal word	: Warning
Hazard statements	 Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Toxic to aquatic life. Harmful to aquatic life with long lasting effects.
Precautionary statements	
Prevention	: Øbtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use explosion-proof electrical, ventilating or lighting equipment. Use non-sparking tools. Take action to prevent static discharges. Keep container tightly closed. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Avoid breathing vapor. Wash thoroughly after handling.
Response	: F exposed or concerned: Get medical advice or attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. Wash with plenty of water. If skin irritation occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsin If eye irritation persists: Get medical advice or attention.
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Storage	: Store locked up. Store in a well-ventilated place. Keep cool.
Disposal	 Dispose of contents and container in accordance with all local, regional, national and international regulations.

Section 2. Hazards identification

Physical and chemical	: Flammable liquid and vapor.
hazards	

- **Health hazards**
- : Causes skin irritation. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Prolonged or repeated contact may dry skin and cause irritation.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact	: Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	: No specific data.

Delayed and immediate effects and also chronic effects from short and long term exposure

<u>Short term exposure</u>	
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
<u>Long term exposure</u>	
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Environmental hazards	: Toxic to aquatic life. Harmful to aquatic life with long lasting effects.
Other hazards which do not result in classification	: Prolonged or repeated contact may dry skin and cause irritation.

Section 3. Composition/information on ingredients

Substance/mixture

: Mixture

CAS number/other identifiers

Ingredient name	%	CAS number
parium sulfate	25 - <40	7727-43-7
xylene isomers mixture	10 - <25	1330-20-7
n-butyl acetate	1 - <10	123-86-4
ethylbenzene	1 - <10	100-41-4
Talc, not containing asbestiform fibers	1 - <10	14807-96-6
Solvent naphtha (petroleum), light aromatic	1 - <10	64742-95-6
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	0.1 - <1	41556-26-7
toluene	0.1 - <1	108-88-3

China Page: 3/14

Section 3. Composition/information on ingredients

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SUB codes represent substances without registered CAS Numbers.

Section 4. First aid measures

Description of necessary first aid measures		
Eye contact	 Remove contact lenses, irrigate copiously with clean, fresh water, holding the eyelids apart for at least 10 minutes and seek immediate medical advice. 	
Inhalation	 Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. 	
Skin contact	 Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners. 	
Ingestion	 If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting. 	

Most important symptoms/effects, acute and delayed

Potential acute health effe	<u>cts</u>
Eye contact	: Causes serious eye irritation.
Inhalation	: Harmful if inhaled.
Skin contact	: May be harmful in contact with skin. Causes skin irritation. Defatting to the skin.
Ingestion	: No known significant effects or critical hazards.
Over-exposure signs/symp	<u>otoms</u>
Eye contact	: Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	: No specific data.
Indication of immediate me	dical attention and special treatment needed, if necessary
Notes to physician	: In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours.
Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

Product code 00345920

Section 4. First aid measures

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is toxic to aquatic life. This material is harmful to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protec	tiv	re equipment and emergency procedures
For non-emergency personnel	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	:	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). Water polluting material. May be harmful to the environment if released in large quantities.

Methods and materials for containment and cleaning up

Section 6. Accidental release measures

Small spill	: Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
Large spill	: Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling	: Put on appropriate personal protective equipment (see Section 8). Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapor or mist. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.
Conditions for safe storage, including any incompatibilities	: Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

Section 8. Exposure controls/personal protection

Ingredient name		Exposure limits
parium sulfate		GBZ 2.1 (China, 8/2019).
		PC-TWA: 10 mg/m ³ , (as Ba) 8 hours.
xylene isomers mixture		GBZ 2.1 (China, 8/2019).
-		PC-STEL: 100 mg/m ³ 15 minutes.
		PC-TWA: 50 mg/m ³ 8 hours.
n-butyl acetate		GBZ 2.1 (China, 8/2019).
5		PC-STEL: 300 mg/m ³ 15 minutes.
		PC-TWA: 200 mg/m ³ 8 hours.
ethylbenzene		GBZ 2.1 (China, 8/2019).
		PC-STEL: 150 mg/m ³ 15 minutes.
		PC-TWA: 100 mg/m ³ 8 hours.
Talc, not containing asbestif	form fibers	GBZ 2.1 (China, 8/2019).
Tale, not containing aspesti	onn nbers	PC-TWA: 1 mg/m ³ 8 hours. Form:
		respirable dust
t - 1		PC-TWA: 3 mg/m ³ 8 hours. Form: total dus
toluene		GBZ 2.1 (China, 8/2019). Absorbed
		through skin.
		PC-STEL: 100 mg/m ³ 15 minutes.
		PC-TWA: 50 mg/m ³ 8 hours.
Recommended monitoring procedures	atmosphere or biological mo of the ventilation or other con protective equipment. Refer	edients with exposure limits, personal, workplace onitoring may be required to determine the effectivenes ntrol measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the
	atmosphere or biological mo of the ventilation or other co protective equipment. Refer standards. Reference to na	onitoring may be required to determine the effectivenes ntrol measures and/or the necessity to use respiratory rence should be made to appropriate monitoring
	 atmosphere or biological mo of the ventilation or other con protective equipment. Refer standards. Reference to na determination of hazardous Use only with adequate vent 	onitoring may be required to determine the effectivenes ntrol measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required.
procedures	 atmosphere or biological mo of the ventilation or other con protective equipment. Refer standards. Reference to na determination of hazardous Use only with adequate vent ventilation or other engineer 	onitoring may be required to determine the effectivenes introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required.
procedures Appropriate engineering	 atmosphere or biological mo of the ventilation or other con protective equipment. Refer standards. Reference to na determination of hazardous Use only with adequate vent ventilation or other engineer 	onitoring may be required to determine the effectivenes introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required.
procedures Appropriate engineering	 atmosphere or biological mo of the ventilation or other con protective equipment. Refer standards. Reference to na determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any record 	onitoring may be required to determine the effectivenes introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive
procedures Appropriate engineering controls	 atmosphere or biological mo of the ventilation or other col protective equipment. Refer standards. Reference to nat determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any reca also need to keep gas, vapo limits. Use explosion-proof 	onitoring may be required to determine the effectivenes introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment.
procedures Appropriate engineering	 atmosphere or biological mo of the ventilation or other con protective equipment. Refer standards. Reference to nat determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any rec also need to keep gas, vapo limits. Use explosion-proof v Emissions from ventilation or 	onitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. In work process equipment should be checked to ensur
procedures Appropriate engineering controls Environmental exposure	 atmosphere or biological moon of the ventilation or other comprotective equipment. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof vertilation or other ventilation or other ventilation or they comply with the require 	onitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. or work process equipment should be checked to ensur ments of environmental protection legislation. In some
procedures Appropriate engineering controls Environmental exposure	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refersion standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof ventilation or they comply with the require cases, fume scrubbers, filter 	onitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. A substances will also be required. A substances to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. A work process equipment should be checked to ensur
Appropriate engineering controls Environmental exposure controls	 atmosphere or biological mo of the ventilation or other col protective equipment. Refer standards. Reference to nat determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any reca also need to keep gas, vapo limits. Use explosion-proof Emissions from ventilation o they comply with the require cases, fume scrubbers, filter equipment will be necessary 	onitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. Evaluation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering contro or or dust concentrations below any lower explosive ventilation equipment. In work process equipment should be checked to ensur- ments of environmental protection legislation. In some or or engineering modifications to the process
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof vertilation or they comply with the require cases, fume scrubbers, filter equipment will be necessary 	onitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. In work process equipment should be checked to ensure ments of environmental protection legislation. In some rs or engineering modifications to the process of to reduce emissions to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineeric contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof ventilation or they comply with the require cases, fume scrubbers, filter equipment will be necessary Wash hands, forearms and the standards and the standards. 	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. In work process equipment should be checked to ensur ments of environmental protection legislation. In some or engineering modifications to the process or to reduce emissions to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineeric contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof ventilation or they comply with the require cases, fume scrubbers, filter equipment will be necessary Wash hands, forearms and reating, smoking and using the second statement of the second statement of the second statement will be necessary 	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering contro or or dust concentrations below any lower explosive ventilation equipment. In work process equipment should be checked to ensure ments of environmental protection legislation. In some or or engineering modifications to the process of to reduce emissions to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Referrence to national determination of hazardous Use only with adequate vent ventilation or other engineeric contaminants below any recalls and the ventilation or other engineeric contaminants below any recalls on need to keep gas, vapoon limits. Use explosion-proof versions from ventilation or they comply with the require cases, fume scrubbers, filter equipment will be necessary Wash hands, forearms and reating, smoking and using the Appropriate techniques should be appropriate techniques appropriate techniques	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering contro or or dust concentrations below any lower explosive ventilation equipment. or work process equipment should be checked to ensur- ments of environmental protection legislation. In some res or engineering modifications to the process of to reduce emissions to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineering contaminants below any recomplexity and the second structure of t	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering contro or or dust concentrations below any lower explosive ventilation equipment. or work process equipment should be checked to ensur- ments of environmental protection legislation. In some or or engineering modifications to the process of to reduce emissions to acceptable levels.
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineer contaminants below any recalso need to keep gas, vapo limits. Use explosion-proof ventilation or they comply with the require cases, fume scrubbers, filter equipment will be necessary Wash hands, forearms and reating, smoking and using the Appropriate techniques show Wash contaminated clothing safety showers are close to the standards. 	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. or work process equipment should be checked to ensur- ments of environmental protection legislation. In some of or reduce emissions to acceptable levels. face thoroughly after handling chemical products, befor- ne lavatory and at the end of the working period. uld be used to remove potentially contaminated clothing before reusing. Ensure that eyewash stations and
procedures Appropriate engineering controls Environmental exposure controls	 atmosphere or biological moon of the ventilation or other comprotective equipment. Refern standards. Reference to national determination of hazardous Use only with adequate vent ventilation or other engineering contaminants below any recomplexity and the second structure of t	ponitoring may be required to determine the effectiveness introl measures and/or the necessity to use respiratory rence should be made to appropriate monitoring tional guidance documents for methods for the substances will also be required. dilation. Use process enclosures, local exhaust ing controls to keep worker exposure to airborne ommended or statutory limits. The engineering control or or dust concentrations below any lower explosive ventilation equipment. or work process equipment should be checked to ensur- ments of environmental protection legislation. In some of or reduce emissions to acceptable levels. face thoroughly after handling chemical products, befor- ne lavatory and at the end of the working period. uld be used to remove potentially contaminated clothing before reusing. Ensure that eyewash stations and

Product code 00345920

Product name SIGMADUR 550 BASE CNC1044

Section 8. Exposure controls/personal protection

Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.
Gloves	: For prolonged or repeated handling, use the following type of gloves:
	Recommended: neoprene, natural rubber (latex), polyvinyl alcohol (PVA), Viton® May be used: butyl rubber Not recommended: nitrile rubber
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	 Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

Section 9. Physical and chemical properties

<u>Appearance</u>	
Physical state	: Liquid.
Color	: Blue.
Boiling point	: >37.78°C (>100°F)
Flash point	: Closed cup: 25°C (77°F)
Lower and upper explosive (flammable) limits	: Greatest known range: Lower: 1.4% Upper: 7.6% (n-butyl acetate)
Relative density	: 1.3
Solubility	: Insoluble in the following materials: cold water.
Viscosity	: Kinematic (40°C): >21 mm²/s

Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.

Product code 00345920

Product name SIGMADUR 550 BASE CNC1044

Section 10. Stability and reactivity

Conditions to avoid	:	When exposed to high temperatures may produce hazardous decomposition products.
Incompatible materials	:	Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	:	Depending on conditions, decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
▶arium sulfate	LD50 Dermal	Rat	>2000 mg/kg	-
	LD50 Oral	Rat	>5000 mg/kg	-
xylene isomers mixture	LD50 Dermal	Rabbit	1.7 g/kg	-
	LD50 Oral	Rat	4.3 g/kg	-
n-butyl acetate	LC50 Inhalation Vapor	Rat	>21.1 mg/l	4 hours
	LC50 Inhalation Vapor	Rat	2000 ppm	4 hours
	LD50 Dermal	Rabbit	>17600 mg/kg	-
	LD50 Oral	Rat	10.768 g/kg	-
ethylbenzene	LC50 Inhalation Vapor	Rat	17.8 mg/l	4 hours
	LD50 Dermal	Rabbit	17.8 g/kg	-
	LD50 Oral	Rat	3.5 g/kg	-
Solvent naphtha (petroleum), light aromatic	LD50 Dermal	Rabbit	3.48 g/kg	-
	LD50 Oral	Rat	8400 mg/kg	-
bis(1,2,2,6,6-pentamethyl- 4-piperidyl) sebacate	LD50 Oral	Rat	3.125 g/kg	-
toluene	LC50 Inhalation Vapor	Rat	49 g/m³	4 hours
	LD50 Dermal	Rabbit	8.39 g/kg	-
	LD50 Oral	Rat	5580 mg/kg	-

Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
xylene isomers mixture	Skin - Moderate irritant	Rabbit	-	24 hours 500 mg	-

Sensitization

Not available.

Mutagenicity

Not available.

Carcinogenicity

Not available.

Reproductive toxicity

Not available.

Teratogenicity

Section 11. Toxicological information

Not available.

Specific target organ toxicity (single exposure)

Name	Category	Route of exposure	Target organs
-butyl acetate	Category 3	-	Narcotic effects
Talc, not containing asbestiform fibers	Category 3	-	Respiratory tract irritation
Solvent naphtha (petroleum), light aromatic	Category 3	-	Respiratory tract irritation
	Category 3		Narcotic effects
toluene	Category 3	-	Narcotic effects

Specific target organ toxicity (repeated exposure)

Name	•••	Route of exposure	Target organs
ethylbenzene	Category 2	-	-
toluene	Category 2	-	-

Aspiration hazard

Name	Result
Solvent naphtha (petroleum), light aromatic	ASPIRATION HAZARD - Category 1 ASPIRATION HAZARD - Category 1 ASPIRATION HAZARD - Category 1

Information on the likely : Not available.

routes of exposure

Potential acute health effect	<u>s</u>	
Eye contact	1	Causes serious eye irritation.
Inhalation	1	Harmful if inhaled.
Skin contact	1	May be harmful in contact with skin. Causes skin irritation. Defatting to the skin.
Ingestion	:	No known significant effects or critical hazards.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact	: Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	: No specific data.

<u>Delayed and immediate effects and also chronic effects from short and long term exposure</u> <u>Short term exposure</u>

Section 11. Toxicological information

Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Long term exposure	
Potential immediate effects	: Not available.
Potential delayed effects	: Not available.
Potential chronic health eff	<u>ects</u>
General	 Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/ or dermatitis.
Carcinogenicity	: Suspected of causing cancer. Risk of cancer depends on duration and level of exposure.
Mutagenicity	: No known significant effects or critical hazards.
Reproductive toxicity	: No known significant effects or critical hazards.

Numerical measures of toxicity

Acute toxicity estimates

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases) (ppm)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
GMADUR 550 BASE CNC1044	15504.4	3956.3	N/A	27.9	3.6
barium sulfate	N/A	2500	N/A	N/A	N/A
xylene isomers mixture	4300	1700	N/A	11	1.5
n-butyl acetate	10768	N/A	N/A	N/A	N/A
ethylbenzene	3500	17800	N/A	17.8	1.5
Solvent naphtha (petroleum), light aromatic	8400	3480	N/A	N/A	N/A
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	3125	N/A	N/A	N/A	N/A
toluene	5580	8390	N/A	49	N/A

Other information

Frolonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

Section 12. Ecological information

Toxicity

Product/ingredient name	Result	Species	Exposure
-butyl acetate	Acute LC50 18 mg/l	Fish	96 hours
ethylbenzene	Acute EC50 1.8 mg/l Fresh water	Daphnia	48 hours
Solvent naphtha (petroleum),	Chronic NOEC 1 mg/l Fresh water	Daphnia - Ceriodaphnia dubia	-
light aromatic	Acute LC50 8.2 mg/l	Fish	96 hours

China Page: 11/14

Section 12. Ecological information

Persistence/degradability

Product/ingredient name	Test	Result		Dose		Inoculum
n-butyl acetate	TEPA and OECD 301D	83 % - Readily - 28 days		-		-
ethylbenzene	-	79 % - Rea	idily - 10 days	-		-
Product/ingredient name	Aquatic half-life		Photolysis		Biodeg	radability
xylene isomers mixture n-butyl acetate ethylbenzene toluene	- - -		- - -		Readily Readily Readily Readily	/ /

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
ylene isomers mixture	3.12	7.4 to 18.5	low
n-butyl acetate	2.3	-	low
ethylbenzene	3.6	79.43	low
toluene	2.73	8.32	low

Mobility in soil

Soil/water partition: Not available.coefficient (Koc)

Other adverse effects

: No known significant effects or critical hazards.

Section 13. Disposal considerations

Disposal methods The generation of waste should be avoided or minimized wherever possible. 2 Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and nonrecyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

	China	UN	IMDG	ΙΑΤΑ
UN number	UN1263	UN1263	UN1263	UN1263
UN proper shipping name	PAINT	PAINT	PAINT	PAINT
Transport hazard class(es)	3	3	3	3
Packing group	111	111	111	111
Environmental hazards	No.	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.	Not applicable.

Additional information

CN	: None identified.
UN	: None identified.
IMDG	: None identified.
ΙΑΤΑ	: None identified.

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

Section 15. Regulatory information

China inventory (IECSC)	: All components are listed or exempted.
References	 Production Safety Law of the People's Republic of China Code of Occupational Disease Prevention of the People's Republic of China Environmental Protection Law of the People's Republic of China Fire Control Law of the People's Republic of China Regulations on the Control over Safety of Dangerous Chemicals Occupational exposure limits for hazardous agents in the workplace chemical hazardous agents (GBZ2.1) General rule for classification and hazard communication of chemicals (GB13690) Safety data sheet for chemical products - Content and order of sections (GB/ T16483) Guidance on the compilation of safety data sheet for chemical products (GB/ T17519) General rule for preparation of precautionary label for chemicals (GB15258) Safety rules for classification, precautionary labeling and precautionary statements of chemicals (GB30000.2-29)

Section 16. Other information

<u>History</u>	
Date of issue/Date of revision	: 8 October 2021
Date of previous issue	: 5/7/2020
Version	: 5.01
	EHS
Key to abbreviations	: ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway
	ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor
	GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association
	IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient
	MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations

✓ Indicates information that has changed from previously issued version.

Notice to reader

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.