# **SAFETY DATA SHEET**

Safety Data Sheet according to GB/T 16483-2008 and GB/T 17519-2013



Date of issue/Date of revision 24 July 2022

Version 1

Section 1. Chemical product and company identification		
Product code	: 00466179	
Product name	: SIGMADUR 550 BASE 5B8/4	
Product name	: SIGMADUR 550 BASE 5B8/4	
Product type	: Liquid.	
Relevant identified uses o	f the substance or mixture and uses advised against	
Product use	: Professional applications, Used by spraying.	
Use of the substance/ mixture	: Coating.	
Uses advised against	: Not applicable.	
Supplier's details	: PPG Coatings (Kunshan) Co., Ltd 53 Jinyang Road, Lujia Town, 215331 Kunshan City, Jiangsu Province, P.R. China Tel: 86 512 57678859 Fax: 86 512 57678857	
Emergency telephone number (with hours of operation)	: 00 86 532 83889090	

## Section 2. Hazards identification

Classification of the substance or mixture according to GB 13690-2009 and GB 30000-2013

#### Emergency overview Liquid. Characteristic. Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Toxic to aquatic life. Harmful to aquatic life with long lasting effects. Prolonged or repeated contact may dry skin and cause irritation.

IF exposed or concerned: Get medical advice or attention. IF INHALED: Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. If skin irritation or rash occurs: Get medical advice or attention. If eye irritation persists: Get medical advice or attention.

### See Section 12 for environmental precautions.

Section 2. Hazard	
Classification of the substance or mixture	<ul> <li>FLAMMABLE LIQUIDS - Category 3         ACUTE TOXICITY (dermal) - Category 5         ACUTE TOXICITY (inhalation) - Category 4          </li> <li>SKIN CORROSION/IRRITATION - Category 2         </li> <li>SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A         </li> <li>SKIN SENSITIZATION - Category 1         CARCINOGENICITY - Category 2          </li> <li>AQUATIC HAZARD (ACUTE) - Category 2         </li> <li>AQUATIC HAZARD (LONG-TERM) - Category 3         </li> <li>Percentage of the mixture consisting of ingredient(s) of unknown acute dermal toxicity: 34.6%         Percentage of the mixture consisting of ingredient(s) of unknown acute inhalation toxicity: 34.6%         </li> <li>Percentage of the mixture consisting of ingredient(s) of unknown hazards to the aquatic environment: 32.9%</li> </ul>
GHS label elements	
Hazard pictograms	
Signal word	: Warning
Hazard statements	<ul> <li>Flammable liquid and vapor. May be harmful in contact with skin. Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Toxic to aquatic life. Harmful to aquatic life with long lasting effects.</li> </ul>
Precautionary statements	
Prevention	: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use explosion-proof electrical, ventilating or lighting equipment. Use non-sparking tools. Take action to prevent static discharges. Keep container tightly closed. Use only outdoors or in a well-ventilated area. Avoid release to the environment. Avoid breathing vapor. Wash thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace.
Response	: IF exposed or concerned: Get medical advice or attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor if you feel unwell. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. Wash with plenty of water. If skin irritation or rash occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice or attention.
Suitable extinguishing media	: Use dry chemical, CO <sub>2</sub> , water spray (fog) or foam.
Storage	: Store locked up. Store in a well-ventilated place. Keep cool.

Date of issue 24 July 2022

## Section 2. Hazards identification

Disposal	:	Dispose of contents and container in accordance with all local, regional, national and international regulations.
Physical and chemical hazards	:	Flammable liquid and vapor.
Health hazards	:	Causes skin irritation. May cause an allergic skin reaction. Causes serious eye irritation. Harmful if inhaled. Suspected of causing cancer. Prolonged or repeated contact may dry skin and cause irritation.
Symptoms related to the phy	sic	al, chemical and toxicological characteristics
Eye contact	:	Adverse symptoms may include the following: pain or irritation watering redness
Inhalation	:	No specific data.
Skin contact	:	Adverse symptoms may include the following: irritation redness dryness cracking
Ingestion	:	No specific data.
Delayed and immediate effec	ts	and also chronic effects from short and long term exposure
Short term exposure		
Potential immediate effects	:	Not available.
Potential delayed effects	:	Not available.
Long term exposure		
Potential immediate effects	:	Not available.
Potential delayed effects	:	Not available.
Environmental hazards	:	Toxic to aquatic life. Harmful to aquatic life with long lasting effects.
Other hazards which do not result in classification	:	Prolonged or repeated contact may dry skin and cause irritation.

# Section 3. Composition/information on ingredients

Not applicable.

Substance/mixture	: Mixture
-------------------	-----------

CAS number/other identifiers	
CAS number	÷

Version 1

Product name SIGMADUR 550 BASE 5B8/4

## Section 3. Composition/information on ingredients

Ingredient name	%	CAS number
xylene isomers mixture	10 - <25	1330-20-7
n-butyl acetate	1 - <10	123-86-4
Talc , not containing asbestiform fibres	1 - <10	14807-96-6
ethylbenzene	1 - <10	100-41-4
Octadecanamide, N,N'-1,6-hexanediylbis[12-hydroxy-	1 - <10	55349-01-4
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	0.1 - <1	41556-26-7

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SUB codes represent substances without registered CAS Numbers.

## Section 4. First aid measures

#### **Description of necessary first aid measures** Eye contact : Remove contact lenses, irrigate copiously with clean, fresh water, holding the eyelids apart for at least 10 minutes and seek immediate medical advice. Inhalation Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is 2 irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. **Skin contact** Remove contaminated clothing and shoes. Wash skin thoroughly with soap and τ. water or use recognized skin cleanser. Do NOT use solvents or thinners. Ingestion : If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.

#### Most important symptoms/effects, acute and delayed

wost important symptoms/er	to, acute and delayed	
Potential acute health effect		
Eye contact	Causes serious eye irritation.	
Inhalation	Harmful if inhaled.	
Skin contact	May be harmful in contact with skin. Causes skin irritation. Defatting to the skin. May cause an allergic skin reaction.	
Ingestion	No known significant effects or critical hazards.	
Over-exposure signs/symptoms		
Eye contact	Adverse symptoms may include the following: pain or irritation watering redness	
Inhalation	No specific data.	
Skin contact	Adverse symptoms may include the following: irritation redness dryness cracking	
Ingestion	No specific data.	

#### Indication of immediate medical attention and special treatment needed, if necessary

Product code       00466179       Date of issue       24 July 2022       Version 1         Product name       SIGMADUR 550 BASE 5B8/4       Date of issue       24 July 2022       Version 1				
Section 4. First ai	d measures			
Notes to physician Specific treatments	<ul> <li>In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours.</li> <li>No specific treatment.</li> </ul>			
Protection of first-aiders	No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.			

See toxicological information (Section 11)

## Section 5. Fire-fighting measures

Extinguishing media	
Suitable extinguishing media	: Use dry chemical, CO <sub>2</sub> , water spray (fog) or foam.
Unsuitable extinguishing media	: Do not use water jet.
Specific hazards arising from the chemical	: Flammable liquid and vapor. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. This material is toxic to aquatic life. This material is harmful to aquatic life with long lasting effects. Fire water contaminated with this material must be contained and prevented from being discharged to any waterway, sewer or drain.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

## Section 6. Accidental release measures

Personal precautions, protecti	ve equipment and emergency procedures		
For non-emergency personnel	No action shall be taken involving any personal risk or withou Evacuate surrounding areas. Keep unnecessary and unprote entering. Do not touch or walk through spilled material. Shu No flares, smoking or flames in hazard area. Avoid breathing Provide adequate ventilation. Wear appropriate respirator w inadequate. Put on appropriate personal protective equipme	ected perso t off all ignit g vapor or n hen ventilat	nnel from ion sources. nist.
For emergency responders	If specialized clothing is required to deal with the spillage, tak information in Section 8 on suitable and unsuitable materials information in "For non-emergency personnel".		
		China	Page: 5/13

## Section 6. Accidental release measures

<b>Environmental precautions</b>	1	Avoid dispersal of spilled material and runoff and contact with soil, waterways,	
Ē		drains and sewers. Inform the relevant authorities if the product has caused	
		environmental pollution (sewers, waterways, soil or air). Water polluting material.	
		May be harmful to the environment if released in large quantities.	

Methods and materials for	cont	ainment and cleaning up
Small spill	:	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
Large spill	:	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

# Section 7. Handling and storage

Precautions for safe handling	:	Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapor or mist. Avoid release to the environment. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use only non-sparking tools. Take precautionary measures against electrostatic discharges. Empty containers retain product residue and can be hazardous. Do not reuse container.
Conditions for safe storage, including any incompatibilities	:	Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

## Section 8. Exposure controls/personal protection

### **Control parameters**

#### **Occupational exposure limits**

xylene isomers mixture       Giz 2.1 (China, 8/2019), CYVenel,         n-butyl acetate       CoTEL: 100 mg/m³ 15 minutes.         Talc , not containing asbestform fibres       Giz 2.1 (China, 8/2019), PC-STEL: 300 mg/m³ 16 minutes.         PC-TWA: 200 mg/m³ 8 hours.       Giz 2.1 (China, 8/2019), PC-STEL: 300 mg/m³ 16 minutes.         PC-TWA: 200 mg/m³ 8 hours.       Form:         ethylbenzene       Giz 2.1 (China, 8/2019), PC-STEL: 300 mg/m³ 16 minutes.         PC-TWA: 3 mg/m³ 8 hours. Form: total dust       Giz 2.1 (China, 8/2019), PC-STEL: 150 mg/m³ 16 minutes.         procedures       Giz 2.1 (China, 8/2019), PC-STEL: 150 mg/m³ 16 minutes.         procedures       FO-TWA: 100 mg/m³ 16 minutes.         procedures       Giz 2.1 (China, 8/2019), PC-STEL: 150 mg/m³ 16 minutes.         procedures       Giz 2.1 (China, 8/2019), PC-STEL: 100 mg/m³ 16 minutes.         procedures       Giz 2.1 (China, 8/2019), PC-STEL: 100 mg/m³ 16 minutes.         procedures       Giz 2.1 (China, 8/2019), PC-STEL: 100 mg/m³ 16 minutes.         procedures       Git 2.1 (China, 8/2019), PC-STEL: 100 mg/m³ 16 minutes.         procedures       If this product contains ingredients with scopare limits. Beersont, workplace atmosphere or biological monitoring may be required.         Appropriate ongineoring       I Use only with adequate ventilation.       Use process encloserse, to eressite to use propriate monitoring alston or other process equipment.	Ingredient name		Exposure limits
Talc , not containing asbestiform fibres       PC-STEL: 300 mg/m <sup>3</sup> 8 hours. PC-TWA: 10 mg/m <sup>3</sup> 8 hours. GBZ 2.1 (China, 8/2019). PC-TWA: 10 mg/m <sup>3</sup> 8 hours. Form: respirable dust PC-TWA: 3 mg/m <sup>3</sup> 8 hours. Form: total dust GBZ 2.1 (China, 8/2019). PC-STEL: 150 mg/m <sup>3</sup> 15 minutes. PC-TWA: 100 mg/m <sup>3</sup> 8 hours. PC-TWA: 100 mg/m <sup>3</sup> 10 mg	xylene isomers mixture		PC-STEL: 100 mg/m <sup>3</sup> 15 minutes. PC-TWA: 50 mg/m <sup>3</sup> 8 hours.
Tale , not containing asbestiform fibres       GB2 2.1 (China, 3/2019). PC-TWA: 1 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-TWA: 3 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: total dust GB2 2.1 (China, 3/2019). PC-STEL: 150 mg/m³ 8 hours. Form: the equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination or ther engineering controls to keep worker exposure to airborne controls or total dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Environmental exposure controls         Environmental exposure controls       : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         ndividual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminat	n-butyl acetate		PC-STEL: 300 mg/m <sup>3</sup> 15 minutes.
ethylbenzene       GBZ 2.1 (China, 6/2019). PC-STEL: 150 mg/m³ 15 minutes. PC-TWA: 100 mg/m³ 8 hours.         Recommended monitoring procedures       : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the venillation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.         Appropriate engineering controls       : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.         Environmental exposure controls       : Emissions from ventilation or work process equipment should be checked to ensure ecases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         ndividual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the working period. Appropriate techniques should be used to remove pote			<b>GBZ 2.1 (China, 8/2019).</b> PC-TWA: 1 mg/m <sup>3</sup> 8 hours. Form: respirable dust
procedures       atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.         Appropriate engineering controls       : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any locar explosive limits. Use explosion-proof ventilation equipment.         Environmental exposure       : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         ndividual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the working exercise. Wash contaminates beging should not be allowed out of the working exercise. Wash contaminates beging shoul not be allowed out of the working. We wash stations and safety showers are close to the workstation location.         Eye protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times	ethylbenzene		GBZ 2.1 (China, 8/2019). PC-STEL: 150 mg/m <sup>3</sup> 15 minutes.
controlsventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.ndividual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection Hand protection: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.Gloves: butyl rubber		atmosphere or biological of the ventilation or other protective equipment. Re standards. Reference to	monitoring may be required to determine the effectiveness control measures and/or the necessity to use respiratory eference should be made to appropriate monitoring national guidance documents for methods for the
controlsthey comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.individual protection measures:Hygiene measures:Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection:Skin protection:Hand protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.Gloves:butyl rubber		ventilation or other engine contaminants below any also need to keep gas, va	eering controls to keep worker exposure to airborne recommended or statutory limits. The engineering controls apor or dust concentrations below any lower explosive
Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye protection: Chemical splash goggles.Skin protection: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.Gloves: butyl rubber		they comply with the requ cases, fume scrubbers, f	irements of environmental protection legislation. In some ilters or engineering modifications to the process
<ul> <li>eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.</li> <li>Eye protection</li> <li>Chemical splash goggles.</li> <li>Skin protection</li> <li>Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.</li> <li>Gloves</li> </ul>	ndividual protection measure	<u>es</u>	
Skin protection         Hand protection         : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.         Gloves       : butyl rubber	Hygiene measures	eating, smoking and usin Appropriate techniques s Contaminated work cloth contaminated clothing be	g the lavatory and at the end of the working period. hould be used to remove potentially contaminated clothing. ing should not be allowed out of the workplace. Wash fore reusing. Ensure that eyewash stations and safety
<ul> <li>Hand protection</li> <li>Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.</li> <li>Gloves</li> </ul>	Eye protection	: Chemical splash goggles	
<ul> <li>be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.</li> <li>Gloves : butyl rubber</li> </ul>			
	Hand protection	be worn at all times wher this is necessary. Consid check during use that the should be noted that the different for different glow several substances, the	handling chemical products if a risk assessment indicates dering the parameters specified by the glove manufacturer, gloves are still retaining their protective properties. It time to breakthrough for any glove material may be e manufacturers. In the case of mixtures, consisting of
China Page: 7/13	Gloves	: butyl rubber	
			China Page: 7/13

## Section 8. Exposure controls/personal protection

•	• •
Body protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static discharges, clothing should include anti-static overalls, boots and gloves.
Other skin protection	<ul> <li>Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.</li> </ul>
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

## Section 9. Physical and chemical properties

<u>Appearance</u>	
Physical state	: Liquid.
Odor	: Characteristic.
Boiling point	: >37.78°C (>100°F)
Flash point	: Closed cup: 25°C (77°F)
Lower and upper explosive (flammable) limits	: Greatest known range: Lower: 1.4% Upper: 7.6% (n-butyl acetate)
Relative density	: 1.36
Solubility	: Insoluble in the following materials: cold water.
Viscosity	: Kinematic (40°C): >21 mm²/s

# Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	: Depending on conditions, decomposition products may include the following materials: carbon oxides nitrogen oxides sulfur oxides metal oxide/oxides

## Section 11. Toxicological information

### Information on toxicological effects

### Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
xylene isomers mixture	LD50 Dermal	Rabbit	1.7 g/kg	-
	LD50 Oral	Rat	4.3 g/kg	-
n-butyl acetate	LC50 Inhalation Vapor	Rat	>21.1 mg/l	4 hours
	LC50 Inhalation Vapor	Rat	2000 ppm	4 hours
	LD50 Dermal	Rabbit	>17600 mg/kg	-
	LD50 Oral	Rat	10.768 g/kg	-
ethylbenzene	LC50 Inhalation Vapor	Rat	17.8 mg/l	4 hours
-	LD50 Dermal	Rabbit	17.8 g/kg	-
	LD50 Oral	Rat	3.5 g/kg	-
bis(1,2,2,6,6-pentamethyl- 4-piperidyl) sebacate	LD50 Oral	Rat	3.125 g/kg	-

#### Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
xylene isomers mixture	Skin - Moderate irritant	Rabbit	-	24 hours 500 mg	-

#### **Sensitization**

Not available.

#### **Mutagenicity**

Not available.

#### Carcinogenicity

Not available.

#### Reproductive toxicity

Not available.

#### Teratogenicity

Not available.

#### Specific target organ toxicity (single exposure)

Name		Route of exposure	Target organs
n-butyl acetate Talc , not containing asbestiform fibres	Category 3 Category 3	-	Narcotic effects Respiratory tract irritation

#### Specific target organ toxicity (repeated exposure)

Name	•••	Route of exposure	Target organs
ethylbenzene	Category 2	-	-

### Aspiration hazard

Name	Result
ethylbenzene	ASPIRATION HAZARD - Category 1

China Page: 9/13	China	Page:	9/13
------------------	-------	-------	------

#### Section 11. Toxicological information Information on the likely : Not available. routes of exposure Potential acute health effects Eye contact : Causes serious eye irritation. Inhalation : Harmful if inhaled. : May be harmful in contact with skin. Causes skin irritation. Defatting to the skin. **Skin contact** May cause an allergic skin reaction. : No known significant effects or critical hazards. Ingestion Symptoms related to the physical, chemical and toxicological characteristics : Adverse symptoms may include the following: Eye contact pain or irritation watering redness Inhalation : No specific data. **Skin contact** Adverse symptoms may include the following: irritation redness

#### cracking Ingestion : No specific data.

dryness

#### Delayed and immediate effects and also chronic effects from short and long term exposure Short term exposure **Potential immediate** : Not available. effects **Potential delayed effects** : Not available. Long term exposure **Potential immediate** : Not available. effects **Potential delayed effects** : Not available. Potential chronic health effects General : Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/ or dermatitis. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels. Carcinogenicity Suspected of causing cancer. Risk of cancer depends on duration and level of ÷ exposure. **Mutagenicity** : No known significant effects or critical hazards. : No known significant effects or critical hazards. **Reproductive toxicity**

#### Numerical measures of toxicity Acute toxicity estimates

Version 1

## Section 11. Toxicological information

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases) (ppm)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
SIGMADUR 550 BASE 5B8/4	11095.5 4300	4977.6 1700	N/A N/A	29	3.7 1.5
xylene isomers mixture n-butyl acetate	10768	N/A	N/A N/A	N/A	N/A
ethylbenzene bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	3500 3125	17800 N/A	N/A N/A	17.8 N/A	1.5 N/A

#### Other information

Prolonged or repeated contact may dry skin and cause irritation. Sanding and grinding dusts may be harmful if inhaled. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Avoid contact with skin and clothing.

## Section 12. Ecological information

т	ovi	417
4	UX	LY

Product/ingredient name	Result	Species	Exposure
n-butyl acetate	Acute LC50 18 mg/l	Fish	96 hours
ethylbenzene	Acute EC50 1.8 mg/l Fresh water	Daphnia	48 hours
	Chronic NOEC 1 mg/l Fresh water	Daphnia - Ceriodaphnia dubia	-

#### Persistence/degradability

Product/ingredient name	Test	Result		Dose		Inoculum
n-butyl acetate	TEPA and OECD 301D	83 % - Rea	adily - 28 days	-		-
ethylbenzene	-	79 % - Rea	adily - 10 days	-		-
Product/ingredient name	Aquatic half-life		Photolysis		Biodeg	<b>Jradability</b>
xylene isomers mixture n-butyl acetate ethylbenzene	- - -		- - -		Readily Readily Readily	/

#### **Bioaccumulative potential**

Product/ingredient name	LogPow	BCF	Potential
xylene isomers mixture	3.12	7.4 to 18.5	low
n-butyl acetate	2.3	-	low
ethylbenzene	3.6	79.43	low

#### Mobility in soil

Soil/water partition coefficient (Koc)

: Not available.

#### **Other adverse effects**

: No known significant effects or critical hazards.

Product code 00466179 Product name SIGMADUR 550 BASE 5B8/4

## Section 12. Ecological information

## Section 13. Disposal considerations

**Disposal methods** The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapor from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

### Section 14. Transport information

•				
	China	UN	IMDG	IATA
UN number	UN1263	UN1263	UN1263	UN1263
UN proper shipping name	PAINT	PAINT	PAINT	PAINT
Transport hazard class(es)	3	3	3	3
Packing group	Ш	111	III	Ш
Environmental hazards	No.	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.	Not applicable.

#### **Additional information**

: None identified. CN UN : None identified. IMDG : None identified. ΙΑΤΑ : None identified.

Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

## Section 15. Regulatory information

China inventory (IECSC)	: All components are listed or exempted.
References	<ul> <li>Production Safety Law of the People's Republic of China Code of Occupational Disease Prevention of the People's Republic of China Environmental Protection Law of the People's Republic of China Fire Control Law of the People's Republic of China Regulations on the Control over Safety of Dangerous Chemicals Occupational exposure limits for hazardous agents in the workplace chemical hazardous agents (GBZ2.1)</li> <li>General rule for classification and hazard communication of chemicals (GB13690) Safety data sheet for chemical products - Content and order of sections (GB/ T16483)</li> <li>Guidance on the compilation of safety data sheet for chemical products (GB/ T17519)</li> <li>General rule for preparation of precautionary label for chemicals (GB15258) Safety rules for classification, precautionary labeling and precautionary statements of chemicals (GB30000.2-29)</li> </ul>

#### Section 16. Other information **History** Date of issue/Date of : 24 July 2022 revision Date of previous issue : No previous validation Version : 1 EHS Key to abbreviations ADN = European Provisions concerning the International Carriage of Dangerous 2 Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate **BCF** = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IMDG = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations

Indicates information that has changed from previously issued version.

#### Notice to reader

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.