# **SAFETY DATA SHEET**



#### Conforms to Official Mexican Standard NOM-018-STPS-2015

Date of revision 12 June 2024

Version 8

Date of issue 12 June 2024

# SECTION 1: Identification of the substance/mixture and of the company/undertaking

Product name	: PSX 700 SILVERY MOON
Product code	: LR20150201/05
Other means of identification	: Not applicable.
Product type	: Liquid.
Relevant identified uses of	the substance or mixture and uses advised against
Product use	: Industrial applications.
Use of the substance/ mixture	: Coating.
Uses advised against	Not applicable.
Manufacturer	: PPG Industries, Inc. One PPG Place Pittsburgh, PA 15272
Emergency telephone number	<ul> <li>#12) 434-4515 (U.S.)</li> <li>(514) 645-1320 (Canada)</li> <li>SETIQ Interior de la República: 800-00-214-00 (México)</li> <li>SETIQ Ciudad de México: (55) 5559-1588 (México)</li> </ul>
<b>Technical Phone Number</b>	: 888-977-4762

# **SECTION 2: Hazards identification**

Classification of the substance or mixture	: SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 1A
	TOXIC TO REPRODUCTION - Category 2
	Percentage of the mixture consisting of ingredient(s) of unknown acute toxicity: 72.5% (oral), 74% (dermal), 68.5% (inhalation)
GHS label elements	
Hazard pictograms	
	$\mathbf{v}$ $\mathbf{v}$
Signal word	: Danger
Hazard statements	: 🗗317 - May cause an allergic skin reaction.
	H350 - May cause cancer.
	H361 - Suspected of damaging fertility or the unborn child.
Precautionary statements	

#### Product name PSX 700 SILVERY MOON

#### **SECTION 2: Hazards identification**

Prevention	:	<ul> <li>P201 - Obtain special instructions before use.</li> <li>P202 - Do not handle until all safety precautions have been read and understood.</li> <li>P280 - Wear protective gloves, protective clothing and eye or face protection.</li> <li>P261 - Avoid breathing vapor.</li> <li>P272 - Contaminated work clothing should not be allowed out of the workplace.</li> </ul>
Response	:	<ul> <li>P308 + P313 - IF exposed or concerned: Get medical advice or attention.</li> <li>P362 + P364 - Take off contaminated clothing and wash it before reuse.</li> <li>P302 + P352 - IF ON SKIN: Wash with plenty of water.</li> <li>P333 + P313 - If skin irritation or rash occurs: Get medical advice or attention.</li> </ul>
Storage	1	P405 - Store locked up.
Disposal	:	P501 - Dispose of contents and container in accordance with all local, regional, national and international regulations.
Other hazards which do not result in classification	:	Sanding and grinding dusts may be harmful if inhaled. This product contains crystalline silica which can cause lung cancer or silicosis. The risk of cancer depends on the duration and level of exposure to dust from sanding surfaces or mist from spray applications. Trimethoxysilanes are capable of forming methanol if hydrolyzed or ingested. If swallowed, methanol may be harmful or fatal or cause blindness. Emits toxic fumes when heated.
See toxicological information	า (ร	Section 11)

# **SECTION 3: Composition/information on ingredients**

Substance/mixture	: Mixture
Product name	: PSX 700 SILVERY MOON
Other means of identification	: Not applicable.

Ingredient name	%	CAS number
4.4'-Isopropylidenedicyclohexanol, oligomeric reaction products with 1-chloro-2,3-epoxypropane	≥20 - ≤50	30583-72-3
titanium dioxide	≥20 - ≤50	13463-67-7
Wollastonite	≥5.0 - ≤10	13983-17-0
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	≥1.0 - ≤5.0	41556-26-7
methyl 1,2,2,6,6-pentamethyl-4-piperidyl sebacate	<1.0	82919-37-7
crystalline silica, respirable powder (<10 microns)	<1.0	14808-60-7

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

#### **SECTION 4: First aid measures**

# Description of necessary first aid measures Eye contact : Remove contact lenses, irrigate copiously with clean, fresh water, holding the eyelids apart for at least 10 minutes and seek immediate medical advice. Inhalation : Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. Skin contact : Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.

Product name PSX 700 SILVERY MOON

#### **SECTION 4: First aid measures**

```
Ingestion
```

: If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.

#### Most important symptoms/effects, acute and delayed

#### Potential acute health effects

Eye contact	: No known significant effects or critical hazards.
Inhalation	: No known significant effects or critical hazards.
Skin contact	: May cause an allergic skin reaction.
Ingestion	: No known significant effects or critical hazards.
Over-exposure sig	ns/symptoms

See toxicological information (Section 11)

#### Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician Specific treatments	-	In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. No specific treatment.
Protection of first-aiders	i r F	No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

# **SECTION 5: Firefighting measures**

Extinguishing media	
Suitable extinguishing media	: Use an extinguishing agent suitable for the surrounding fire.
Unsuitable extinguishing media	: None known.
Specific hazards arising from the chemical	: In a fire or if heated, a pressure increase will occur and the container may burst.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides halogenated compounds metal oxide/oxides
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Version 8

Product name PSX 700 SILVERY MOON

## **SECTION 6: Accidental release measures**

Personal precautions, protect	<u>tiv</u>	e equipment and emergency procedures
For non-emergency personnel	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Avoid breathing vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	•	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and materials for co	ont	ainment and cleaning up
Small spill	:	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
Large spill	:	Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

# **SECTION 7: Handling and storage**

Precautions for safe handling	
Protective measures	: Fut on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Avoid exposure during pregnancy. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapor or mist. If during normal use the material presents a respiratory hazard, use only with adequate ventilation or wear appropriate respirator. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse container.
Special precautions	: Vapors may accumulate in low or confined areas or travel a considerable distance to a source of ignition and flash back. Vapors are heavier than air and may spread along floors. If this material is part of a multiple component system, read the Safety Data Sheet(s) for the other component or components before blending as the resulting mixture may have the hazards of all of its parts.
Advice on general occupational hygiene	: Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Product name PSX 700 SILVERY MOON

# **SECTION 7: Handling and storage**

Conditions for safe storage,	: Store between the following temperatures: 0 to 35°C (32 to 95°F). Store in
including any	accordance with local regulations. Store in original container protected from direct
incompatibilities	sunlight in a dry, cool and well-ventilated area, away from incompatible materials
	(see Section 10) and food and drink. Store locked up. Keep container tightly closed
	and sealed until ready for use. Containers that have been opened must be carefully
	resealed and kept upright to prevent leakage. Do not store in unlabeled containers.
	Use appropriate containment to avoid environmental contamination.

# **SECTION 8: Exposure controls/personal protection**

#### Control parameters

#### **Occupational exposure limits**

Ingredient name	Exposure limits
4-Isopropylidenedicyclohexanol, oligomeric reaction products with 1-chloro-2,3-epoxypropane	None.
titanium dioxide	NOM-010-STPS-2014 (Mexico, 4/2016).
	TWA: 10 mg/m <sup>3</sup> 8 hours.
Wollastonite	ACGIH TLV (United States, 7/2023).
	TWA: 1 mg/m <sup>3</sup> 8 hours. Form: Inhalable
	fraction
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	None.
methyl 1,2,2,6,6-pentamethyl-4-piperidyl sebacate	None.
crystalline silica, respirable powder (<10 microns)	NOM-010-STPS-2014 (Mexico, 4/2016).
	TWA: 0.025 mg/m <sup>3</sup> 8 hours. Form:
	Respirable

#### Key to abbreviations

C = Ceiling Limit IPEL = Internal Permissible Exposure Limit STEL = Short term exposure limit

TLV = Threshold Limit Value TWA = Time Weighted Average

#### Consult local authorities for acceptable exposure limits.

Recommended monitoring procedures	: Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.
Appropriate engineering controls	: If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.
Environmental exposure controls	: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.
Individual protection measure	S
	Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Eye/face protection	: Safety glasses with side shields.
Skin protection	

Version 8

Product name PSX 700 SILVERY MOON

# SECTION 8: Exposure controls/personal protection

Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.
Gloves	: butyl rubber
Body protection	<ul> <li>Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.</li> </ul>
Other skin protection	<ul> <li>Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.</li> </ul>
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

# **SECTION 9: Physical and chemical properties**

				Mexico	Page: 6/12
Viscosity	:	Kinematic (40°C (1	04°F)): >21 mm²/s (>21 cSt)		
Partition coefficient: n- octanol/water	1	Not applicable.			
Solubility in water	;	Not available.			
Solubility(ies)	-	cold water	Not soluble		
Colubility(ico)		Media	Result		
Density(Ibs / gal)	3	11.52			
Relative density	1	1.38			
Vapor density	;	Not available.			
Vapor pressure	:	Not available.			
(flammable) limits Evaporation rate	:	Not available.			
Lower and upper explosive	1	Not available.			
Flammability		Not available.			
Decomposition temperature		Not available.			
Auto-ignition temperature		Not available.			
Flash point		Closed cup: 97°C (			
Boiling point		>37.78°C (>100°F)			
Melting point		Not available.			
Molecular weight pH	-	Not applicable.			
Odor threshold	ł	Not available.			
Odor	1	Characteristic.			
Color	1	Gray.			
Physical state		Liquid.			
<u>Appearance</u>					

Product code LR20150201/05		Date of issue 12 June 2024	Version 8		
Product name PSX 700 S	ILVERY MOON				
SECTION 9: Physical and chemical properties					
Volatility	: 0% (v/v), 0.277% (w/w)				
% Solid. (w/w)	: 99.723				
<b>SECTION 10: Stal</b>	bility and reactivity	1			
Reactivity	: No specific test data relate	ed to reactivity available for this produc	ct or its ingredients.		
Chemical stability	: The product is stable.				
Possibility of hazardous reactions	: Under normal conditions of	of storage and use, hazardous reactior	ns will not occur.		
Conditions to avoid	products.	nperatures may produce hazardous de res listed in sections 7 and 8.	ecomposition		
Incompatible materials	: Keep away from the follow oxidizing agents, strong a	ving materials to prevent strong exothe kalis, strong acids.	ermic reactions:		
Hazardous decomposition products		decomposition products may include t kides halogenated compounds metal			

# **SECTION 11: Toxicological information**

#### Information on toxicological effects

#### Acute toxicity **Product/ingredient name** Result **Species** Dose Exposure titanium dioxide LC50 Inhalation Dusts and mists >6.82 mg/l Rat 4 hours LD50 Dermal Rabbit >5000 mg/kg >5000 mg/kg LD50 Oral Rat bis(1,2,2,6,6-pentamethyl-LD50 Oral Rat 3.125 g/kg \_ 4-piperidyl) sebacate LD50 Oral methyl Rat 3.125 g/kg 1,2,2,6,6-pentamethyl-4-piperidyl sebacate **Conclusion/Summary** : There are no data available on the mixture itself. Irritation/Corrosion **Conclusion/Summary** : There are no data available on the mixture itself. Skin Eyes : There are no data available on the mixture itself. : There are no data available on the mixture itself. Respiratory **Sensitization Conclusion/Summary** Skin : There are no data available on the mixture itself. : There are no data available on the mixture itself. Respiratory **Mutagenicity Conclusion/Summary** : There are no data available on the mixture itself. **Carcinogenicity Conclusion/Summary** : There are no data available on the mixture itself.

Mexico Page: 7/12

#### Product name PSX 700 SILVERY MOON

# **SECTION 11: Toxicological information**

<u>Classification</u>			
Product/ingredient name	OSHA	IARC	NTP
Manium dioxide Wollastonite crystalline silica, respirable powder (<10 microns)	- - +	2B 3 1	- - Known to be a human carcinogen.

Carcinogen Classification code:

IARC: 1, 2A, 2B, 3, 4 NTP: Known to be a human carcinogen; Reasonably anticipated to be a human carcinogen OSHA: + Not listed/not regulated: -

#### Reproductive toxicity

**Conclusion/Summary** : There are no data available on the mixture itself.

#### **Teratogenicity**

**Conclusion/Summary** : There are no data available on the mixture itself.

Specific target organ toxicity (single exposure)

Not available.

#### Specific target organ toxicity (repeated exposure)

Name		Route of exposure	Target organs
Fystalline silica, respirable powder (<10 microns)	Category 1	inhalation	-

**Target organs** 

: Contains material which causes damage to the following organs: upper respiratory tract, skin, eyes.

Contains material which may cause damage to the following organs: lungs.

#### **Aspiration hazard**

Not available.

#### Information on the likely routes of exposure

# Potential acute health effectsEye contact: No known significant effects or critical hazards.Inhalation: No known significant effects or critical hazards.Skin contact: May cause an allergic skin reaction.

Ingestion : No known significant effects or critical hazards.

#### **Over-exposure signs/symptoms**

Eye contact	: No specific data.
Inhalation	: Adverse symptoms may include the following: reduced fetal weight increase in fetal deaths skeletal malformations
Skin contact	: Adverse symptoms may include the following: irritation redness reduced fetal weight increase in fetal deaths skeletal malformations

Product name PSX 700 SILVERY MOON

# **SECTION 11: Toxicological information**

Ingestion	:	Adverse symptoms r	nay include t	he following:				
		reduced fetal weight	lh a					
		increase in fetal deaths skeletal malformations						
Delayed and immediate effe	<u>cts</u>	and also chronic eff	ects from sh	ort and long	<u>y term expos</u>	<u>sure</u>		
Conclusion/Summary	:	There are no data aver forming methanol if h or fatal or cause blind lung cancer or silicos exposure to dust from products, TiO2 is utili case, the TiO2 particl human exposure to u brush or roller. Sand harmful depending or appropriate personal 8). If splashed in the Ingestion may cause known, delayed and i short-term and long-t and eye contact.	ydrolyzed or Iness. This p is. The risk of sanding sur zed as a raw les are bound nbound parti ing the coatir n the duration protective eq eyes, the liqu nausea, diar mmediate eff	ingested. If s product conta of cancer dep faces or mist material in a d in a matrix v cles of TiO2 v ng surface or and level of juipment and uid may caus rhea and von fects and also	wallowed, me ins crystalline bends on the t from spray a liquid coating with no mean when the pro mist from sp exposure an /or engineering e irritation an hiting. This ta o chronic effe	ethanol may be e silica which duration and applications. g formulation ingful potenti duct is applie ray application d require the ng controls (so a reversible of a kes into accosors of compo-	be harmful can cause level of For many . In this al for d with a ms may be use of dee Section damage. ount, where onents from	
<u>Short term exposure</u>								
Potential immediate effects	:	There are no data av	ailable on the	e mixture itsel	lf.			
Potential delayed effects	1	There are no data av	There are no data available on the mixture itself.					
<u>Long term exposure</u>								
Potential immediate effects	:	There are no data av	ailable on the	e mixture itsel	lf.			
Potential delayed effects	:	There are no data av	ailable on the	e mixture itsel	lf.			
Potential chronic health effe	ects	ž						
General	-	Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels.						
Carcinogenicity	:	May cause cancer.	May cause cancer. Risk of cancer depends on duration and level of exposure.					
Mutagenicity	:	No known significant	t effects or cr	itical hazards				
Reproductive toxicity	:	Suspected of damaging fertility or the unborn child.						
Numerical measures of toxic	city	L						
Acute toxicity estimates	-							
Product/ingredient name			Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases)	Inhalation (vapors)	Inhalation (dusts	

	kg)	(mg/kg)	(gases) (ppm)	(vapors) (mg/l)	(dusts and mists) (mg/l)
SX 700 SILVERY MOON	54858.3	N/A	N/A	N/A	N/A
bis(1,2,2,6,6-pentamethyl-4-piperidyl) sebacate	3125	N/A	N/A	N/A	N/A
methyl 1,2,2,6,6-pentamethyl-4-piperidyl sebacate	3125	N/A	N/A	N/A	N/A

Mexico	Page: 9/12

Product name PSX 700 SILVERY MOON

# **SECTION 12: Ecological information**

#### **Toxicity**

Product/ingredient name	Result	Species	Exposure
4'- Isopropylidenedicyclohexanol, oligomeric reaction products	LC50 11.5 mg/l	Fish	96 hours
with 1-chloro- 2,3-epoxypropane titanium dioxide	Acute LC50 >100 mg/l Fresh water	Daphnia - <i>Daphnia magna</i>	48 hours

#### Persistence and degradability

Not available.

#### **Bioaccumulative potential**

Not available.

#### Mobility in soil

Soil/water partition : Not available. coefficient (Koc)

Other adverse effects : No known significant effects or critical hazards.

## **SECTION 13: Disposal considerations**

 Disposal methods
 The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees. Section 6. Accidental release measures

# **SECTION 14: Transport information**

	Mexico Classification	IMDG	ΙΑΤΑ
UN number	Not regulated.	Not regulated.	Not regulated.
UN proper shipping name	-	-	-
Transport hazard class(es)	-	-	-
			Mexico Page: 10/1

#### Date of issue 12 June 2024

Version 8

#### Product name PSX 700 SILVERY MOON

# **SECTION 14: Transport information**

Packing group	-	-	-
Environmental hazards	No.	No.	No.
Marine pollutant substances	Not applicable.	Not applicable.	Not applicable.

#### Additional information

Mexico	: None identified.
IMDG	: None identified.
ΙΑΤΑ	: None identified.

# Special precautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according : Not applicable. to IMO instruments

# **SECTION 15: Regulatory information**

#### **Mexico**

Classification Flammability : 1 Health : 2 Reactivity : 1

#### International regulations

#### **Montreal Protocol**

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Rotterdam Convention on Prior Informed Consent (PIC)

Not listed.

#### **SECTION 16: Other information**

Hazardous Material Information System (U.S.A.)

Health : 2 \* Flammability : 1 Physical hazards : 1 (\*) - Chronic

effects

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered trademark and service mark of the American Coatings Association, Inc.

The customer is responsible for determining the PPE code for this material. For more information on HMIS® Personal Protective Equipment (PPE) codes, consult the HMIS® Implementation Manual.

Date of previous issue	: 2/18/2020
Organization that prepared	: EHS
the SDS	

Product name PSX 700 SILVERY MOON

#### **SECTION 16: Other information**

Key to abbreviations	: ATE = Acute Toxicity Estimate
-	BCF = Bioconcentration Factor
	GHS = Globally Harmonized System of Classification and Labelling of Chemicals
	IATA = International Air Transport Association
	IBC = Intermediate Bulk Container
	IMDG = International Maritime Dangerous Goods
	LogPow = logarithm of the octanol/water partition coefficient
	MARPOL = International Convention for the Prevention of Pollution From Ships,
	1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution)
	N/A = Not available
	SGG = Segregation Group
	UN = United Nations

#### ✓ Indicates information that has changed from previously issued version.

#### Notice to reader

The information, which is based on the current knowledge of the chemical substance or mixture and applies to appropriate safety precautions for the product, is deemed correct but is not exhaustive and will be used only as a guide.

#### **Disclaimer**

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.