SAFETY DATA SHEET



Conforms to Official Mexican Standard NOM-018-STPS-2015

Date of revision 14 November 2022

Version 7

Date of issue 14 November 2022

SECTION 1: Identification of the substance/mixture and of the company/undertaking

	-
Product name	: AMERLOCK SEALER HRD
Product code	: 00333521
Other means of identification	: Not applicable.
Product type	: Liquid.
Relevant identified uses of	the substance or mixture and uses advised against
Product use	: Industrial applications, Used by spraying.
Use of the substance/ mixture	: Coating.
Uses advised against	: Not applicable.
Manufacturer	: PPG Industries, Inc. One PPG Place Pittsburgh, PA 15272
Emergency telephone number	: (412) 434-4515 (U.S.) (514) 645-1320 (Canada) SETIQ Interior de la República: 800-00-214-00 (México) SETIQ Ciudad de México: (55) 5559-1588 (México)
Technical Phone Number	: 888-977-4762

SECTION 2: Hazards identification

Classification of the substance or mixture	: ACUTE TOXICITY (oral) - Category 4 ACUTE TOXICITY (dermal) - Category 4 ACUTE TOXICITY (inhalation) - Category 2 SKIN CORROSION - Category 1B SERIOUS EYE DAMAGE - Category 1 SKIN SENSITIZATION - Category 1 CARCINOGENICITY - Category 2 TOXIC TO REPRODUCTION - Category 2 SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Respiratory tract irritation) - Category 3 SPECIFIC TARGET ORGAN TOXICITY (REPEATED EXPOSURE) - Category 2 Percentage of the mixture consisting of ingredient(s) of unknown acute toxicity:
	Percentage of the mixture consisting of ingredient(s) of unknown acute toxicity: 25.9% (oral), 35.6% (dermal), 69% (inhalation)

GHS label elements

Product code 00333521 Product name AMERI OCK SEALER HR

Product name AMERLOCK SEALER HRD

SECTION 2: Hazards identification

Hererd nieto gramo	
Hazard pictograms	
Signal word	: Danger
Hazard statements	 H302 + H312 - Harmful if swallowed or in contact with skin. H314 - Causes severe skin burns and eye damage. H317 - May cause an allergic skin reaction. H330 - Fatal if inhaled. H335 - May cause respiratory irritation. H351 - Suspected of causing cancer. H361 - Suspected of damaging fertility or the unborn child. H373 - May cause damage to organs through prolonged or repeated exposure. (kidneys)
Precautionary statements	
Prevention	 P201 - Obtain special instructions before use. P202 - Do not handle until all safety precautions have been read and understood. P280 - Wear protective gloves, protective clothing and eye or face protection. P284 - In case of inadequate ventilation wear respiratory protection. P271 - Use only outdoors or in a well-ventilated area. P260 - Do not breathe vapor. P270 - Do not eat, drink or smoke when using this product. P264 - Wash thoroughly after handling. P272 - Contaminated work clothing should not be allowed out of the workplace.
Response	 P308 + P313 - IF exposed or concerned: Get medical advice or attention. P304 + P340, P310 - IF INHALED: Remove person to fresh air and keep comfortable for breathing. Immediately call a POISON CENTER or doctor. P301 + P310, P330, P331 - IF SWALLOWED: Immediately call a POISON CENTER or doctor. Rinse mouth. Do NOT induce vomiting. P303 + P361 + P353, P310 - IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. Immediately call a POISON CENTER or doctor. P363 - Wash contaminated clothing before reuse. P302 + P312, P352 - IF ON SKIN: Call a POISON CENTER or doctor if you feel unwell. Wash with plenty of water. P333 + P313 - If skin irritation or rash occurs: Get medical advice or attention. P305 + P351 + P338, P310 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor.
Storage	 P405 - Store locked up. P403 + P233 - Store in a well-ventilated place. Keep container tightly closed.
Disposal	: P501 - Dispose of contents and container in accordance with all local, regional, national and international regulations.
Other hazards which do not result in classification	: Causes digestive tract burns. Contains a substance that may emit formaldehyde if stored beyond its shelf life and/or during cure at curing temperatures greater than 60C (140F). Prolonged or repeated contact may dry skin and cause irritation. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. Inhalation of vapor/aerosol concentrations above the recommended exposure limits causes headaches, drowsiness and nausea and may lead to unconsciousness or death. Emits toxic fumes when heated.

See toxicological information (Section 11)

SECTION 3: Composition/information on ingredients

Substance/mixture
Product name

- : Mixture : AMERLOCK SEALER HRD
- Other means of identification
- : Not applicable.
- :

Ingredient name	%	CAS number	
Mrfuryl alcohol	≥20 - ≤27	98-00-0	
Poly[α xy(methyl-1,2-ethanediyl)], α -(2-aminomethylethyl)- ω -	≥10 - ≤20	9046-10-0 (n = 2-6)	
(2-aminomethylethoxy)-			
Polyaminoamide	≥10 - ≤20	68082-29-1	
Formaldehyde, polymer with 1,3-dimethylbenzene	≥10 - ≤20	26139-75-3	
benzyl alcohol	≥5.0 - ≤10	100-51-6	
Formaldehyde, polymer with benzenamine, hydrogenated	≥5.0 - ≤10	135108-88-2	
2,4,6-tris(dimethylaminomethyl)phenol	≥1.0 - ≤3.3	90-72-2	
4-nonylphenol, branched	≥0.10 - ≤2.4	84852-15-3	
3,6-diazaoctanethylenediamin	≤1.9	112-24-3	
salicylic acid	≥1.0 - ≤3.1	69-72-7	
4,4'-methylenebis(cyclohexylamine)	≤1.9	1761-71-3	
Phenol, 2-nonyl-, branched	<1.0	91672-41-2	

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

SECTION 4: First aid measures

Description of necessary first aid measures

Eye contact	 Check for and remove any contact lenses. Immediately flush eyes with running water for at least 15 minutes, keeping eyelids open. Seek immediate medical attention.
Inhalation	 Remove to fresh air. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.
Skin contact	 Remove contaminated clothing and shoes. Wash skin thoroughly with soap and water or use recognized skin cleanser. Do NOT use solvents or thinners.
Ingestion	 If swallowed, seek medical advice immediately and show this container or label. Keep person warm and at rest. Do NOT induce vomiting.

Most important symptoms/effects, acute and delayed

Potential acute health e	ifects
Eye contact	: Causes serious eye damage.
Inhalation	: Fatal if inhaled. May cause respiratory irritation.
Skin contact	: Causes severe burns. Harmful in contact with skin. Defatting to the skin. May cause an allergic skin reaction.
Ingestion	: Harmful if swallowed. Corrosive to the digestive tract. Causes burns.
Over-exposure signs/sy	<u>mptoms</u>

See toxicological information (Section 11)

Indication of immediate medical attention and special treatment needed, if necessary

SECTION 4: First aid measures

Notes to physician Specific treatments	 In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

SECTION 5: Firefighting measures

Extinguishing media	
Suitable extinguishing media	: Use an extinguishing agent suitable for the surrounding fire.
Unsuitable extinguishing media	: None known.
Specific hazards arising from the chemical	: In a fire or if heated, a pressure increase will occur and the container may burst.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon oxides nitrogen oxides Formaldehyde.
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

SECTION 6: Accidental release measures

Personal precautions, protec	<u>tiv</u>	e equipment and emergency procedures
For non-emergency personnel	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Do not breathe vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.
For emergency responders	:	If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and materials for co	nt	ainment and cleaning up
Small spill	:	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a

licensed waste disposal contractor.

SECTION 6: Accidental release measures

Large spill : Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

SECTION 7: Handling and storage

Precautions for safe handling

Protective measures	:	Put on appropriate personal protective equipment (see Section 8). Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Avoid exposure - obtain special instructions before use. Avoid exposure during pregnancy. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not breathe vapor or mist. Do not ingest. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse container.
Special precautions	:	Vapors may accumulate in low or confined areas or travel a considerable distance to a source of ignition and flash back. Vapors are heavier than air and may spread along floors. If this material is part of a multiple component system, read the Safety Data Sheet(s) for the other component or components before blending as the resulting mixture may have the hazards of all of its parts.
Advice on general occupational hygiene	:	Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
Conditions for safe storage, including any incompatibilities	:	Do not store above the following temperature: 50°C (122°F). Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

SECTION 8: Exposure controls/personal protection

<u>Control parameters</u> <u>Occupational exposure limits</u>

SECTION 8: Exposure controls/personal protection

 ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. 	Ingredient name	Exposure limits		
Poly(gray(methyl-1,2-ethanediyl)), a-(2-aminomethylethyl)-w- (2-aminomethylethoxy)- Polyaminoamide None. Formaldehyde, polymer with 1,3-dimethylbenzene benzyl alcohol None. Formaldehyde, polymer with benzenamine, hydrogenated None. 2,4,6-tris(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3,6-diazaoctanethylenediamin IPEL (-), Absorbed through skin. salicylic acid None. 4,4-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C C Calling Limit IPEL Intershol Limit IPEL Intershol Limit Phenol, 2-nonyl-, branched None. Consult local authorities for acceptable exposure limits. STEL Recommended monitoring : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenees of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documental product so the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or owrk process equipment should be checked to ensur	furfuryl alcohol		Absorbed through skin. STEL: 15 ppm 15 minutes.	
Polyaminoamide None. Formaldehyde, polymer with 1,3-dimethylbenzene None. benzyl alcohol TWA: 5 ppm Formaldehyde, polymer with benzenamine, hydrogenated None. 2,4,6-tris(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3,6-diazaoctanethylenediamin IFEL (-). Absorbed through skin. salicylic acid None. 4.4-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. Vertex STEL = Short term exposure limit PH E - Celling Limit STEL Phenol, 2-nonyl-, branched None. None. Vertex Threshoid Limit Via None. C = Celling Limit STEL = Short term exposure limit. TPL = Internal Permissible Exposure Limit STEL = Short term exposure limits. Recommended monitoring : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenees of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to ataltory limits. Conto		-(2-aminomethylethyl)-ω-		
Formaldehyde, polymer with 1,3-dimethylbenzene benzyl alcohol None. Formaldehyde, polymer with benzenamine, hydrogenated 2,4,6-tris(dimethylaminomethyl)phenol None. A-nonylphenol, branched 3,6-diazaoctanethylenediamin None. salicylic acid None. 4,4-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Celling Limit IPEL = Internal Permissible Exposure Limit STEL = Short term exposure limit TUV = Threshold Limit Value TWA = Timeshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. If this product contains ingredients with exposure limit to be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, tume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. </td <td></td> <td></td> <td>None.</td>			None.	
Formaldehyde, polymer with benzenamine, hydrogenated TWA's 5 ppm STEL: 10 ppm None. 2,4,6-tris(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3,6-diazaoctanethylenediamin None. salicylic acid None. 4,4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Ceiling Limit STEL: = Short term exposure limit IPEL = Internal Permissible Exposure Limit TW = Threshold Limit Value IPEL = Internal Permissible Exposure Limit TW = Threshold Limit Value procedures : If this product contains ingredients with exposure limits, personal, workplace attribution or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination or ther agineering controls to keep worker exposure to airborne controls measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate molitoring standards. Reference to national guidance documents for methods for the determination or ther engineering controls to keep worker exposure to airborne controls measures Environmental exposure : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection measures		methylbenzene		
Formaldehyde, polymer with benzenamine, hydrogenated STEL: 10 ppm A.G. tris(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3.6-diazaoctanethylenediamin None. salicylic acid None. 4.4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. VIEL = Ceiling Limit STEL IPEL = Internal Permissible Exposure Limit TLV IPEL = Internal Permissible Exposure Limit TLV TUX = Timeshold Limit Value TVA = Time Weighted Average Consult local authorities for acceptable exposure limits. Recommended monitoring Procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenees of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference should be made to appropriate monitoring standards. Reference should be made to kerphore should be recked to ensure they comply with the requirements of environmental protection legislation. In some cases, fure scrubbers, filters or engineering modification. In some cases, fure scrubbers, filters or engineering modification. In some cases, fure scrubbers, filters or engineering modintimuts. Appropriat	benzyl alcohol			
Formaldehyde, polymer with benzenamine, hydrogenated None. 2.4,6-tris(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3.6-diazaoctanethylenediamin IPEL (-). Absorbed through skin. salicylic acid None. 4.4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. PEL = Internal Permissible Exposure Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TLV = Threshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. Time Weighted Average Recommended monitoring : If this product contains ingredients with exposure lot betermine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other control measures in contained or they comply with the requirements of environmental protection legislation. In some cases, furme scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. mitotividual p				
2.4.6-trist(dimethylaminomethyl)phenol None. 4-nonylphenol, branched None. 3.6-diazaoctanethylenediamin None. salicylic acid TWA: 1 ppm 4.4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Ceiling Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TW = Timeshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenese of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination or hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation or work process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne control measures are conturbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Appropriate engineering : Wash hands, forearms and face thoroughly after	Formaldebyde, polymer with benze	pamine bydrogenated		
4-nonylphenol, branched None. 3,6-diazaoctanethylenediamin IPEL (-). Absorbed through skin. salicylic acid None. 4,4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Ceiling Limit STEL IPEL = Internal Permissible Exposure Limit TV TVA = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborme contaminants below any				
3.6-diazaoctanethylenediamin IPEL (-). Absorbed through skin. TWA: 1 ppm salicylic acid None. 4.4*-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Ceiling Limit IPEL = Internal Permissible Exposure Limit STEL = Short term exposure limit TWV = Threshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. STEL = Short term exposure limit, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Individual protection measures Hyglene measures : Wash hands, forearms and face thoroughly after handling chemical products, befo eating, smoking and using the lavatory and at the end of the working perio				
salicylic acid 4.4'-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched None. C = Ceiling Limit IPEL Internal Permissible Exposure Limit STEL TV = Short term exposure limit TV C = Ceiling Limit IPEL Internal Permissible Exposure Limit STEL TV = Short term exposure limit TV Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Individual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techni			IPEL (-). Absorbed through skin.	
4.4*-methylenebis(cyclohexylamine) None. Phenol, 2-nonyl-, branched Key to abbreviations C = Ceiling Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TLV = Threshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. ndividual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, befo eating, smoking and using the lavatory and at the end of the working period. Appropri				
Phenol, 2-nonyl-, branched None. C = Ceiling Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TLV = Threshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Individual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, befo eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should not be allowed out of the working contaminated clothing Contaminated work clothing shefore reusing. Ensure that eyewash stations and				
C = Ceiling Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TLV = Threshold Limit Value TWA TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fure scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Individual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should not be allowed out of the working period. Appropriate techniques should not be allowed out of the working period. A		=)		
C = Ceiling Limit STEL = Short term exposure limit IPEL = Internal Permissible Exposure Limit TLV = Trime Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Consult local authorities for acceptable exposure limits. = Time Weighted Average Appropriate engineering controls : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectivenes of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, furme scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.	i nonoi, 2 nonyi , branonou			
IPEL = Internal Permissible Exposure Limit TLV = Threshold Limit Value TWA = Time Weighted Average Consult local authorities for acceptable exposure limits. Feecommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required. Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. Individual protection measures : Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing contaminated work clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye/face protection : Chemical splash goggles and face shiel	C = Ceiling Limit	-	= Short term exposure limit	
Consult local authorities for acceptable exposure limits.Recommended monitoring proceduresIf this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Chemical splash goggles and face shield.			•	
Recommended monitoring procedures: If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated work clothing should not be allowed out of the working.Eye/face protection: Chemical splash goggles and face shield.		TWA	= Time Weighted Average	
proceduresatmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.Appropriate engineering controls: Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, befor eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Chemical splash goggles and face shield.	Consult local authorities for acc	eptable exposure limits.		
controlsventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits.Environmental exposure controls: Emissions from ventilation or work process equipment should be checked to ensur they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, befo eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Chemical splash goggles and face shield.	procedures a o p s	tmosphere or biological monitoring r of the ventilation or other control mea protective equipment. Reference sho tandards. Reference to national gui	may be required to determine the effectiveness isures and/or the necessity to use respiratory build be made to appropriate monitoring dance documents for methods for the	
controlsthey comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measuresWash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Chemical splash goggles and face shield.	controls v	entilation or other engineering control	ols to keep worker exposure to airborne	
Hygiene measures: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Chemical splash goggles and face shield.	controls th			
 eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. Eye/face protection : Chemical splash goggles and face shield. 	ndividual protection measures			
	e A C c	eating, smoking and using the lavator appropriate techniques should be use Contaminated work clothing should n contaminated clothing before reusing	ry and at the end of the working period. ed to remove potentially contaminated clothing ot be allowed out of the workplace. Wash . Ensure that eyewash stations and safety	
	Eve/face protection : C	Chemical splash goggles and face sh	nield.	

Product name AMERLOCK SEALER HRD

SECTION 8: Exposure controls/personal protection

Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.
Gloves	: nitrile neoprene
Body protection	 Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Other skin protection	 Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	: Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator. If workers are exposed to concentrations above the exposure limit, they must use appropriate, certified respirators. Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary.

SECTION 9: Physical and chemical properties

				Mexico	Page: 7/14
Viscosity	:	Kinematic (40°C (104°F)): >	21 mm²/s (>21 cSt)		
Partition coefficient: n- octanol/water	:	Not applicable.			
Solubility in water	:	21.5 g/l			
Solubility(ies)	1	old water	Not soluble		
Solubility(ico)		Media F	Result		
Density(lbs / gal)	;	8.51			
Relative density	:	1.02			
Vapor density	:	Not available.			
Vapor pressure	:	Not available.			
(flammable) limits Evaporation rate	:	Not available.			
Lower and upper explosive	:	Not available.			
Flammability		Not available.			
Decomposition temperature		Not available.			
Auto-ignition temperature		Not available.			
Flash point		Closed cup: 100°C (212°F)			
Boiling point	:	>37.78°C (>100°F)			
Melting point	:	Not available.			
pH	÷	Not applicable.			
Odor threshold Molecular weight	÷	Not available. Not applicable.			
Odor	÷	Characteristic.			
Color	÷	Not available.			
Physical state		Liquid.			
Appearance					

Product code 00	333521
-----------------	--------

SECTION 9: Physical and chemical properties

Volatility % Solid. (w/w) : 28% (v/v), 30.26% (w/w) : 69.74

SECTION 10: Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: When exposed to high temperatures may produce hazardous decomposition products. Refer to protective measures listed in sections 7 and 8.
Incompatible materials	: Keep away from the following materials to prevent strong exothermic reactions: oxidizing agents, strong alkalis, strong acids.
Hazardous decomposition products	 Depending on conditions, decomposition products may include the following materials carbon oxides nitrogen oxides Formaldehyde.

SECTION 11: Toxicological information

Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
furfuryl alcohol	LC50 Inhalation Vapor	Rat	934 mg/m ³	4 hours
	LC50 Inhalation Vapor	Rat	233 ppm	4 hours
	LD50 Dermal	Rabbit	400 mg/kg	-
	LD50 Dermal	Rat	3825 mg/kg	-
	LD50 Oral	Rat	0.132 g/kg	-
Poly[oxy(methyl-	LD50 Dermal	Rat	2980 mg/kg	-
1,2-ethanediyl)], α-			0.0	
(2-aminomethylethyl)-ω-				
(2-aminomethylethoxy)-				
/	LD50 Oral	Rat	2885 mg/kg	-
benzyl alcohol	LC50 Inhalation Dusts and mists	Rat	>4178 mg/m ³	4 hours
	LD50 Dermal	Rabbit	2000 mg/kg	-
	LD50 Oral	Rat	1.23 g/kg	-
2,4,6-tris	LD50 Dermal	Rabbit	1.28 g/kg	-
(dimethylaminomethyl)				
phenol				
	LD50 Dermal	Rat	1280 mg/kg	-
	LD50 Oral	Rat	1200 mg/kg	-
4-nonylphenol, branched	LD50 Dermal	Rabbit	2.14 g/kg	-
	LD50 Oral	Rat	1300 mg/kg	-
3,6-diazaoctanethylenediamin	LD50 Dermal	Rabbit	1465 mg/kg	-
	LD50 Oral	Rat	1716 mg/kg	-
salicylic acid	LD50 Oral	Rat	0.891 g/kg	-
4,4'-methylenebis	LD50 Dermal	Rabbit	2.11 g/kg	-
(cyclohexylamine)				
	LD50 Oral	Rat	0.625 g/kg	-

Product name AMERLOCK SEALER HRD

SECTION 11: Toxicological information

: There are no data available on the mixture itself.

Irritation/Corrosion								
Product/ingredient name	Result			Species	Scor	e	Exposure	• Observation
2,4,6-tris (dimethylaminomethyl) phenol	Skin - Visi	ble necr	osis	Rabbit	-		4 hours	7 days
4-nonylphenol, branched	Skin - Ery	thema/E	schar	Rabbit	4		-	-
Conclusion/Summary Skin Eyes Respiratory Sensitization	: There a	re no da	a availab	le on the mix le on the mix le on the mix	cture itse	lf.		
Product/ingredient name	Route of exposure	;	Species			Resul	t	
Formaldehyde, polymer with benzenamine, hydrogenated	skin		Guinea pi	•		Sensi	U U	
3,6-diazaoctanethylenediamin	skin		Guinea pi	g		Sensi	tizing	
<u>Conclusion/Summary</u> Skin Respiratory <u>Mutagenicity</u> Conclusion/Summary <u>Carcinogenicity</u> Conclusion/Summary <u>Classification</u>	: There and : There and :	re no dat re no dat	a availab a availab	le on the mix le on the mix le on the mix le on the mix	kture itse	lf. If.		
Product/ingredient name	OSHA	IARC	NTP					
furfuryl alcohol	-	2B	-					
Carcinogen Classificatio IARC: 1, 2A, 2B, 3 NTP: Known to b OSHA: + Not listed/not reg	, 4 e a human ca	rcinogen;	Reasonabl	y anticipated t	o be a hun	nan carc	inogen	
Reproductive toxicity								
Conclusion/Summary	: There a	re no dat	ta availab	le on the mix	cture itse	lf.		
<u>Teratogenicity</u> Conclusion/Summary <u>Specific target organ toxicit</u> y				le on the mix	cture itse	lf.		
Name				Category		Route c xposu		Target organs

	exposure	
Category 3	-	Respiratory tract irritation
Category 3	-	Respiratory tract irritation

Specific target organ toxicity (repeated exposure)

SECTION 11: Toxicological information

Name	Category	Route of exposure	Target organs
furfuryl alcohol	Category 2	-	-
Formaldehyde, polymer with benzenamine, hydrogenated	Category 2	oral	kidneys
4,4'-methylenebis(cyclohexylamine)	Category 2	oral	-

Target organs

: Contains material which causes damage to the following organs: blood, liver, heart, brain, skin, central nervous system (CNS). Contains material which may cause damage to the following organs: kidneys, the

reproductive system, gastrointestinal tract, upper respiratory tract, eye, lens or cornea, muscle tissue, nose/sinuses.

Aspiration hazard

Name	Result
	ASPIRATION HAZARD - Category 2 ASPIRATION HAZARD - Category 2

Information on the likely routes of exposure

Potential acute health effects

Eye contact : Causes serious eye damage. Inhalation : Fatal if inhaled. May cause respiratory irritation. Skin contact : Causes severe burns. Harmful in contact with skin. Defatting to the skin. May cause an allergic skin reaction. Ingestion : Harmful if swallowed. Corrosive to the digestive tract. Causes burns. Over-exposure signs/symptoms : Eye contact : Adverse symptoms may include the following: pain watering redness Inhalation : Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: respiratory tract irritation redness in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: pain or irritation redness dryness cracking bilistering may occur reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced			
Skin contact : Causes severe burns. Harmful in contact with skin. Defatting to the skin. May cause an allergic skin reaction. Ingestion : Harmful if swallowed. Corrosive to the digestive tract. Causes burns. Over-exposure signs/symptoms Eye contact : Adverse symptoms may include the following: pain watering redness Inhalation : Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: pain or irritation increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: pain or irritation increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Eye contact	es serious eye damage.	
Ingestion : Harmful if swallowed. Corrosive to the digestive tract. Causes burns. Over-exposure signs/symptoms Eye contact : Adverse symptoms may include the following: pain watering redness Inhalation : Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: pain or irritation reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: pain or irritation reduced fetal weight increase in fetal deaths skeletal malformations	Inhalation	if inhaled. May cause respiratory irritation.	
Over-exposure signs/symptoms Eye contact : Adverse symptoms may include the following: pain watering redness Inhalation : Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformations Skin contact : Adverse symptoms may include the following: pain or irritation redness Skin contact : Adverse symptoms may include the following: pain or irritation redness Ingestion : Adverse symptoms may include the following: pain or irritation reduced fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Skin contact		to the skin. May
Eye contact: Adverse symptoms may include the following: pain watering rednessInhalation: Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformationsSkin contact: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Ingestion	ful if swallowed. Corrosive to the digestive tract. Causes	burns.
pain watering rednessInhalation: Adverse symptoms may include the following: respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformationsSkin contact: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Over-exposure signs/sympto		
respiratory tract irritation coughing reduced fetal weight increase in fetal deaths skeletal malformationsSkin contact: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformationsIngestion: Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Eye contact	ing	
pain or irritation redness dryness cracking blistering may occur reduced fetal weight increase in fetal deaths skeletal malformations Ingestion : Adverse symptoms may include the following: stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Inhalation	ratory tract irritation ning sed fetal weight ase in fetal deaths	
stomach pains reduced fetal weight increase in fetal deaths skeletal malformations	Skin contact	or irritation ess ss ing ring may occur ed fetal weight ase in fetal deaths	
Delayed and immediate effects and also chronic effects from short and long term exposure	Ingestion	ach pains ed fetal weight ase in fetal deaths	
	Delayed and immediate effect	so chronic effects from short and long term exposure	<u>9</u>

Product name AMERLOCK SEALER HRD

SECTION 11: Toxicological information

Conclusion/Summary	:	There are no data available on the mixture itself. This product either contains formaldehyde or is capable of releasing formaldehyde above 0.5 ppm under certain conditions. Formaldehyde is a known cancer hazard, a skin sensitizer and a respiratory sensitizer. Exposure to component solvent vapor concentrations in excess of the stated occupational exposure limit may result in adverse health effects such as mucous membrane and respiratory system irritation and adverse effects on the kidneys, liver and central nervous system. Symptoms and signs include headache, dizziness, fatigue, muscular weakness, drowsiness and, in extreme cases, loss of consciousness. Solvents may cause some of the above effects by absorption through the skin. There is some evidence that repeated exposure to organic solvent vapors in combination with constant loud noise can cause greater hearing loss than expected from exposure to noise alone. If splashed in the eyes, the liquid may cause irritation and reversible damage. Ingestion may cause nausea, diarrhea and vomiting. This takes into account, where known, delayed and immediate effects and also chronic effects of components from short-term and long-term exposure by oral, inhalation and dermal routes of exposure and eye contact.
Short term exposure		
Potential immediate effects	:	There are no data available on the mixture itself.
Potential delayed effects	1	There are no data available on the mixture itself.
Long term exposure		
Potential immediate effects	:	There are no data available on the mixture itself.
Potential delayed effects	:	There are no data available on the mixture itself.
Potential chronic health effe	cts	
General	:	May cause damage to organs through prolonged or repeated exposure. Prolonged or repeated contact can defat the skin and lead to irritation, cracking and/or dermatitis. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels.
Carcinogenicity	1	Suspected of causing cancer. Risk of cancer depends on duration and level of exposure.
Mutagenicity	:	No known significant effects or critical hazards.
Reproductive toxicity	1	Suspected of damaging fertility or the unborn child.

Numerical measures of toxicity

Acute toxicity estimates

Product/ingredient name	Oral (mg/ kg)	Dermal (mg/kg)	Inhalation (gases) (ppm)	Inhalation (vapors) (mg/l)	Inhalation (dusts and mists) (mg/l)
MERLOCK SEALER HRD	933	1954.3	N/A	1.3	0.63
furfuryl alcohol	500	1100	N/A	0.934	0.5
Poly[oxy(methyl-1,2-ethanediyl)], α- (2-aminomethylethyl)-ω-(2-aminomethylethoxy)-	2885	2980	N/A	N/A	N/A
benzyl alcohol	1230	2000	N/A	N/A	1.5
Formaldehyde, polymer with benzenamine, hydrogenated	500	N/A	N/A	N/A	N/A
2,4,6-tris(dimethylaminomethyl)phenol	1200	1280	N/A	N/A	N/A
4-nonylphenol, branched	1300	2140	N/A	N/A	N/A
3,6-diazaoctanethylenediamin	1716	1465	N/A	N/A	N/A
salicylic acid	891	N/A	N/A	N/A	N/A
4,4'-methylenebis(cyclohexylamine)	625	2110	N/A	N/A	N/A
Phenol, 2-nonyl-, branched	500	N/A	N/A	N/A	N/A
				Mexico	Page: 11/14

Product name AMERLOCK SEALER HRD

SECTION 11: Toxicological information

SECTION 12: Ecological information

<u>Toxicity</u>

Product/ingredient name	Result	Species	Exposure
P oly[oxy(methyl- 1,2-ethanediyl)], α-	EC50 15 mg/l	Algae	72 hours
(2-aminomethylethyl)-ω- (2-aminomethylethoxy)-			
Formaldehyde, polymer with	Acute EC50 63 mg/l	Fish	96 hours
benzenamine, hydrogenated 2,4,6-tris	Acute LC50 175 mg/l	Fish	96 hours
(dimethylaminomethyl)phenol 4-nonylphenol, branched	Acute EC50 0.044 mg/l	Crustaceans - Moina macrocopa	48 hours
	Acute LC50 0.221 mg/l	Fish	96 hours
salicylic acid	Acute EC50 1147.57 mg/l Fresh water	Daphnia - Daphnia longispina - Neonate	48 hours
	Chronic NOEC 5.6 mg/l Fresh water	Daphnia - Daphnia magna - Neonate	21 days
Phenol, 2-nonyl-, branched	Acute LC50 0.017 mg/l	Fish - Pleuronectes americanus	96 hours

Persistence and degradability

Product/ingredient name	Aquatic half-life	Photolysis	Biodegradability
Poly[oxy(methyl- 1,2-ethanediyl)], α- (2-aminomethylethyl)-ω-	-	-	Not readily
(2-aminomethylethoxy)- benzyl alcohol	-	-	Readily

Bioaccumulative potential

Product/ingredient name	LogPow	BCF	Potential
furfuryl alcohol	0.3	-	low
benzyl alcohol	0.87	-	low
Formaldehyde, polymer with	-	209 to 219	low
benzenamine, hydrogenated			
2,4,6-tris	0.219	-	low
(dimethylaminomethyl)phenol			
4-nonylphenol, branched	5.4	251.19	low
3,6-diazaoctanethylenediamin	-1.66 to -1.4	-	low
salicylic acid	2.21 to 2.26	-	low
4,4'-methylenebis	2.03	-	low
(cyclohexylamine)			

Mobility in soil

Soil/water partition	: Not available.
coefficient (Koc)	

Other adverse effects :

: No known significant effects or critical hazards.

Product name AMERLOCK SEALER HRD

SECTION 13: Disposal considerations

Disposal methods

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and nonrecyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Disposal should be in accordance with applicable regional, national and local laws and regulations. Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees. Section 6. Accidental release measures

SECTION 14: Transport information

	Mexico Classification	IMDG	ΙΑΤΑ
UN number	UN3066	UN3066	UN3066
UN proper shipping name	PAINT	PAINT	PAINT
Transport hazard class(es)	8	8	8
Packing group	III	III	III
Environmental hazards	Yes. The environmentally hazardous substance mark is not required.	Yes.	Yes. The environmentally hazardous substance mark is not required.
Marine pollutant substances	Not applicable.	(4-nonylphenol, branched, 4,4'- methylenebis(cyclohexylamine))	Not applicable.

Mexico	: None identified.		
IMDG	: The marine pollutant mark is not required when transported in sizes of ≤5 L or ≤5 kg.		
ΙΑΤΑ	: The environmentally hazardous substance mark may appear if required by other transportation regulations.		
Special pred	cautions for user : Transport within user's premises: always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.		
Transport ir	ubulk according : Not applicable. uments		

Product name AMERLOCK SEALER HRD

SECTION 15: Regulatory information

Mexico

Classification

Flammability : 1 Health : 3 Reactivity : 1

International regulations

Montreal Protocol

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Rotterdam Convention on Prior Informed Consent (PIC)

Not listed.

SECTION 16: Other information

Hazardous Material Information System (U.S.A.)

Health : 3 * Flammability : 1 Physical hazards : 1

(*) - Chronic effects

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered trademark and service mark of the American Coatings Association, Inc.

The customer is responsible for determining the PPE code for this material. For more information on HMIS® Personal Protective Equipment (PPE) codes, consult the HMIS® Implementation Manual.

Date of previous issue Organization that prepared the SDS	: 11/7/2021 : EHS
Key to abbreviations	: ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IBC = International Air Transport Association IBC = International Maritime Dangerous Goods LogPow = logarithm of the octanol/water partition coefficient MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) N/A = Not available SGG = Segregation Group UN = United Nations
7 I I	have a base of the second s

Indicates information that has changed from previously issued version.

Notice to reader

The information, which is based on the current knowledge of the chemical substance or mixture and applies to appropriate safety precautions for the product, is deemed correct but is not exhaustive and will be used only as a guide.

Disclaimer

The information contained in this data sheet is based on present scientific and technical knowledge. The purpose of this information is to draw attention to the health and safety aspects concerning the products supplied by PPG, and to recommend precautionary measures for the storage and handling of the products. No warranty or guarantee is given in respect of the properties of the products. No liability can be accepted for any failure to observe the precautionary measures described in this data sheet or for any misuse of the products.