



PDS N1.4

January 2005

P850-14 and P850-1402

SPIRIT WIPE

PRODUCT DESCRIPTION

Spirit Wipe is an additive free solvent-borne cleaner for use in removing contaminants on the surface prior to tack ragging and painting.

- Fast Quality Repairs = customer satisfaction

Note: The most important part of any repair process is a clean surface.

SPIRIT WIPE

PRODUCTS

P850-14


Spirit Wipe – Normal

P850-1402

Spirit Wipe – Slow Flash

THESE PRODUCTS ARE FOR THE PROFESSIONAL PAINTING OF AUTOMOTIVE VEHICLES ONLY

PROCESS

MIX RATIO	<p>Spirit Wipe is packaged Ready-for-Use.</p>
APPLICATION 	<ol style="list-style-type: none"> 1. Apply Spirit Wipe to the panel with a clean rag. 2. Follow immediately with another clean rag to wipe off contaminants. <p>Note: For higher temperatures, fast air movement and large areas, Spirit Wipe Slow Flash (P850-1402) should be used.</p> <p>Caution: Do not use on fiberglass or plastic parts. Application on these surfaces can generate static build-up, which can result in a flash fire.</p>

2K™ PERFORMANCE SPECIFICATIONS

Product:	P850-14 Spirit Wipe
	P850-1402 Spirit Wipe
Category:	Surface Cleaner
VOC As Packaged:	P850-14 6.05 lbs. per gal/726 gm/l
	P850-1402 6.26 lbs. per gal/750 gm/l
VOC RTU:	Packaged Ready-for-Use

Note: Surface Cleaners are not regulated by the USA National V.O.C. Rule.

For further information please contact:

Nexa Autocolor-USA
19699 Progress Drive
Strongsville, OH 44149

Nexa Autocolor-Canada
2301 Royal Windsor Drive
Mississauga, Ontario L5J 1K5